

INSURANCE

INS. CASE OWNER:

CC 6/AIG1801

8853

U/K/18

LKK

IDAC

Surveyor:

MARINS

DOI:

ASSIGNMENT

16/10/18

Date / Time:

17/10/18

Registered in Merimen:

17/10/18

Pre-assign / CCU / FTE

SGT 265R

8760 6564556



Insured Vehicle No.:

HYMS CAR LEASING LLC

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$

D.O.A.:

9/10/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBM 4250



INSRS:
WSP:
Tel:
Liability:
RMKS:

BHM



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

10/10/18 - x

17/10/18 - x

STAGE

DATE / PIC

Non-Reporting Ir (1st): 24/10/18

Non-Reporting Ir (2nd): 21/10/18 - SGT AR

Non-Reporting Ir (Final):

Notification Ir (if non-pickup):

Call Of: 10/11/2020

After call Ir to OI: 12 mail only

Documentation Check List: Handler Typo

Notification Ir (if non-pickup)

After call Ir to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA/GIA:

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P.P

\$5 752

(2 days) Reduction:

77%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 2E. Ass. Lia.:

Repair Cost:

(WGST)

\$5 804.64

Loss of Rental (LOR):

\$5

(- days)

Loss of Use (LOU):

\$5

40 (5 20 + 2 days)

Loss of Income (LOI):

\$5

(5 - 1 - days)

LOR only

LOU only

☒

LOR + LOU

☐

LOR + LO

☐

(Tick only one)

GIA/LTA Search

\$5

7.45

Medical:

\$5

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

\$5

-

(e.g. Tow/ Independent)

2) Report Format:

TP

Legal Cost:

\$5

-

3) Survey fee:

\$320

Total:

\$5

852.09

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

852.09

Name 1:

BAN HOE HIN CO PTELTO

Payee 2: (Strike if N.A.)

\$5

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$5

-

Name 3:

-

COPY SENT

21/11/2020

REF:

Date: 10/01/18

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front:

R/Bal:

L/Bal:

D.O.A.

Survey held at:

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

C PIP \$ 752 / Red \$ 2,547 (77%)

Low total: \$ 252.00

Date/Time File Pass to:



Prel. Report

11



Final Report

Date/Time File Return to:

12

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transport:

Fuel:

Phone:

Other:

Report Format:

Lump Sum / I.B. (13)

Add Fee:



Site Insp. \$



Interview \$



Tech. lines \$



Workshop \$

TOTAL

Survey Fee	
Transport	
Fuel	
Phone	
Other	
TOTAL	\$214



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18018853/Uhb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-10-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGZ 2552R	Veh. Inspected	FBM 4215D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/10/2018	Inspection Date	16/10/2018	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000200K
MOTOR VEHICLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 33104

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 13/10/2018
CLAIM NO. : 11196
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBM4215D
MAKE/MODEL : YAM / YBR125

*not approved
2hr
take photo After 14-
16/10/18
2hr.*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COWLING FRONT (RED) P/N: 42639	REPLACE	1.00	\$283.00	283.00 X
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
3	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	55.00
4	HEADLIGHT ASSY. P/N: 50950	REPLACE	1.00	\$490.00	490.00 X
5	LABOUR P/N: 06766		4.00	\$35.00	140.00
6	LAMP SIGNAL REAR RH P/N: 45419	REPLACE	1.00	\$63.00	63.00 X
7	LEVER BRAKE P/N: 50001	REPLACE	1.00	\$23.00	23.00
8	MIRROR RH P/N: 54029	REPLACE	1.00	\$80.00	80.00
9	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$98.00	98.00 X
10	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00	68.00 X
11	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$88.00	88.00
12	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$1,655.00	1,655.00 X
13	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$12.00	12.00 10 51



Address: No. 6, Delfi Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 300-14380
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
15	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00

SUB TOTAL	\$3,299.00
GST @ 7 %	\$230.93
GRAND TOTAL	\$3,529.93

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Customer's Consent, hence notify
the following:

- The resurvey is subject to confirmation
- The resurvey is for a "Without Prejudice" basis
- No large modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P-630
102
x67



Address: No. 6, Delta Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bmh.com.sg

Fax: (Main) +65 6281 2830. (Spare Parts) +65 6285 7530. (Insurance/Project) +65 6284 2969. (Accounts) +65 6281 6759

CERT NO: 300-M-000
00-001-371



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000280K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 33141

Supplementary 1 To QTN: 33104

DATE : 19/10/2018
CLAIM NO. : 11196
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBM4215D
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price	Amount
1	PROTECTOR EXHAUST P/N: 50024	Replace	1.00	\$119.00	119.00
2	PROTECTOR EXHAUST CAP P/N: 50006	Replace	1.00	\$56.00	56.00
SUB TOTAL					\$175.00
GST @ 7 %					\$12.25
GRAND TOTAL					\$187.25

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700280K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 33104

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 13/10/2018
CLAIM NO. : 11196
POLICY NO. : AVFMSB0000591803

FROM : RAYMOND

VEHICLE NO. : FBM4215D
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00 Disc %: 10.00	175.50
2	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
3	LABOUR P/N: 06766		4.00	\$35.00	140.00
4	LEVER BRAKE P/N: 50001	REPLACE	1.00	\$23.00 Disc %: 10.00	20.70
5	MIRROR RH P/N: 54029	REPLACE	1.00	\$80.00 Disc %: 10.00	72.00
6	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$88.00 Disc %: 10.00	79.20
7	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
8	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
9	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00
10	PROTECTOR EXHAUST P/N: 50024	Replace	1.00	\$119.00 Disc %: 10.00	107.10
11	PROTECTOR EXHAUST CAP P/N: 50006	Replace	1.00	\$56.00 Disc %: 10.00	50.40

SUB TOTAL

\$752.00

GST @ 7 %

\$52.64

GRAND TOTAL

\$804.64



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-14080
ISO 9001:2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33104

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 13/10/2018
CLAIM NO. : 11196
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBM4215D
MAKE/MODEL : YAM / YBR125

*Not Approved
2 bar
take photo After repair
16/10/18
Ydy.*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COWLING FRONT (RED) P/N: 42639	REPLACE	1.00	\$283.00	283.00 X
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
3	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	55.00
4	HEADLIGHT ASSY. P/N: 50950	REPLACE	1.00	\$490.00	490.00 X
5	LABOUR P/N: 06766		4.00	\$35.00	140.00
6	LAMP SIGNAL REAR RH P/N: 45419	REPLACE	1.00	\$63.00	63.00 X
7	LEVER BRAKE P/N: 50001	REPLACE	1.00	\$23.00	23.00
8	MIRROR RH P/N: 54029	REPLACE	1.00	\$80.00	80.00
9	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$98.00	98.00 X
10	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00	68.00 X
11	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$88.00	88.00
12	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$1,655.00	1,655.00 X
13	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$12.00	12.00 10



S/N	Description	Action	Qty	Unit Price	Amount
14	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
15	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00

SUB TOTAL \$3,299.00

GST @ 7 % \$230.93

GRAND TOTAL \$3,529.93**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By

**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

1. The Repairer shall notify the Insurer of the following:
 a. The extent of the damage to the vehicle
 b. The location of the damaged part(s) during resurvey
 c. The repair work is subject to confirmation
 d. The repair work is on a "Without Prejudice" basis
 e. The repair work is allowed
 f. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0288K
Vehicle Details	
Vehicle No.:	FBM4215D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	E3F5E044376
Chassis No.:	LBP101000059379
Maximum Power Output:	-
Open Market Value:	\$1,859.00
Original Registration Date:	24 Oct 2017
First Registration Date:	24 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$279.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,903.00
COE Rebate Amount:	\$4,421.00
Total Rebate Amount:	\$4,421.00

The information contained herein is correct as at 16 Oct 2018

OK

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBM4215D		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	YBR125		
Chassis No. :	LBPRE101000059379		
Propellant :	Petrol		
Engine No. :	E3F5E044376		
Engine Capacity :	124 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	320 kg		
Unladen Weight :	114 kg		
Year Of Manufacture :	2017		
Original Registration Date :	24 Oct 2017		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$4,903.00		
COE Expiry Date :	23 Oct 2027		
Road Tax Expiry Date :	23 Apr 2019		
Inspection Due Date :	23 Oct 2020		
Intended Transfer Date :	12 Oct 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

CERTIFICATE OF INSURANCETHE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189) OF THE REPUBLIC OF SINGAPORE
THE ROAD TRANSPORT ACT 1987 OF MALAYSIATHE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS' BUREAU OF SINGAPORE DATED 22 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS' BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1968
ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

CERTIFICATE No.

AVFMSB0000591803

ChaNo: LBPRI01000059379

1. Index Mark and Registration Number of Vehicle FBM 4215 D

2. Name of Policyholder BAN HOCK HIN CO PTE LTD

3. Effective Date of Commencement of Insurance 10 April 2018
for the purposes of the Ordinance

09 April 2019

4. Date of Expiry of Insurance

5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)

ANY PERSON WHO IS UNDER THE POLICYHOLDER &/OR HIRER'S EMPLOYMENT AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

USE ONLY FOR THE POLICYHOLDER &/OR HIRER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

1. USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
2. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING (OTHER THAN FOR REWARD) OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.
3. USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD BY ANY PERSON TO WHOM THE VEHICLE IS HIRED.

Type of Cover : Third Party

* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore)



Approved Insurers

Examined By

View Received Message

This mail is associated with :

*FBM4215D (8160556352SG)
[SGZ2552R]

TP
BAN HOCK HIN CO PTE LTD
Oct 9 2018 12:00AM
[HYMS CAR LEASING PTE LTD]
Ban Hock Hin Co. Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 22/10/2018 09:33 AM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be advise that no OI GIA report received.
Please find OI details below for your further actions.

OI Name: HYMS Car Leasing Pte Ltd

Address: 176 Sin Ming Drive #04-02 Singapore 575721

Mobile No.: 64515752

Thanks & Regards,
Yin Rui, Hor (Viviane)

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18018853/Uhb3

24 October, 2018

HYMS Car Leasing Pte Ltd

176 Sin Ming Drive #04-02

Singapore 575721

Dear Sirs,

**ACCIDENT INVOLVING FBM 4215D AND SGZ 2552R ON 09.10.2018 ALONG/
AT CANTONMENT ROAD BEFORE JUNC WITH HOE CHIANG ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan

Claims

Tel : 6841 2096

Fax: 6741 4108

Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18018853/Uhb3

21 March 2019

By Registered Mail

HYMS Car Leasing Pte Ltd
176 Sin Ming Drive #04-02
Singapore 575721

Dear Sir,

**ACCIDENT INVOLVING FBM 4215D AND SGZ 2552R ON 09.10.2018 ALONG/
AT CANTONMENT ROAD BEFORE JUNC WITH HOE CHIANG ROAD**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 24/10/2018

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by 04/04/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c *Claims Manager
AIG Asia Pacific Insurance Pte. Ltd
(Motor Claims Dept)*

View Sent Message

This mail is associated with :

***FBM4215D (8160556352SG)
[SGZ2552R]**

TP

BAN HOCK HIN CO PTE LTD

Oct 9 2018 12:00AM

[HYMS CAR LEASING PTE LTD]

Ban Hock Hin Co. Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 13/03/2019 14:08 PM.
To NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosi
ngh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
CC AIG_SG; admin-a@lkkauto.com; vicalpeh@lkkauto.com
Subject Re: No OI GIA Report

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Suwanna Te-uttaruang
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 25/10/2018 10:49 AM
Subject: Re: No OI GIA Report

Hi,

Insured has not report accident to us till date.
Please find OI details at email below for your further actions.

Thanks & Regards,
Yin Rul, Hor (Viviane)

<-- Original Message -->

From: LKK_HQ
To: AIG_SG; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; NoorMariesa.AbuKassim@aig.com; yokeshi.chan@aig.com
CC: Admin-a@lkkauto.com; vicalpeh@lkkauto.com
Sent On: 26/10/2018 10:38 AM
Subject: Re: No OI GIA Report

Dear All,

Please assist to upload OI GIA report in merimen if available.

Thank you.

Vic Alpeh
LKK Auto COnsultants Pte Ltd
Tel: 6841 2096

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 22/10/2018 09:33 AM
Subject: No OI GIA Report

Hi,

Please be advise that no OI GIA report received.
Please find OI details below for your further actions.

Ol Nar Car Leasing Pte Ltd
Address: 176 Sin Ming Drive #04-02 Singapore 575721
Mobile No.: 64515752
Thanks & Regards,
Yin Rul, Hor (Viviane)

DOCUMENTS SUMMARY

There are no documents.

Hsiao Tong (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 13 March 2019 5:20 PM
To: NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com;
yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com;
Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
Cc: Admin A; Vic (LKKAUTO)
Subject: Re: No OI GIA Report

This mail is associated with :
***FBM4215D (8160556352SG)**
[SGZ2552R]
TP
BAN HOCK HIN CO PTE LTD
Oct 9 2018 12:00AM
[HYMS CAR LEASING PTE LTD]
Ban Hock Hin Co. Pte Ltd

Dear Suwanna,

OI has not reported till date.

Thanks and regards,

Syaza Irdina

<-- Original Message -->

From: LKK_HQ
To: NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com;
Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
CC: AIG_SG; admin-a@lkkauto.com; vicalpeh@lkkauto.com
Sent On: 13/03/2019 02:08 PM
Subject: Re: No OI GIA Report

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Suwanna Te-uttaruang
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 26/10/2018 10:49 AM
Subject: Re: No OI GIA Report

Print Sent Message

This mail is associated with :

***FBM4215D (8160556352SG)
[SGZ2552R]**

TP

BAN HOCK HIN CO PTE LTD
Oct 9 2018 12:00AM
[HYMS CAR LEASING PTE LTD]
Ban Hock Hin Co. Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 08/01/2020 17:47 PM.
To NoorMariesa.AbuKassim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com; AIG_SG
CC admin-a@lkkauto.com; khanchna@lkkauto.com
Subject Re: No OI GIA Report

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Khanchna
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: AIG_SG
To: NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com; LKK_HQ
CC: admin-a@lkkauto.com; vicalpeh@lkkauto.com
Sent On: 13/03/2019 05:14 PM
Subject: Re: No OI GIA Report

Dear Suwanna,
OI has not reported till date.
Thanks and regards,
Syaza Irdina

<-- Original Message -->

From: LKK_HQ
To: NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
CC: AIG_SG; admin-a@lkkauto.com; vicalpeh@lkkauto.com
Sent On: 13/03/2019 02:08 PM
Subject: Re: No OI GIA Report

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Suwanna Te-uttaruang
LKK Auto Consultants Pte Ltd

<-- Original Message -->

Khanchna (LKK Auto)

From: Raymond <raymond@bhh.com.sg>
Sent: Wednesday, 15 January 2020 5:41 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: Accident Involving FBM4215D & SGZ2552R on 09/10/2018 - LKK REF: CC6/AIG18018853/Ukb3

Dear Khanchna,

Apologies for the late reply.

There is not injury claim for this case.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg | [facebook.com/bhhsg](https://www.facebook.com/bhhsg)

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEAS



From: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Sent: Wednesday, 15 January, 2020 11:10 AM

To: Raymond <raymond@bhh.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident Involving FBM4215D & SGZ2552R on 09/10/2018 - LKK REF: CC6/AIG18018853/Ukb3

WITHOUT PREJUDICE

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 16 January 2020 10:50 AM
To: 'Raymond'
Cc: Admin A
Subject: RE: Accident Involving FBM4215D & SGZ2552R on 09/10/2018 - LKK REF CC6/AIG18018853/Ukb3
Attachments: AIG DV.pdf

Without Prejudice

Dear Raymond,

We refer to the above matter and your e-mail below.

Please be informed that our Insured informed that they are not doing private settlement.

We confirm settlement as per your LOD on this matter.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond <raymond@bhh.com.sg>
Sent: Wednesday, 15 January 2020 5:41 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Oct 2018 Edit Reg		16 Oct 2018 00:00 Edit Adj Rpt	S\$752.00 Edit Estimates	S\$752.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K								
Main Claimant:	BAN HOCK HIN CO PTE LTD, Co. Reg. No.: 197000288K								
Vehicle Reg. No.:	FBM4215D	Date of Loss:	09/10/2018 11:00 - :59 [11 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8160556352SG	Policy/Cover Note No.:	0999994505 (Comprehensive)						
Vehicle Reg. No. (Insured):	SG22552R	Policy No. (Claimant):	AVFM580000591702						
		Excess:							
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (13/03/2019): Re: No OI GIA Report - AIG_SG (26/10/2018): Re: No OI GIA Report - AIG_SG (22/10/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBM4215D (8160556352SG)
[SGZ2552R]
TP
BAN HOCK HIN CO PTE LTD
Oct 9 2018 11:00AM
[HYMS CAR LEASING PTE LTD]
Ban Hock Hin Co. Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences										1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	{Draft}	Third Party Express Settlement – Payment Breakdown										Edit	
Photos/Images										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	19/10/18 17:47	Chassis Number										Load JPG ☒	
2	19/10/18 17:47	Odometer Reading										Load JPG ☒	
3	19/10/18 17:47	General View										Load JPG ☒	
4	19/10/18 17:47	General View										Load JPG ☒	
5	19/10/18 17:47	General View										Load JPG ☒	
6	19/10/18 17:47	General View										Load JPG ☒	
7	19/10/18 17:47	General View										Load JPG ☒	
8	19/10/18 17:47	General View										Load JPG ☒	
9	19/10/18 17:47	General View										Load JPG ☒	
10	19/10/18 17:47	General View										Load JPG ☒	
11	19/10/18 17:47	General View										Load JPG ☒	
12	19/10/18 17:47	General View										Load JPG ☒	
13	19/10/18 17:47	General View										Load JPG ☒	
14	19/10/18 17:47	General View										Load JPG ☒	
15	19/10/18 17:47	General View										Load JPG ☒	
16	19/10/18 17:47	General View										Load JPG ☒	
17	19/10/18 17:47	General View										Load JPG ☒	
18	19/10/18 17:47	General View										Load JPG ☒	
19	19/10/18 17:47	General View										Load JPG ☒	
20	19/10/18 17:47	General View										Load JPG ☒	
21	19/10/18 17:47	General View										Load JPG ☒	
22	19/10/18 17:47	General View										Load JPG ☒	
23	19/10/18 17:47	General View										Load JPG ☒	
24	19/10/18 17:47	General View										Load JPG ☒	
25	19/10/18 17:47	General View										Load JPG ☒	
26	19/10/18 17:47	General View										Load JPG ☒	
27	19/10/18 17:47	General View										Load JPG ☒	
28	19/10/18 17:47	General View										Load JPG ☒	
29	19/10/18 17:47	General View										Load JPG ☒	
30	19/10/18 17:47	General View										Load JPG ☒	
31	19/10/18 17:47	General View										Load JPG ☒	
32	19/10/18 17:47	General View										Load JPG ☒	
33	19/10/18 17:47	General View										Load JPG ☒	
34	19/10/18 17:47	General View										Load JPG ☒	
35	19/10/18 17:47	General View										Load JPG ☒	
36	19/10/18 17:47	General View										Load JPG ☒	
37	19/10/18 17:47	General View										Load JPG ☒	
38	19/10/18 17:47	General View										Load JPG ☒	
39	19/10/18 17:47	General View										Load JPG ☒	
40	19/10/18 17:47	General View										Load JPG ☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	19/10/18 17:47	General View	 Load JPG	☒
42	19/10/18 17:47	General View	 Load JPG	☒
43	19/10/18 17:47	General View	 Load JPG	☒
44	19/10/18 17:47	General View	 Load JPG	☒
45	19/10/18 17:47	General View	 Load JPG	☒
46	19/10/18 17:47	General View	 Load JPG	☒
47	19/10/18 17:47	General View	 Load JPG	☒
48	19/10/18 17:47	General View	 Load JPG	☒
49	19/10/18 17:47	General View	 Load JPG	☒
50	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
51	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
52	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
53	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
54	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
55	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
56	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
57	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
58	19/10/18 17:47	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/18 17:06	TP ESTIMATE- MARKED	 Load PDF	
2	18/10/18 17:06	TP GIA REPORT	 Load PDF	
3	24/10/18 10:37	Non reporting letter	 Load PDF	
4	10/01/20 13:39	EMAIL TO OI	 Load PDF	
5	16/01/20 17:23	EMAIL FROM OI	 Load PDF	
6	30/01/20 11:35	WORKSHOP INVOICE	 Load PDF	
7	30/01/20 11:35	AUTHORISATION TO ACT FORM	 Load PDF	
8	30/01/20 11:35	Release Voucher	 Load PDF	
9	30/01/20 11:35	Registered Mail Fee	 Load PDF	
10	30/01/20 11:35	LTA SEARCH	 Load PDF	
11	30/01/20 11:35	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/01/20 08:55	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGZ2552R (Insd veh)	Model:	YAMAHA YBR125 123CC
	FBM4215D (TP veh)		(M)
Date of Accident:	09/10/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,717.18
Final Repair Cost	:	\$	804.64
Loss of Use	:	\$	40.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	852.09

2.00 days at \$20.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ 100____(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ban Hock Hin Co. Pte Ltd	:	\$ 852.09
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

30 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC8/AIG18018853/UKS3Q2

Date: 30/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994505
Claimant
Vehicle No : FBM4215D **Insured Vehicle No :** SGZ2552R
Date of Loss: 09/10/2018 **Nature of Claim:** TP **Claim No:** 8160556352SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM4215D**
 Make & Model: YAMAHA YBR125, 123cc (M) Engine No: E3F5E044376
 Reg. Date: 24/10/2017 (Man. Year: 2017) Chassis No: LBPREF101000059379
 Colour: Red Odometer: 33660 km
 Engine Capacity: 124 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 90-90-18
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,299.00	577.00	2,722.00	82.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	175.00	175.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,474.00	752.00	2,722.00	78.35
+ GST 7.00/7.00% (S\$)	243.18	52.64	190.54	78.35
Nett Amount (S\$)	3,717.18	804.64	2,912.54	78.35
+ Loss of Use (2.0 x S\$20.00/day) (S\$)		40.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		852.09		

INSPECTION

Date of Assignment: 16/10/2018
 Date Inspected: 16/10/2018 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
 No. 6 Defu Lane 4
 Singapore 539410
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COWLING FRONT (RED)	Serviceable	283.00 F	*- FL
2	1		*CRASH BAR	Dented	195.00 F	*195.00 FL
3	1		*FOOT REST 1	Bent	55.00 F	*55.00 FL
4	1		*HEADLIGHT ASSY (Scratched)	Not Consistent With The Impact	490.00 F	*- FL
5	1		*LAMP SIGNAL REAR RH	Serviceable	63.00 F	*- FL
6	1		*LEVER BRAKE	Cut	23.00 F	*23.00 FL
7	1		*MIRROR RH	Cut	80.00 F	*80.00 FL
8	1		*MUDGUARD FRONT (RED)	Repair	98.00 F	*- FL
9	1		*MUDGUARD REAR	Serviceable	68.00 F	*- FL
10	1		*PEDAL BRAKE	Cut	88.00 F	*88.00 FL
11	1		*PIPE EXHAUST ASSY	Repair	1,655.00 F	*- FL
12	1		*PLATE NUMBER REAR (6.5 INCH X9 INCH)	Cut	12.00 FS	*10.00 FS
13	1		*RUBBER FOOTREST FRONT	Torn	14.00 F	*14.00 FL
14	1		*PROTECTOR EXHAUST	Cut	119.00 F	*119.00 FL
15	1		*PROTECTOR EXHAUST CAP	Cut	56.00 F	*56.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,299.00	640.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	63.00

Total Parts (\$\$)	3,299.00	577.00
--------------------	----------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD	New	35.00	35.00
2	LABOUR	New	140.00	140.00
Gross Labour Cost (\$\$)			175.00	175.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >