

REF:

CC3 / ALH18018901 / Avber

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

 OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured _____

Policy No: 1800110324

Claims No: _____

Sum Insured: _____

Excess: 0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 160K

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 15 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA178K. Yr Regn: 2018 Sept

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A6 CC: 1798

Colour: Silver. A/C: Insured / Std / NI / NA

Sp Reading: 472 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ4G4JN062432

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / R/Rim / STD A/Rim or

Tyre Size: F: 225/55R17.

R: 225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A: 13/10/18 D.O.I: 18/10/18

Survey held at: Premium

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: _____

OD ALG.

S/L 61302 - CC3 / CT118001209 / K/sub3g2

DFA: 17/12/18

19/10/18 Revert via merimen

19/10/18 Rece approved \$20,513 from Victor by merimen

19/10/18 Informed Tony CIA ex \$0 by email

27/3/19 @ 10:44am Carrine agree Labour \$5000

1/4/19 final. fig \$23,281.92 (Fed 15,038.08, 3919) confirmed by email

Case/Time, File Path (if)

 Prel. Report Final Report

Case/Time, File Return (if)

25/4 - typist

Report Format: merimen

Lump Sum / I.B.H. 23,281.92

Days Of Repair: 15

Resurvey No. of Trip: 2

Add Fee: Site Insp \$ Interview \$ Tech. Insp \$ Weekend \$

Survey Fee

Transporter

Fuel + Mileage

1. Taxes

1. Other

2. Other

TOTAL

200

10

210

RECEIVED 27 MAR 2019

View Received Message

This mail is associated with :

***SKA178K (7480615729SG)**

OD

Oct 13 2018 10:15AM

[LOW WEE SIONG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 01/04/2019 16:16 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$23281.92) - SKA178K - Claim Handler: Loo, Tong Shing

Approved:23281.92.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKA178K (7480615729SG)**

OD

Oct 13 2018 10:15AM

[LOW WEE SIONG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/03/2019 10:41 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SKA178K - Claim Handler: Loo, Tong Shing

Maintained:Labour at 10 days \$5000.00, to amend. Submit survey report.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	--

Attn: Loo, Tong Shing	Date: 25 Mar 2019
------------------------------	--------------------------

Preliminary Advice

Vehicle No	: SKA178K	Accident Date	: 13/10/2018
Make	: AUDI A6	Policy No.	: 1800110324
Assignment Date	: 17/10/2018	Excess	: S\$0.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 15.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,320.00	(incl.supplementary \$163.00)
Revised Amount	:S\$	23,781.92	(incl.supplementary \$163.00)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	23,781.92	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	68,520.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,480.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 19 October 2018 11:29 AM
To: 'Claims'; SUR
Subject: RE: OD CLAIM FOR SKA 178 K-DOA: 13/10/2018

Dear Tony,

As instructed by our client , please proceed to repair the **insured vehicle SKA 178K (Excess S0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 19 October 2018 9:29 AM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SKA 178 K-DOA: 13/10/2018

Dear Tony,

We are pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 18 October 2018 12:15 PM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SKA 178 K

Dear all,

Attached is revised estimate from Adrian.

Kindly follow up this case closely.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 17 October, 2018 4:52 PM

To: 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: OD CLAIM FOR SKA 178 K

Dear Catherine,

Kindly assist register OD claim for AIG, tomorrow morning will arrange survey.

Aside to SUR Team,

Kindly assist follow up this case. Once survey done tomorrow, we will email to you.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SKA178K (7480615729SG)**
OD
Oct 13 2018 10:15AM
[LOW WEE SIONG]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 19/10/2018 11:17 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20513.00) - SKA178K - Claim Handler: Loo, Tong Shing

Approved:20513.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 19 Oct 2018

Preliminary Advice

Vehicle No	: SKA178K	Accident Date	: 13/10/2018
Make	: AUDI A6	Policy No.	: 1800110324
Assignment Date	: 17/10/2018	Excess	: S\$0.00
Date of Inspection	: 18/10/2018	Est. Duration of Repair	: 14.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,157.00
Revised Amount	:S\$	20,513.00
Check Items (Estimated)	:S\$	3,587.00
Total	:S\$	24,100.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	68,520.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,480.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3288E
Vehicle Details	
Vehicle No.:	SKA178K
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CYG024872
Chassis No.:	WAUZZZ4G4JN062432
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$40,761.00
Original Registration Date:	17 Sep 2018
First Registration Date:	17 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$49,066.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Sep 2028
PARF Rebate Amount:	\$36,799.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$31,721.00
Total Rebate Amount:	\$68,520.00

The information contained herein is correct as at 18 Oct 2018

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LOW WEE SIONG (LIU WEIXIONG)
Period of Insurance : 17 Sep 2018 To 16 Sep 2020
Engine No. : CYG024872
Chassis No. : WAUZZZ4G4JN062432

Vehicle No. : SKA178K
Policy No. : 1800110324
Endorsement No. :
Issued Date : 18 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A6 1.8 TFSI ULTRA
Engine Capacity/Tonnage : 1,798.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2018
Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LOW WEE SIONG (LIU WEIXIONG) - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63862323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125277

PREMIUM LEASING -TKC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Cheng Chang Chee

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8223263Z



Name

DU YUKAI
@TOH YUKAI
杜 瑜 凯

Race

CHINESE

Date of Birth: 17-08-1982 Sex: F

Country of Birth:
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8223263Z

Name:

DU YUKAI

Birth Date: 17 Aug 1982

Issue Date: 26 May 2003



000514746G

3031803



NRIC No: S8223263Z



Blood Group: A+ Date of issue: 23-06-1998

Address:
59 LILY AVENUE
SINGAPORE 277788

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

14 Jun 2001

NP 428A



Licence No: S8223263Z

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7723288E



Name
LOW WEE SIONG
(LIU WEIXIONG)
刘伟雄
Race
CHINESE
Date of birth
27-08-1977
Country of birth
SINGAPORE

Sex
M
S7723288E



4099682

NRIC No. S7723288E



Date of issue
12-09-2007

Address
19 MOUNT SINAI VIEW
SINGAPORE 276812

NRIC No. S7723288E Date: 04/03/2008 No: 5956680

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/10/2018 13:58
Date Of Accident	13/10/2018 10:15
Exact Location Of Accident	TRAFFIC LIGHT U-TURN ALONG CLEMENTI RD OPP CLEMENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA178K
Insured/Policyholder	
Name Of Registered Owner	LOW WEE SIONG
NRIC No	S7723288E
Email Address	SUNSHINE.HEAVEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98457238
Alternative Phone No	OTHERS-98457238

Vehicle Particulars

Manufacturer	AUDI
Model	A6 1.8 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800110324
Cover Note Number	

Driver

Name of Driver	DU YUKAI @TOH YUKAI
NRIC No	S8223263Z
Date Of Birth	17/08/1982
Occupation	INDOOR
Date Of Driving Pass	14/06/2001
Driving Experience	17 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98159876
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	19 MOUNT SINAI VIEW
Postcode	276812
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THERE IS A TRAFFIC LIGHT U-TURN ALONG CLEMENTI ROAD OPPOSITE CLEMENTI CRESCENT. THIS IS NOT A JUNCTION. I WAS THE FIRST CAR WAITING AT THE U-TURN TRAFFIC LIGHT. WHEN MY LIGHT TURNED GREEN, I WAITED FOR THE ONCOMING CARS TO SLOW DOWN. I DID NOT U-TURN IMMEDIATELY AS THIS IS A BUSY ROAD. WHEN THE ONCOMING CARS SLOWED DOWN DUE TO THEIR OWN LIGHT, I MADE THE TURN. I WAS ABOUT TO COMPLETE THE TURN, WHEN I HEARD TYRES SCREECHING AND MY CAR WAS HIT FROM THE BACK (LEFT REAR END CORNER). I FELT MY CAR JERK OFF THE GROUND. IN THE VOICE RECORDING, THE DRIVER ADMITTED THAT HE WENT AGAINST MY GREEN LIGHT AND THAT HE WAS LOOKING AT HIS MAP. VOICE RECORDING WILL UPLOAD TO THE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	YES

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW7975P
Vehicle Make/Model/Colour	HONDA STREAM / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD KHAIRUDDIN BIN ALIAS
NRIC/Passport Number	S8720170H
Contact Number	90089926
Address	BLK 890A TAMPINES AVE 1 #11-309
Postcode	521890
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name: Tom Fong
NRIC/FIN No: 62041671



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


There is a traffic light u-turn along Clementi Road opposite Clementi (resident). This is not a junction. I was the first car waiting at the u-turn traffic light when my light turned green. I waited for the oncoming cars to slow down. I did not u-turn immediately as this is a busy road when the oncoming cars slowed down due to their own red light. I made my turn. I was about to complete my turn when I heard tyres screeching and my car was hit from the back (left rear end corner). I felt my car jerk off the ground.


In the voice recording, the driver admitted that he went against my green light and that he was looking at his map.

Voice recording will upload to the report

DECLARATION

I/we declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



Reporting Centre Personnel's Signature
 Name: Tony Pong
 NRIC/FIN No: 6704117X

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1177/2018/PH
Date : 16-Oct-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Low Wee Siong
Address : 19 Mount Sinai View
Singapore 276812
Telephone : HP +65 98457238
Type of Claim : Own Damage Claims
Policy No. : 1800110324
Vehicle No : **SKA 178 K**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : Sep-18
Engine No : CYG 024872
Chassis No : WAUZZZ4G4JN062432
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Oct-18
Place of Accident : Traffic light U-turn along Clementi Rd opp Clementi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 178 K.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	✓
2	To renew rear windscreen and lhs 1/4 glass for fender renewal.	S/N \$ 600.00 ✓	✓
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	✓
4	To remove and reinstall rear seat assy, back rest, ABCD pillar trims, curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc.	S/N \$ 1,400.00 ✓	✓
5	To dismantle rear bumper, lhs sill panel trim and rear lid. Cut out and reweld lhs rear fender, lhs bottom plate, lhs wheel housing inner and outer and lhs connecting plate. Renew rear bumper and lhs sill panel trim. Inspect for further damages. Reinstall all parts removed.	\$ 8,400.00	3500 5000
SUB TOTAL LABOUR CHARGES		: \$ 12,160.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 178 K.

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
6	To respray rear bumper, lhs rear fender, lhs wheel housing inner and outer, lhs bottom plate, lhs connecting plate, lhs sill panel, lhs sill panel trim, door entrances, roof channel, drain channel and end panelling. To carry out joint sealant work and stone chip treatment.	\$ 6,800.00	3950 2800 2750.
7	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
8	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 19,432.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	S	2,519.00 ✓ 2015.20
2	FIXING PARTS FOR REAR BUMPER <i>new</i>	S	234.00 ✓
3	REAR BUMPER SPOILER <i>new</i>	S	416.00 ✓
4	SECURING STRIP <i>new</i>	S	191.00 ✓
5	CLOSING ELEMENT - LH <i>new</i>	S	69.00 ✓
6	TRIM FOR EXHAUST TAIL PIPE - LH <i>new</i>	S	497.00 ✓
7	REAR BUMPER CARRIER <i>new</i>	S	851.00 ✓
8	SEAL - LH/RH <i>Not new</i>	2 S	24.00 ? ✗
9	GUIDE SECTION - LH <i>new</i>	S	46.00 ✓ 36.08
10	GUIDE SECTION - LH <i>new</i>	S	28.00 ✓ >>
11	CONNECTING PIECE <i>Not new</i>	S	11.00 ? ✗
12	GUIDE PROFILE - LH <i>new</i>	S	57.00 ? ✗
13	HOLDING STRAP - LH <i>new</i>	S	54.00 ? ✗
14	REAR BUMPER SENSOR <i>new</i>	S	211.00 ✓
15	SECTIONAL PART - SIDE PANEL - LH <i>Distorted</i>	S	2,739.00 ✓ 2191.20
16	REAR WINDSCREEN <i>new</i>	S	1,017.00 ✓ 813.60
17	PRIMER <i>new</i>	2 S	38.00 ✓ 114.56
18	REAR 1/4 GLASS - LH <i>new</i>	S	344.00 ✓ 275.20
19	TRIM STRIPS FOR SIDE WINDOW CHROME - LH REAR <i>new</i>	S	222.00 ✓
20	MOLDING - ROOF CHROME <i>new</i>	S	440.00 ✓
SUB-TOTAL SPARE PARTS CHARGES		:	\$ 10,008.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	SIDE MEMBER TRIM - LH <i>Repair to 1/2</i>	S	752.00 + 601.60
22	ATTACHMENT PARTS - CLIP <i>new</i>	S	77.00 - 60.88
23	ADHESIVE TAPE <i>new</i>	S	14.00 - 10.96
24	SILL TRIM STRIP SATIN BLACK - LH REAR <i>new</i>	S	104.00 +
25	WHEEL HOUSING LINER - LH <i>Dented</i>	S	246.00 - 196.80
26	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>2 new</i>	S	62.00 ? X
27	WHEEL HOUSING - LH OUTER <i>Dented</i>	S	655.00 ? 524
28	CONNECTING PLATE <i>Best</i>	S	85.00 ? 67.92
29	BOTTOM PLATE - LH OUTER <i>Best</i>	S	605.00 ? 484
30	WHEEL HOUSING - LH INNER <i>Repair</i>	S	655.00 ? X
31	LED TAIL LIGHT - LH <i>new</i>	S	1,094.00 +
32	TRIM FOR TAIL LIGHT <i>new</i>	S	26.00 +
33	LUGGAGE COMPARTMENT TRIM SOUL BLACK - LH <i>new</i>	S	676.00 ? X
34	REAR BOOT AMPLIFIER BRACKET <i>new</i>	S	100.00 ? X
35	REAR SILENCER - LH <i>Dented</i>	S	1,157.00 ✓ 925.60
36	DUAL CLIP <i>new</i>	S	53.00 ? 41.84
37	BRACKET <i>Best</i>	S	50.00 ? 39.92
38	REAR LHS ALUMINIUM RIM <i>ut</i>	S	726.00 ✓ 580.40
39	ARCYLIC SEALANT } <i>new</i>	S/N S	180.00 ✓ 180
40	CAVITY WAX }	S/N S	140.00 ✓ 140
SUB-TOTAL SPARE PARTS CHARGES		:	\$ 7,457.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	STONE CHIP TREATMENT	S/N \$ 180.00 ✓	180
42	METAL FILLER POWDER	S/N \$ 280.00 ✓	280
43	REAR WINDSCREEN SEALANT	S/N \$ 200.00 ✓	200
44	1/4 GLASS SEALANT	S/N \$ 100.00 ✓	100
45	SUNDRIES <i>New</i>	\$ 500.00 ?	500
TOTAL SPARE PARTS CHARGES		: \$ 18,725.00	
TOTAL LABOUR CHARGES		: \$ 19,432.00	
GRAND TOTAL		: \$ 38,157.00	38,320

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

38291.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 18/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 14 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	SIDE MEMBER TRIM - LH <i>Repair bt ✓</i>	S	752.00 ✓
22	ATTACHMENT PARTS - CLIP <i>new</i>	S	77.00 ✓
23	ADHESIVE TAPE <i>new</i>	S	14.00 ✓
24	SILL TRIM STRIP SATIN BLACK - LH REAR <i>new</i>	S	104.00 ✓
25	WHEEL HOUSING LINER - LH <i>Dented</i>	S	246.00 ✓
26	ATTACHMENT PARTS FOR WHEEL HOUSING LINER ?	S	62.00 ?
27	WHEEL HOUSING - LH OUTER ? <i>bt ✓</i>	S	655.00 ?
28	CONNECTING PLATE ? <i>bt ✓</i>	S	85.00 ?
29	BOTTOM PLATE - LH OUTER ? <i>bt ✓</i>	S	605.00 ?
30	WHEEL HOUSING - LH INNER ? <i>bt ✓</i>	S	655.00 ?
31	LED TAIL LIGHT - LH <i>new</i>	S	1,094.00 ✓
32	TRIM FOR TAIL LIGHT <i>new</i>	S	26.00 ✓
33	LUGGAGE COMPARTMENT TRIM SOUL BLACK - LH ?	S	676.00 ?
34	REAR BOOT AMPLIFIER BRACKET ?	S	100.00 ?
35	REAR SILENCER - LH <i>Dented</i>	S	1,157.00 ✓
36	DUAL CLIP ?	S	53.00 ?
37	BRACKET ?	S	50.00 ?
38	REAR LHS ALUMINIUM RIM <i>cut</i>	S	726.00 ✓
39	ARCYLIC SEALANT ?	S/N S	180.00 ✓
40	CAVITY WAX <i>new</i>	S/N S	140.00 ✓
SUB-TOTAL SPARE PARTS CHARGES		:	<u>S 7,457.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1177/2018/PH 23-Oct-18 Kee Siang 23-Oct SKA 178 K Audi A6 1.8 TFSI S-Tronic
--	---	--

Quantity	Description	Unit Price	Amount
Parts			
1	Retainer for Aerial	S 22.00	bt X nn
2	Vent Trim	S 65.00	de / 5136
TOTAL		S 87.00	

For Premium Automobiles Pte Ltd

Justin
23/10/18

[Signature]

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1177/2018/PH 23-Oct-18 Kee Siang 26-Oct SKA 178 K Audi A6 1.8 TFSI S-Tronic
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Heat Shield for Rear Silencer <i>sampled</i>	\$ 76.00	\$ 61.20
TOTAL		\$ 76.00	\$ 61.20

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1177/2018/PH
Date : 16-Oct-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

15 days - jb - 27 dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Low Wee Siong
Address : 19 Mount Sinai View
Singapore 276812
Telephone : HP +65 98457238
Type of Claim : Own Damage Claims
Policy No. : 1800110324
Vehicle No : **SKA 178 K**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : Sep-18
Engine No : CYG 024872
Chassis No : WAUZZZ4G4JN062432
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Oct-18
Place of Accident :

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 178 K.

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid rear lid kick sensor. Check function.	S/N \$	360.00	\$ 360.00
2	To renew rear windscreen and lhs 1/4 glass for fender renewal.	S/N \$	600.00	\$ 600.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat assy, back rest, ABCD pillar trims, curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc.	S/N \$	1,400.00	\$ 1,400.00
5	To dismantle rear bumper, lhs sill panel trim and rear lid. Cut out and reweld lhs rear fender, lhs bottom plate, lhs wheel housing inner and outer and lhs connecting plate. Renew rear bumper and lhs sill panel trim. Inspect for further damages. Reinstall all parts removed. (Added 4 days for checked items 27, 28, 29)	\$	8,400.00	\$ 5,500.00 5000
SUB TOTAL LABOUR CHARGES		:	<u>\$ 12,160.00</u>	<u>\$ 9,260.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 178 K.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 9,260.00
6	To respray rear bumper,lhs rear fender,lhs wheel housing inner and outer,lhs bottom plate,lhs connecting plate,lhs sill panel,lhs sill panel trim,door entrances,roof channel,drain channel and end panelling.To carry out joint sealant work and stone chip treatment. <i>(Add \$1200 for checked items)</i>		\$ 6,800.00	\$ 3,950.00
7	To renew lhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
10	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES			\$ 19,432.00	\$ 13,682.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 178 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,519.00	\$ 2,015.20
2	FIXING PARTS FOR REAR BUMPER	\$ 234.00	
3	REAR BUMPER SPOILER	\$ 416.00	
4	SECURING STRIP	\$ 191.00	
5	CLOSING ELEMENT - LH	\$ 69.00	
6	TRIM FOR EXHAUST TAIL PIPE - LH	\$ 497.00	
7	REAR BUMPER CARRIER	\$ 851.00	
8	SEAL - LH/RH	2 \$ 24.00	
9	GUIDE SECTION - LH	\$ 46.00	\$ 36.08
10	GUIDE SECTION - LH	\$ 28.00	\$ 22.00
11	CONNECTING PIECE	\$ 11.00	
12	GUIDE PROFILE - LH	\$ 57.00	
13	HOLDING STRAP - LH	\$ 54.00	
14	REAR BUMPER SENSOR	\$ 211.00	
15	SECTIONAL PART - SIDE PANEL - LH	\$ 2,739.00	\$ 2,191.20
16	REAR WINDSCREEN	\$ 1,017.00	\$ 813.60
17	PRIMER	2 \$ 38.00	\$ 14.56
18	REAR 1/4 GLASS - LH	\$ 344.00	\$ 275.20
19	TRIM STRIPS FOR SIDE WINDOW CHROME - LH REAR	\$ 222.00	
20	MOLDING - ROOF CHROME	\$ 440.00	
SUB-TOTAL SPARE PARTS CHARGES		\$ 10,008.00	\$ 5,367.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKA 178 K.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 5,367.84
21	SIDE MEMBER TRIM - LH	\$ 752.00	\$ 601.60
22	ATTACHMENT PARTS - CLIP	\$ 77.00	\$ 60.88
23	ADHESIVE TAPE	\$ 14.00	\$ 10.96
24	SILL TRIM STRIP SATIN BLACK - LH REAR	\$ 104.00	
25	WHEEL HOUSING LINER - LH	\$ 246.00	\$ 196.80
26	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 62.00	
27	WHEEL HOUSING - LH OUTER	\$ 655.00	\$ 524.00
28	CONNECTING PLATE	\$ 85.00	\$ 67.92
29	BOTTOM PLATE - LH OUTER	\$ 605.00	\$ 484.00
30	WHEEL HOUSING - LH INNER	\$ 655.00	
31	LED TAIL LIGHT - LH	\$ 1,094.00	
32	TRIM FOR TAIL LIGHT	\$ 26.00	
33	LUGGAGE COMPARTMENT TRIM SOUL BLACK - LH	\$ 676.00	
34	REAR BOOT AMPLIFIER BRACKET	\$ 100.00	
35	REAR SILENCER - LH	\$ 1,157.00	\$ 925.60
36	DUAL CLIP	\$ 53.00	\$ 41.84
37	BRACKET	\$ 50.00	\$ 39.92
38	REAR LHS ALUMINIUM RIM	\$ 726.00	\$ 580.40
39	ARCYLIC SEALANT	S/N \$ 180.00	\$ 180.00
40	CAVITY WAX	S/N \$ 140.00	\$ 140.00
SUB-TOTAL SPARE PARTS CHARGES		\$ 7,457.00	\$ 9,221.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKA 178 K.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 9,221.76
41	STONE CHIP TREATMENT	S/N \$ 180.00	\$ 180.00
42	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
43	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
44	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
45	<i>Added parts - see attached</i>	\$ 76.00	\$ 61.20
46	<i>Added parts - see attached</i>	\$ 65.00	\$ 51.36
47	SUNDRIES	\$ 500.00	\$ 5.60
TOTAL SPARE PARTS CHARGES		\$ 18,866.00	\$ 10,099.92
TOTAL LABOUR CHARGES		\$ 19,432.00	\$ 13,682.00
GRAND TOTAL		\$ 38,298.00	\$ 23,781.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1177/2018/PH 23-Oct-18 Kee Siang 23-Oct SKA 178 K Audi A8 1.8 TFSI S-Tronic
Quantity	Description	Unit Price	Amount
Parts			
1	Retainer for Aerial	\$ 22.00	
2	Vent Trim	\$ 65.00	\$ 51.36
TOTAL		\$ 87.00	\$ 51.36

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 1 April 2019 4:40 PM
To: 'Carrine Leong'; SUR
Cc: jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing'; 'Boo seng yak'
Subject: RE: FINAL REVISION - SKA178K - OD AIG - SURVEYED 18 OCT 18

Dear Carrine,

Confirm repair cost of \$23,281.92 before GST @ 15 days of repairs.

Labour charges amend to \$5000 instead of \$5500

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 21 February 2019 5:17 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SKA178K - OD AIG - SURVEYED 18 OCT 18


Hi Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 27 Dec 2018.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 109902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [<mailto:boojohnny@gmail.com>]

Sent: Thursday, 27 December, 2018 3:58 PM

To: Adrian Ling <adrianling@lkkauto.com>; Veron Chen <veronchen@lkkauto.com>; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKA178K - OD AIG - SURVEYED 18 OCT 18

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$23,781.92 @ 15 days of repairs exclude weekend.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKA 178 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1177/2018/MAS

24 April 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SKA 178 K, Audi A6 1.8 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SKA 178 K** claimant, **Mr. Low Wee Siong**, please find the related document per attached.

1. A copy of the Original invoice no. 85013695 – S\$24,911.65
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKA 178 K

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159998
Main Telephone: 6394 2223
Main Telefax: 6471 2333

Alexandra Service Centre
281 Alexandra Road
Singapore 159939
Telephone: 6394 2223
Telefax: 6471 1022

Ubi Service Centre
55 Ubi Road 1
Singapore 338711

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6394 2323
9628 1233

INS TAX INVOICE
Company Reg. No. S99902271W
GST Reg. No. 199902271W

Page 1 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013695 Date : 17/04/2019 Order : SKA0178K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKA0178K (V 38079)	Regn Date: 17/09/2018	Mileage: 472	WIP No.: 28361
Model: A6 1.8 TFSI S tronic 4GC066 (A	Chassis: WAUZZZ4G4JN062432	Engine: CYG 024872	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS FOR FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO DISLUDGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIM, CURTAIN AIRBAG, SAFETY BELTS, CARPETS, ROOF LINER, CARPET, SILL TRIM, ETC	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER, LHS SILL PANEL TRIM AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER, LHS BOTTOM PLATE, LHS WHEEL HOUSING	5000.00	1.00	5,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159988
Main Telephone: 6884 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159988
Telephone: 6884 2223
Telefax: 6475 1025

UBI Service Centre
55 Ubi Road 1
Singapore 4086 3713

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2222
9528 1233

INSURANCE TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013695 Date : 17/04/2019 Order : SKA0178K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKA0178K (V 38079)	Regn Date: 17/09/2018	Mileage: 472	WIP No.: 28361
Model: A6 1.8 TFSI S tronic AGC066 (A	Chassis: WAUZZZ4G4JN062432	Engine: CYB 024872	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	INNER AND OUTER AND LHS CONNECTING PLATE,RENEW REAR BUMPER AND LHS SILL PANEL TRIM,INSPECT FOR FUTHER DAMAGES.REINSTALL ALL PARTS REMOVED M: TO RESPRAY REAR BUMPER,LHS REAR FENDER,LHS WHEEL HOUSING INNER AND OUTER,LHS SILL PANEL,END PANELLING AND BOOT COMPARTMENT. TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT	3950.00	1.00	3,950.00
S	BODYWORK	M: TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	288.00	1.00	288.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALANT,CAVITY WAX,STONE CHIP TREATMENT,METAL FILLER POWDER,REAR WINDSCREEN SEALANT AND 1/4 GLASS SEALANT	1888.00	1.00	1,888.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6394 2223
Page 3 of 3

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6394 2223
Telex: 6475 1022

Ubi Service Centre
55 Ubi Avenue 1
Singapore 408707
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
24 Hour Appointment
24 Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6346 2323
9828 1228

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013695 Date : 17/04/2019 Order : SKA0178K Term : 30	Account: 8006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No.: SKA0178K (V 38079) Regn Date: 17/09/2018 Mileage: 472 WIP No.: 28361

Model: A6 1.8 TFSI S tronic 4GC06G (A Chassis: WAUZZZ464JN062432 Engine: CYG 024872 Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A460253609CE	(V) (G) SILENCER (22/10)	Less 020%	1.00	1157.00	925.60
X	A460009411A	(V) (G) HOUSING	Less 020%	1.00	655.00	524.00
X	A460004171A	(V) (SK) PLATE	Less 020%	1.00	76.50	61.20
X	A460053855M GRU	(V) (G) TRIM	Less 020%	1.00	752.00	601.60
X	A465009837	SUBPART	Less 020%	1.00	2739.00	2,191.20
X	A465045297 NVB	SIDE WINDOW	Less 020%	1.00	344.00	275.20
X	A460010171B	WHEEL HOUS	Less 020%	1.00	246.00	196.80
X	A460002009TR	(V) (G) FLOOR PAN (22/1	Less 020%	1.00	605.00	484.00
X	A465045501 NVB	GLASS	Less 020%	1.00	1017.00	813.60
X	A465007067K GRU	(V) (G) COVER (22/10/20	Less 020%	1.00	2519.00	2,015.20
X	A460601025BH	(V) (G) RIM 17" 10-SPO	Less 020%	1.00	725.50	580.40
X	A460009347	(V) (SK) PLATE (22/10/2	Less 020%	1.00	84.90	67.92
X	A0X0253144M	BRACKET	Less 020%	1.00	49.90	39.92
X	A1X0253141L	CLAMP	Less 020%	1.00	52.30	41.84
X	A465019161A	TRIM	Less 020%	1.00	64.20	51.36
X	A460098909A	SECUR. SET	Less 020%	1.00	13.70	10.96
X	A460098909C	SECUR. SET	Less 020%	1.00	76.10	60.88
X	A465007453C	(A) (SK) GUIDE (22/10/2	Less 020%	1.00	45.10	36.08
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Ruzli Centre Singapore
281 Alexandra Road
Singapore 159956
Main Telephone: 4828 2222
Main Telefax: 4471 3193

Alexandra Service Centre
281 Alexandra Road
Singapore 159956
Telephone: 4388 2222
Telefax: 4475 1025

Ubi Service Centre
35 Ubi Road 1
Singapore 408721

Customer Service
Service Appointment
Breakdown Service
Email: customer.care@premiumauto.com.sg

4388 2222
4475 1025

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 18:04

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013695 Date : 17/04/2019 Order : SKA0178K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKA0178K (V 38079) Regn Date: 17/09/2018 Mileage: 472 WIP No.: 28361
Model: A6 1.8 TFSI S tronic 4GC066 (A Chassis: WAUZZZ4G4JN062432 Engine: CYB 024872 Dept: U
VSB No. :
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A465807889A	GUIDE	Less 020%	1.00	27.50	22.00
X	AD 00920002	PRIMER (DG)	Less 020%	1.00	18.20	14.56
X	AN 30654704	THREADED PIN	Less 020%	3.00	1.00	2.40
X	AN 0140325	(A) (SK) BOLT	Less 020%	10.00	0.40	3.20

Parts	9,019.92	Sub-Total	23,281.92
Labour	0.00	7% GST	1,629.73
Sublet	14,252.00	Grand Total	24,911.65
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SKA 178 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1177/2018/JT
8 Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 1.8 TFSI S-tronic
Vehicle Chassis No. : WAUZZZ4G4JN062432
Vehicle Regn No. : SKA 178 K
Vehicle Mileage : 472 km
Vehicle Owner : Mr. Low Wee Siong
Certificate No : 1800110324
Policy Excess : NIL
Accident Date : 13th October 2018
Place : Traffic light U-turn along Clementi Road
Repair Cost : \$ 24,911.65
WIP No. : 28361
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____
Time : _____
Date : _____

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8223263Z



Name
DU YUKAI
@TOH YUKAI
杜 瑜 凯
Race
CHINESE
Date of Birth 17-08-1982 Sex F
Country of Birth
SINGAPORE



3031803



NRIC No. S8223263Z

Blood Group: A+ Date of Issue: 23-06-1998

Address
59 LILY AVENUE
SINGAPORE 277788

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Vehicle Class	Pass Date
3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	14 Jun 2001



NP 428A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LOW WEE SIONG (LIU WEIXIONG)
 Period of Insurance : 17 Sep 2018 To 16 Sep 2020
 Engine No. : CYG024872
 Chassis No. : WAUZZZ4G4JN062432

Vehicle No. : SKA178K
 Policy No. : 1800110324
 Endorsement No. :
 Issued Date : 18 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A6 1.8 TFSI ULTRA
 Engine Capacity/Tonnage : 1,798.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LOW WEE SIONG (LIU WEIXIONG) - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125277

PREMIUM LEASING -TKC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159936

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Cheng Cheng Chen

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2018 17:32		17 Oct 2018 16:58 Edit Adj Rpt	S\$23,281.92 Edit Estimates	S\$23,281.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LOW WEE SIONG , ID: S7723288E, Tel: +6598457238								
Vehicle Reg. No.:	SKA17BK	Date of Loss:	13/10/2018 10:00 - :59 [26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7480615729SG	Policy/Cover Note No.:	1800110324 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/10/2018]								
Driver/Custodian:	DU YUKAI @TOH YUKAI (36 / Female) , NRIC: S8223263Z, Tel: +6598159876 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> • AIG_SG (01/04/2019): Alert - Adj Mandate Approved (S\$23281.92) - SKA17BK - Claim Handler: Loo, Tong S... • AIG_SG (26/03/2019): Alert - Adj Mandate Maintained - SKA17BK - Claim Handler: Loo, Tong Shing • AIG_SG (19/10/2018): Alert - Adj Mandate Approved (S\$20513.00) - SKA17BK - Claim Handler: Loo, Tong S... • AIG_SG (19/10/2018): SKA17BK / OD / 13/10/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA178K (7480615729SG)
 OD
 Oct 13 2018 10:15AM
 [LOW WEE SIONG]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View	View in Browser
Audio															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail	Print			
1	15/10/18 09:01	Audio - Drivers <small>[Linked Accident Report Documents]</small>											Load MP3	<input type="checkbox"/>		
2	15/10/18 09:01	Audio - Drivers <small>[Linked Accident Report Documents]</small>											Load MP3	<input type="checkbox"/>		
Assessment Reports															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	19/10/18 09:20	Adjuster Immediate Advice											Load HTM	<input type="checkbox"/>		
2	25/03/19 17:14	Adjuster Immediate Advice											Load HTM	<input type="checkbox"/>		
Photos/Images															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
2	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
3	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
4	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
5	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
6	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
7	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
8	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
9	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
10	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
11	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
12	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
13	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
14	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
15	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
16	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
17	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
18	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
19	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
20	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
21	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
22	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
23	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
24	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
25	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
26	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
27	18/10/18 17:39	General View											Load JPG	<input checked="" type="checkbox"/>		
28	21/03/19 17:00	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
29	21/03/19 17:00	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		

Audio			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
30	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
31	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
32	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
33	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	21/03/19 17:00	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	21/03/19 17:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	21/03/19 17:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	21/03/19 17:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	21/03/19 17:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	21/03/19 17:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	21/03/19 17:01	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/18 17:47	Singapore Accident Statement		Load PDF
2	18/10/18 17:47	Certificate of Insurance		Load PDF
3	18/10/18 17:47	Driver's Driving License		Load PDF
4	18/10/18 17:56	MARK ESTIMATE		Load PDF
5	25/03/19 17:08	SURVEYOR'S MARKING		Load PDF
6	25/03/19 17:08	SUPPLEMENTARY		Load PDF
7	29/04/19 17:53	Workshop Invoice		Load PDF
8	29/04/19 17:53	Discharge Voucher		Load PDF

Linked Accident Report Documents

Audio			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/10/18 09:01	Audio - Drivers		Load MP3
2	15/10/18 09:01	Audio - Drivers		Load MP3
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/10/18 10:06	Accident Statement		Load HTML
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print

Audio			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	13/10/18 14:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	15/10/18 10:08	ACCIDENT SCENE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
15	15/10/18 10:08	ACCIDENT SCENE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
16	15/10/18 10:08	ACCIDENT SCENE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/18 14:11	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	13/10/18 14:11	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18018901/AVBE2

Date: 30/04/2019

REFERENCE

Insured/Claimant:	LOW WEE SIONG	Policy No:	1800110324	
Date of Loss:	13/10/2018	Nature of Claim:	OD	Claim No: 7480615729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA178K	Engine No:	CYG024872
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G4JN062432
Reg. Date:	17/09/2018 (Man. Year: 2017)	Odometer:	472 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,859.56	10,099.92	8,759.64	46.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,432.00	13,182.00	6,250.00	32.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	38,291.56	23,281.92	15,009.64	39.20
+ GST 7.00/7.00% (S\$)	2,680.41	1,629.73	1,050.68	39.20
Nett Amount (S\$)	40,971.97	24,911.65	16,060.32	39.20

INSPECTION

Date of Assignment:	17/10/2018		
Date Inspected:	18/10/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,519.00 FS	*2,015.20 FS
2	1		*FIXING PARTS FOR REAR BUMPER	Not Necessary	234.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Not Necessary	416.00 FS	*- FS
4	1		*SECURING STRIP	Not Necessary	191.00 FS	*- FS
5	1		*CLOSING ELEMENT - LH	Not Necessary	69.00 FS	*- FS
6	1		*TRIM FOR EXHAUST TAIL PIPE - LH	Not Necessary	497.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	851.00 FS	*- FS
8	2		*SEAL - LH/RH	Not Necessary	24.00 FS	*- FS
9	1		*GUIDE SECTION - LH	Damaged	46.00 FS	*36.08 FS
10	1		*GUIDE SECTION - LH	Damaged	28.00 FS	*22.00 FS
11	1		*CONNECTING PIECE	Not Necessary	11.00 FS	*- FS
12	1		*GUIDE PROFILE - LH	Not Necessary	57.00 FS	*- FS
13	1		*HOLDING STRAP - LH	Not Necessary	54.00 FS	*- FS
14	1		*REAR BUMPER SENSOR	Not Necessary	211.00 FS	*- FS
15	1		*SECTIONAL PART - SIDE PANEL - LH	Distorted	2,739.00 FS	*2,191.20 FS
16	1		*REAR WINDSCREEN	Necessary	1,017.00 FS	*813.60 FS
17	2		*PRIMER	Necessary	38.00 FS	*14.56 FS
18	1		*REAR 1/4 GLASS - LH	Necessary	344.00 FS	*275.20 FS
19	1		*TRIM STRIPS FOR SIDE WINDOW CHROME - LH REAR	Not Necessary	222.00 FS	*- FS
20	1		*MOLDING - ROOF CHROME	Not Necessary	440.00 FS	*- FS
21	1		*SIDE MEMBER TRIM - LH	Torn	752.00 FS	*601.60 FS
22	1		*ATTACHMENT PARTS - CLIP	Necessary	77.00 FS	*60.88 FS
23	1		*ADHESIVE TAPE	Necessary	14.00 FS	*10.96 FS
24	1		*SILL TRIM STRIP SATIN BLACK - LH REAR	Not Necessary	104.00 FS	*- FS
25	1		*WHEEL HOUSING LINER - LH	Deformed	246.00 FS	*196.80 FS
26	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	62.00 FS	*- FS
27	1		*WHEEL HOUSING - LH OUTER	Dented	655.00 FS	*524.00 FS
28	1		*CONNECTING PLATE	Bent	85.00 FS	*67.92 FS
29	1		*BOTTOM PLATE - LH OUTER	Bent	605.00 FS	*484.00 FS
30	1		*WHEEL HOUSING - LH INNER	Repair	655.00 FS	*- FS
31	1		*LED TAILLIGHT - LH	Not Necessary	1,094.00 FS	*- FS
32	1		*TRIM FOR TAIL LIGHT	Not Necessary	26.00 FS	*- FS
33	1		*LUGGAGE COMPARTMENT TRIM SOUL BLACK - LH	Not Necessary	676.00 FS	*- FS
34	1		*REAR BOOT AMPLIFIER BRACKET	Not Necessary	100.00 FS	*- FS
35	1		*REAR SILENCER - LH	Dented	1,157.00 FS	*925.60 FS
36	1		*DUAL CLIP	Necessary	53.00 FS	*41.84 FS
37	1		*BRACKET	Bent	50.00 FS	*39.92 FS
38	1		*REAR LHS ALUMINIUM RIM	Cut	726.00 FS	*580.40 FS
39	1		*ARCYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
40	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
41	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
42	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
43	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
44	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
45	1		*SUNDRIES	Necessary	500.00 FS	*5.60 FS
46	1		*RETAINER FOR AERIAL	Not Necessary	22.00 FS	*- FS
47	1		*VENT TRIM	Deformed	51.36 FS	*51.36 FS
48	1		*HEAT SHIELD FOR REAR SILENCER	Crumpled	61.20 FS	*61.20 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	18,859.56	10,099.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS FOR FENDER RENEWAL	New	600.00	600.00
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, CURTAIN AIRBAGS, SAFETY BELTS, CARPETS, ROOF LINER, CARPETS, SILL TRIMS, ETC	New	1,400.00	1,400.00
5	TO DISMANTLE REAR BUMPER, LHS SILL PANEL TRIM AND REAR LID. CUT OUT AND REWELD LHS REAR FENDER, LHS BOTTOM PLATE, LHS WHEEL HOUSING INNER AND OUTER AND LHS CONNECTING PLATE. RENEW REAR BUMPER AND LHS SILL PANEL TRIM. INSPECT FOR FURTHER DAMAGES. REINSTALL ALL PARTS REMOVED	New	8,400.00	5,000.00
6	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS WHEEL HOUSING INNER AND OUTER, LHS BOTTOM PLATE, LHS CONNECTING PLATE, LHS SILL PANEL, LHS SILL PANEL TRIM, DOOR ENTRANCES, ROOF CHANNEL, DRAIN CHANNEL AND END PANELLING. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	6,800.00	3,950.00
7	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			19,432.00	13,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >