

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LIM SIEW BEE

c/o 46 Lentor Plain

Singapore 786548

Not Authorised
1/10/87
Resurvey After Paint
5 days

Date: 16/10/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SJS3973D / BMW 320i	
1 pc	rear door	<i>Not in scope</i> 2,176.00 ✓
1 pc	front doot	<i>R</i> 2,350.00 X
1 pc	side rocker panel garnish	1,276.00 7
1 pc	rear bumper	<i>dup</i> <i>Not in scope</i> 1,675.00 ✓
	sub-total	7,477.00
	less 10%	747.70
	sub-total	6,729.30
	alloy rim <i>P1:</i> s.nett	<i>Rs</i> 900.00 ✓
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	<i>550</i> 900.00
	To check wiring system.	<i>20</i> 40.00
	To apply putty & spray painting on affected areas.	<i>1000</i> 1,350.00
	To transfer doors accessories.	<i>60</i> 120.00
	To perform 4 wheels computerised alignment.	<i>60</i> 85.00
	Total	10,124.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: