

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES180004

Date : 17/10/2018
 Vehicle Num. : SLQ 5394Z
 Make/Model : TOYOTA PRIUS HYBRID 1.8S
 Chassis/Eng# :
 Accident Date : 16/10/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR TAILGATE		922.50 ^{XR}
2.	1	REAR TAILGATE LOCK		447.40 ^{X SVC}
3.	1	REAR TAILGATE OUTER GARNISH		420.00 ^{X SVC}
4.	1	REAR TAILGATE PRIUS EMBLEM	^{NFC}	68.50
5.	1	REAR TAILGATE HYBRID EMBLEM	^{NFC}	52.30
6.	1	REAR BUMPER		423.90 [?]
7.	1	REAR LOWER BUMPER		552.30 ^{DEF}
8.	1	REAR BUMPER SIDE RETAINER		111.50 [?]
9.	1	REAR BUMPER REINFORCEMENT		318.80 [?]
10.	1	REAR BUMPER LOWER SIDE SPOILER LH		148.40 ^{XR}
11.	1	REAR BUMPER TAIL LAMP LH	^{SCR}	481.90
12.	1	REAR TAIL LAMP - LH		433.70 ^{CR}
13.	1	REAR WINDSCREEN GLASS MOULDING		29.50 ^{XNW}
14.	1	REAR TAILGATE LOWER GLASS MOULDING		27.60 ^{XNW}

List TotalS\$:	4,438.30
25.00% Discount S\$:	1,109.58
	<u>3,328.72</u>

SPECIAL NETT ITEMS :

1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS		30.00 [?]
2.	1SET	REAR TAILGATE OUTER GARNISH CLIPS		30.00 [?]
3.	1SET	REAR BUMPER CLIP		30.00 [?]
4.	2	WINDSCREEN SEALANT	80.00	160.00 ^{XNW}
5.	1SET	REVERSE SENSOR		280.00 [?]

Special Nett Total S\$:	530.00
--------------------------	--------

LABOUR :	
REMOVE & REFIT REAR WINDSCREEN GLASS (X2 GLASS)	360.00 ^{XNW}

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES180004

Date : 17/10/2018
 Vehicle Num. : SLQ 5394Z
 Make/Model : TOYOTA PRIUS HYBRID 1.8S
 Chassis/Eng# :
 Accident Date : 16/10/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

.		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00 <i>xun</i>
.		WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00 <i>50</i>
.		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		1,200.00 <i>700</i>
.		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS		1,200.00 <i>700</i>
.		Labour Total S\$:		3,120.00

NAZ LKX
 18/10/18 1130
 PIP
 4 DAYS

- CHECK ITEMS PHOTOS
- BEFORE PAINT PHOTOS

LKK Auto Consultant hereby notify
the Repairer of the following:

- To resurvey before commencing
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E.

Total S\$: 6,978.72