

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: SAPIYAH BINTE MOHAMED
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5101294263
 REFERENCE: TP CLAIM
 DATE OF ACCIDENT: 16/10/2018

712 AXA
Soj.

REPAIR ESTIMATE

Est. No. : E18100009
 Date : 17/10/2018
 Vehicle Num. : SLQ1915Y
 Make/Model : CHEVROLET ,ORLANDO
 1.4
 Chassis/Eng# : KL1YA7589HK612838
 Yr. of Manu : 2017

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	REAR BUMPER (LOWER) <i>ut</i>	1.00	395.00	395.00 ✓
2	REAR BUMPER REINFORCEMENT <i>neu</i>	1.00	691.00	691.00 ✓
3	REAR BUMPER REVERSE LAMP <i>neu</i>	1.00	166.00	166.00 ✓
4	REAR END PANEL <i>Repr</i>	1.00	621.00	621.00 ✓
5	REVERSE SENSOR <i>changed</i>	1.00	172.00	172.00 ✓
				Amt S\$ 2,045.00
				Discount (10.00%) S\$ 204.50
				Subtotal S\$ 1,840.50

567
510.30

Section: LABOUR				
6	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	550.00	550.00 <i>200</i>
7	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	450.00	450.00 <i>200</i>
				Amt S\$ 1,000.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,000.00

400

Surveyed by/Company : _____
 Contact Number : _____
 Date/Time : _____
 Licensed Automotive Surveyor's Sign : _____

total: 910.30
4/5 700.
Adrian King
4/5 18/10/18.
02 Pags

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Joo Hak Kee Auto Pte. Ltd.



LIST ITEMS Subtotal S\$ 1,840.50
LABOUR Subtotal S\$ 1,000.00
Total S\$ 2,840.50

BLK 3011 NRI ROAD #01-406, SINGAPORE 408701 TEL: 6743 1913 FAX: 6743 5234 CO/GST REG NO: 201300082W
 BLK 3014 NRI ROAD #01-324, SINGAPORE 408702 EMAIL: admin@jhk.com.sg WEBSITE: www.jhk.com.sg

Date: _____

bizSAFE 3