

STRICTLY

Xhd.

REF: III

8623m

ASSIGNMENT

From: Date: 23/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YN6750J

at Workshop m/s:

GoldBell Engineering

of 48 changi south street

Insured

Policy No:

9797127 lewei

Claims No:

Sum Insured:

Excess:

(Client's Record)

After 10am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res:

Yes or No

Lump Sum:

300

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YN6750J

Yr Regn:

13 Nov 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi

C.C:

7545

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

19349.7

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FMGS FMA10118

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

11R 22.5

R:

11

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA (Tt)

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6/6

mm

L/Bal:

6

mm

L/Bal:

6/6

mm

D.O.A.

D.O.I.

23-10-18

Survey held at

w/s

12 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1700.24

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + P.S. \$

Therap

Other:

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

plmt 170024 / \$1,756.36 / 50.81%



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
10 Tuas Avenue 18 Singapore 638894
Tel: +65 6831 0007 Fax: +65 6801 3676 (Sales)
Fax: +65 6853 0425 (Service) +65 6852 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 105001963G

Page 1 / 2

ESTIMATE

Date	: 18/10/2018	Reg No	: YN6750J
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: FM65FM2RDEB C/C
Attn.	:	Chassis No	: FM65FMA10118
Office / Mobile	:	Engine No	: 6M60194440
Email Address	:	Quotation No.	: 73977
		Ref. No.	: GBE/SVC/SALES-4708/181018
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 13/06/2018
Attn.	: LILEWEI	Policy No.	: M496479
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - III
Email / Fax No.	: LILewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MX915944	LAMP, LICENSE PLATE <i>1 PC</i>	2	66.98	-25	50.24	100.47
PARTS TOTAL :							100.47

SPECIAL NETT ITEMS

1	REAR BUMPER	1	600	950.00
2	REAR BUMPER BRACKET LHS	1		250.00
3	REAR NUMBER PLATE	1	10	20.00
PARTS TOTAL:				1220.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600	1200.00	610
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK	180	280.00	
3	TO PUTTY, CLEAN, SPRAY PAINT, ETC.	250	400.00	
4	SUNDRIES <i>1040</i>	10	30.00	

LABOUR TOTAL : 1,910.00

SUB-TOTAL : 3,230.47

GST @ 7% for \$ 3,230.47 226.13

GRAND TOTAL (S\$) : 3,456.60

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 Days. 1700.24
part by part.
Before paint photos.
After paint photos.
23/10/18 **biSAFE**



Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 10 May 2019 5:23 PM
To: Ramesh
Cc: William Oh Soon Lee; Ashlyn Chng; Admin A
Subject: RE: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018
Attachments: DV YN 6750J.pdf
Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/III18019032/Gfa3
Your Ref: YN 6750J

Dear Ramesh,

We refer to above matter and your letter of demand.

We hereby confirmed settlement as below:

1. Cost of Repair (w/gst)	S\$ 1,819.26
2. Loss of Use (\$180.00 x 2days)	S\$ 360.00
	S\$ 2,179.26

Please duly sign the DV attached and return with Authorization to ACT to us (LKK) for payment processing.

We need original copy DV and documents in your letter of demand.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAUTO)


From: Ramesh <Ramesh@goldbell.com.sg>
Sent: Tuesday, 14 May 2019 3:09 PM
To: Poh Kin (LKKAUTO)
Cc: William Oh Soon Lee; Admin A
Subject: RE: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018
Attachments: 13052019123721-0001.pdf; 20190513172752407.pdf
Categories: clear

Dear Ms. Poh Kin,

We have attached above DV and Letter of Authority for your records and will send original to you.

Thank you.

 **Ramesh | Goldbell Engineering Pte Ltd**
Senior Executive, Motor Claims
DID: +65 6864 0695 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 8157 8014 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Tuas)
8 Tuas Ave 18 Singapore 638894


From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Friday, May 10, 2019 5:23 PM
To: Ramesh <Ramesh@goldbell.com.sg>
Cc: William Oh Soon Lee <WilliamOhSL@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018
Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/III18019032/Gfa3
Your Ref: YN 6750J

Dear Ramesh,

We refer to above matter and your letter of demand.

We hereby confirmed settlement as below:

1. Cost of Repair (w/gst)	S\$ 1,819.26
2. Loss of Use (\$180.00 x 2days)	S\$ 360.00
	S\$ 2,179.26

Please duly sign the DV attached and return with Authorization to ACT to us (LKK) for payment processing.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Friday, 2 November 2018 6:22 PM
To: 'LiLewei@goldbell.com.sg'; 'Ramesh@goldbell.com.sg'
Cc: Guo Qiang (LKKAUTO)
Subject: RE: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018

Importance: High

"Without Prejudice"

Our Ref: CC4/III18019032/Gfa3
Your Ref: YN 6750J

Dear Sir,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018

We refer to the above matter.

For COR, our surveyor had recommended amount for COR at P/P: **\$1,700.24 with 2 repair days.**

Please note that: All finalisation is subject to our Principal Insurer's approval.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action. We need **original copy LOD.**

In the meantime, we appreciate if you could furnish us a copy of **before paint photo & after repair photo** for our file record.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability, damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | Email: pohkin@lkk.com.sg | Fax: 6741-4108

Blk 51, Paya Lebar Road #01-10/11, Singapore 409251 | 84408933

LKK  *Call only when necessary*

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Friday, 2 November 2018 6:04 PM
To: 'LiLewei@goldbell.com.sg'; 'Ramesh@goldbell.com.sg'
Cc: Admin A
Subject: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018

Importance: High

"Without Prejudice"

Our Ref: CC4/III18019032/Gfa3
Your Ref: YN 6750J

Dear Sir,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHC 2855B, YN 6750J AND OTHERS ON 13/06/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, UB 1, #02-25 | S(408033)

LKK  *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

View Received Message

This mail is associated with :

***YN6750J (MCT18060417)
[SHC2855B]**

TP
SINGAPORE POST LIMITED
Jun 13 2018 6:00PM
[-]
Goldbell Engineering Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/05/2019 15:56 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2179.26) - YN6750J - Claim Handler: Priya

Approved:2179.26.

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

This mail is associated with :

***YN6750J (MCT18060417)**
[SHC2855B]

TP
SINGAPORE POST LIMITED
Jun 13 2018 6:00PM

Goldbell Engineering Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/11/2018 16:48 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - YN6750J - Claim Handler: Priya

Approved:0.00.

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	19 Oct 2018 15:23	Clim Veh Model Changed	(204571) MITSUBISHI FUSO 7.5 D FM65FM2RDEB (M).		[A] HOW MEI KWAN
2	19 Oct 2018 15:23	Clim Created	Reg No: YN67503, Acct Date: 2018/06/13, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: India International Insurance Pte Ltd (HQ), Workshop: Goldbell Engineering Pte Ltd ((Tuas))		[A] HOW MEI KWAN
3	19 Oct 2018 15:23	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] HOW MEI KWAN
4	19 Oct 2018 15:23	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/10/30		[A] HOW MEI KWAN
5	19 Oct 2018 15:23	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.		[A] HOW MEI KWAN
6	19 Oct 2018 15:23	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.		[A] HOW MEI KWAN
7	19 Oct 2018 15:23	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID		[A] HOW MEI KWAN
8	22 Oct 2018 08:46	TP Ins Updated	TPRegNo:SHC2885B -> SHC2855B.		[I] Gabriel Wee
9	26 Oct 2018 12:24	Label Removed	(30651):Vehicle Not In.		[A] HOW MEI KWAN
10	26 Oct 2018 12:24	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> XING GUO QIANG		[A] HOW MEI KWAN
11	02 Nov 2018 16:23	Adj Mandate Request	Cur,Req:0.00:PODS Liability:0% Remarks: 3 car chain collision, TP is first vehicle and OI D is second vehicle and was push forward by behind vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim		[A] Chong Poh Kin

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Print Received Message

This mail is associated with :

***YN6750J (MCT18060417)
[SHC2855B]**

TP
SINGAPORE POST LIMITED
Jun 13 2018 6:00PM

[~]
Goldbell Engineering Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/05/2019 15:56 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2179.26) - YN6750J - Claim Handler: Priya

Approved:2179.26.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 19 October 2018 9:31 AM
To: Li Lewei; Ramesh; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: SHC 2855 B
Attachments: Accident Report - YN6750J.PDF; Estimate.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle YN6750J and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 10B Building | Singapore 049711

Tel: 6347 6100, Ext - 248

10:30am @ 19/10/18.
person @ Lewei
VNI

From: Li Lewei [mailto:LiLewei@goldbell.com.sg]

Sent: 19 October, 2018 8:52 AM

To: Motor Claim - III <motorclaim@iii.com.sg>; Ramesh <Ramesh@goldbell.com.sg>

Cc: Derek Chow Zhi Da <DerekChowZD@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>

Subject: RE: SHC 2885 B

Dear Gabriel,

Kindly arrange LKK to survey the vehicle.

Thanks & Best Regards,

Li Lewei | Goldbell Engineering Pte Ltd

Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |

Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>

Address: Goldbell Engineering Pte Ltd (Tuas)

8 Tuas Ave 18 Singapore 638894

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Thursday, October 18, 2018 2:36 PM
To: Ramesh <Ramesh@goldbell.com.sg>; Li Lewei <LiLewei@goldbell.com.sg>
Cc: Derek Chow Zhi Da <DerekChowZD@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>
Subject: RE: SHC 2885 B

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Ramesh [mailto:Ramesh@goldbell.com.sg]
Sent: 18 October, 2018 1:50 PM
To: Motor Claim - III <motorclaim@iii.com.sg>; Li Lewei <LiLewei@goldbell.com.sg>
Cc: Derek Chow Zhi Da <DerekChowZD@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>
Subject: RE: SHC 2885 B
Importance: High

Dear Gabriel,



Taxi No. is SHC2855B

SHC2855B is insured under us not SHC2885B.

Please info your surveyor to contact our Motor Claims Officer for survey

Meantime we get out customer to amend the mistake.

Thank you.

Ramesh | Goldbell Engineering Pte Ltd
Senior Executive, Motor Claims

DID: +65 6864 0695 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 8157 8014 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Tuas)
8 Tuas Ave 18 Singapore 638894

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Thursday, October 18, 2018 9:48 AM

To: Li Lewei <LiLewei@goldbell.com.sg>

Cc: Derek Chow Zhi Da <DerekChowZD@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>; Ramesh <Ramesh@goldbell.com.sg>

Subject: RE: SHC 2885 B

Dear Sirs,

SHC2855B is insured under us not SHC2885B.

Kindly confirm the vehicle number.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Li Lewei [mailto:LiLewei@golddbell.com.sg]

Sent: 18 October, 2018 9:04 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Derek Chow Zhi Da <DerekChowZD@golddbell.com.sg>; Ashlyn Chng <AshlynChng@golddbell.com.sg>; Ramesh <Ramesh@golddbell.com.sg>

Subject: SHC 2885 B

Dear Sir/Madam,

Kindly advise if the mentioned vehicle is your insured.

Thanks & Best Regards,

Li Lewei | Goldbell Engineering Pte Ltd

Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |

Mobile: +65 9755 7336 | Web: <http://www.golddbell.com.sg>

Address: Goldbell Engineering Pte Ltd (Tuas)

8 Tuas Ave 18 Singapore 638894

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



GOLDBELL
ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638864
Tel: +65 6861 3007 Fax: +65 6861 3576 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
CIN Reg No: 108003400

07 March 2019

Our Reference : YN6750J

INDIA INTERNATIONAL INSURANCE PTE. LTD.

64 CECIL STREET
#04-02 IOB BUILDING
Singapore 047711

Attn: MOTOR CLAIMS DEPT.

Dear Sir,

Subject: Accident Involving YN6750J and SHC2885B on 013/06/2018 along Jalan Buroh towards Toll Logistics

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. XB8729J

We quantify our client's claim as follows:

1. Cost of Repair (\$1700.24 x 7% GST)	S\$	1819.26
2. Loss of Use (\$180 x 2 days)	S\$	360.00
Total	S\$	2179.26

We hereby append the following relevant documents for your perusal:

- I. Repair Bill Tax Invoice
- II. Surveyor COR confirmation

Best regards,

RAMESH
Motor Claims
GOLDBELL Engineering Pte Ltd
Tel : 8157 8014

LETTER OF AUTHORITY

I/We, SINGAPORE POST LIMITED, owner of
YN 67503 (Vehicle no.) hereby authorize GOLDBELL ENGINEERING PTE LTD to act
on my/our behalf with respect to my/our claim for repair costs and/or rental and/or loss of
use for my vehicle no. YN 67503 that was damage pursuant to the accident
which occurred on 13/06/2019 at/along Pie Townards Changi Lamp Post 156
involving vehicle no. SHC 2855B.

I/We further authorize GOLDBELL ENGINEERING PTE LTD to have full discretion to
settle my/our above mentioned claim in a manner that they deem fit and to sign any
discharge voucher or receive any payment on my/our behalf further to the settlement of
my/our claim with payment cheque/s being made in favor of GOLDBELL ENGINEERING
PTE LTD.

I/We further acknowledge that any settlement that GOLDBELL ENGINEERING PTE LTD
may reach on my/our behalf is in full and final settlement of my/our property damage
claims against the owner/ driver/ motor insurer of the third party vehicle bearing
registration number SHC 2855B and is on a without prejudice / without admission
of liability basis insofar as the driver/ owner/ motor insurer of vehicle concerned.

Date this 13 day of May (month) 2019 (year)

Signature of claimant



(With Company Stamp of applicable)

Name of claimant

TAN CHEE KOON

Company reg. / NRIC no.

S7044106C

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

Without Prejudice
to any claim for
personal injury

India Ref: TP / MCT18080417

Claimant Ref: YN 6750J

We/I, Goldbell Engineering Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 1,819.26 (repair cost), S\$ 360.00 (loss of use/rental), S\$ — (search fee), vehicle no. YN 6750J that was damaged pursuant to the accident which occurred on 13/08/2018 (date) at PIE towards Changi (location) involving vehicle no. SHC 2855B (insured vehicle). This is pursuant to the inspection conducted on 19/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Singapore Post Limited ("the third party claimant") of vehicle no. YN 6750J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to YN 6750J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,179.26 to Goldbell Engineering Pte Ltd

Dated this 24th day of May 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

RAMESH S/SOMASUNDARAM

NRIC:

S6435991D

Address:

B1K296L COMPASSvale CRESCENT
#05-253 4'PORE 543296

Nationality:

SINGAPOREAN

Occupation:

SENIOR EXECUTIVE, MOTOR CLAIMS

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



XGA

LKK AUTO CONSULTANTS PL

51 Ubi Ave 1
Paya Ubi Industrial Park
Singapore 408933
Tel: 6256 3561

LKK AUTO CONSULTANTS PL

51 Ubi Ave 1, #01-25
Paya Ubi Industrial Park
Singapore 408933
Tel: 6256 3561



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3678

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Ce. Reg. No.: 190003963G

Page 1 / 2

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-02 IOB BUILDING
SINGAPORE 049711

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : EXI00149389
Invoice Date. : 18-12-2018
Account No. : C00001902
Quotation No. : 73977
Work Order No. : 693131
Service Centre. : 8 TUAS AVE 18
Agreement No. : GBE-34017

PARTICULARS

AMOUNT SGD

Reg No : YN6750J
Chassis No : FM65FMA10118
Engine No : 6M60194440
Model No : FM65FM2RDEB C/C
Mileage : 193497
SRR No :

ACCIDENT REPAIR: GBE/SVC/SALES-4708/181018
DATE OF ACCIDENT: 13/06/2018
POLICY NO.: M496479

**** TP CLAIM - III ****

ITEM 1: TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC

ITEM 2: TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK

ITEM 3: TO PUTTY, CLEAN, SPRAY PAINT, ETC

ITEM 4: SUNDRIES

Description	QTY	U/Price	Disc	Net Price	Ext Price
LAMP, LICENSE PLATE	1	50.24	N	50.24	50.24
REAR BUMPER	1	600.00	N	600.00	600.00
REAR NUMBER PLATE	1	10.00	N	10.00	10.00
LABOUR CHARGES (REFER TO ITEM 1)	1	600.00	N	600.00	600.00
LABOUR CHARGES (REFER TO ITEM 2)	1	180.00	N	180.00	180.00
LABOUR CHARGES (REFER TO ITEM 3)	1	250.00	N	250.00	250.00
LABOUR CHARGES (REFER TO ITEM 4)	1	10.00	N	10.00	10.00

Parts Charges: 1700.24

Sub Total: 1700.24

GST @ 7.00 % 119.02

E. & O. E



AIRMAN.





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 199003663G

Page 2 / 2

TOTAL 1819.26

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD.
When making payment, please quote our invoice numbers.
No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.

FUSO

AIRMAN.

biSAFE
STARS



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2018 Edit Reg		19 Oct 2018 00:00 Edit Adj Rpt	S\$1,700.23 Edit Estimates	S\$1,700.23 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	SINGAPORE POST LIMITED, Co. Reg. No.: 199201623M								
Vehicle Reg. No.:	YN6750J	Date of Loss:	13/06/2018 18:00 - :59 [43 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060417	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC2855B	Policy No. (Claimant):	M496479						
		Excess:							
Repairer:	Goldbell Engineering Pte Ltd ((Tuas)) No. 10 Tuas Avenue 18, 638894 Tuas - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (10/05/2019): Alert - Adj Mandate Approved (S\$2179.26) - YN6750J - Claim Handler: Priya III_SG (02/11/2018): Alert - Adj Mandate Approved (S\$0.00) - YN6750J - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YN6750J (MCT18060417)
[SHC2855B]
TP
SINGAPORE POST LIMITED
Jun 13 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
Goldbell Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
2	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
3	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
4	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
5	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
6	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
7	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
8	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
9	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
10	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
11	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
12	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
13	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
14	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
15	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
16	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
17	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
18	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
19	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
20	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
21	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
22	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
23	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
24	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
25	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
26	03/11/18 09:35	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>			
27	03/11/18 09:35	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>			
28	03/11/18 09:35	General View	1	Load JPG	<input checked="" type="checkbox"/>			
							1 per page	<input checked="" type="checkbox"/>
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	19/10/18 15:24	ACKNOWLEDGEMENT EMAIL TO III DD 19.10.2018	1	Load PDF				
2	19/10/18 15:24	TP ESTIMATE	1	Load PDF				
3	19/10/18 15:24	TP GIA REPORT	1	Load PDF				
4	27/10/18 22:47	TP ESTIMATE-MARKED	1	Load PDF				
5	12/03/19 08:52	WORKSHOP INVOICE	1	Load PDF				
6	12/03/19 08:52	LOD	1	Load PDF				
7	31/05/19 09:09	DISCHARGE VOUCHER	1	Load PDF				
8	31/05/19 09:09	AUTHORISATION TO ACT FORM	1	Load PDF				

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	31/10/18 09:39	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18019032/GFA3Q2

Date: 31/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : YN6750J

Insured Vehicle No : SHC2855B

Date of Loss: 13/06/2018

Nature of Claim:

TP

Claim No: MCT18060417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN6750J

Make & Model: MITSUBISHI FUSO, 7.5 D FM65FM2RDEB (M)

Engine No: 8M60194440

Reg. Date: 13/11/2014 (Man. Year: 2014)

Chassis No: FM65FMA10118

Colour: Blue

Odometer: 193497 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5

Rear Tyre Size:

11 R22.5 (D)

Front Left Side: Firenza 6 mm

Rear Left Side:

Bridgestone 6/6 mm

Front Right Side: Firenza 6 mm

Rear Right Side:

Bridgestone 6/6 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,350.47	670.23	680.24	50.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,030.00	850.00	45.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,230.47	1,700.23	1,530.24	47.37
+ GST 7.00/7.00% (S\$)	226.13	119.02	107.11	47.37
Nett Amount (S\$)	3,456.60	1,819.25	1,637.35	47.37
+ Loss of Use (2.0 x S\$180.00/day) (S\$)		360.00		
	Nett Liability (S\$)	2,179.25		

INSPECTION

Date of Assignment: 19/10/2018

Date Inspected: 23/10/2018 Inspected At:

48 CHANGI SOUTH STREET 1

SINGAPORE 486130

Repairer: Goldbell Engineering Pte Ltd

((Tuas))

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 May 2019)	
Parts:	N/A	MITSUBISHI FUSO 7.5 D FM65FM2RDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN6750J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ,LICENSE PLATE	Cracked (1 PCS ONLY)	133.96 FL	*66.98 FL
2	1		*REAR BUMPER	Bent	950.00 FS	*600.00 FS
3	1		*REAR BUMPER BRACKET LHS	Not Necessary	250.00 FS	*- FS
4	1		*REAR NUMBER PLATE	Bent	20.00 FS	*10.00 FS
5	1		*SUNDRIES	Necessary	30.00 FS	*10.00 FS
					Sub Total (\$\$)	1,383.96 686.98
					- List Item Discount on L Items 25.00/25.00% (\$\$)	33.49 16.75
					Total Parts (\$\$)	1,350.47 670.23

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGN ,ETC	New	1,200.00	600.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS ,TO CONDUCT DIAGNOSTIC CHECK	New	280.00	180.00
3	TO PUTTY ,CLEAN ,SPRAY PAINT ,ETC	New	400.00	250.00
Gross Labour Cost (S\$)			1,880.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >