

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Oct 2018

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-----------------|
| Vehicle No | : SLR3073H | Accident Date | : 18/10/2018 |
| Make | : AUDI A3 | Policy No. | : 1700037426-01 |
| Assignment Date | : 22/10/2018 | Excess | : S\$0.00 |
| Date of Inspection | : 22/10/2018 | Est. Duration of Repair | : 21 days |
| Inspection At | : Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 75,347.00 |
| Revised Amount | :S\$ | 57,016.00 |
| Check Items (Estimated) | :S\$ | 6,365.00 |
| Total | :S\$ | 63,381.00 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|---------------------------------------|
| New for Old Value | :S\$ | 136,440.00 |
| Pre-Accident Value | :S\$ | 97,000.00 |
| COE / PARF Rebate | :S\$ | 49,815.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 86,625.00 (NEW CAR VALUE MINUS RESIDU |
| | :S\$ | 47,185.00 (MARKET VALUE MINUS RESIDU/ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :