



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

FWD Singapore Pte. Ltd.
6 Temasek Boulevard #18-01
Suntec Tower 4 038986

Attention : Motor Claim Department
Contact : 68208888

Not Authored
Re survey B & paint
4-5 days

Estimate : E18/2464

Date : 12/10/2018
Vehicle Num. : SKM818J
Make/Model : TOYOTA ALPHARD-2016
Chassis/Eng# : GGH300005812/2GRK108390
Accident Date : 17/10/2018
Claim No. : TP CLAIM
Reference : BFG
Policy No. : GA258270

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER		
2.	2PCS	REAR BUMPER REFLECTOR		
3.	1PC	TAIL GATE RUBBER		
4.	2PCS	REAR BUMPER RETAINER		
5.	1PC	TAIL GATE		
6.	1PC	REAR END PANEL		
7.	1PC	REAR END PANEL GARNISH		
8.	1PC	REAR WINDSCREEN GLASS MOULDING		
List TotalS\$:				7,059.83
25.00% Discount S\$:				1,764.96
				5,294.87
SPECIAL NETT ITEMS :				
1.	8PCS	REAR BUMPER CLIPS	5.80	46.40
2.	4PCS	REVERSE SENSOR	120.00	480.00
3.	1TUBE	SEALANT		25.00
4.	1PC	EMBLEM (VELLFIRE)		165.60
5.	1PC	EMBLEM (V6)		52.20
Special Nett Total S\$:				769.20
LABOUR :				
TO PANEL BEATING ON AFFECTED AREAS			500	800.00
TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS			500	1,200.00
TO APPLY ANTI-RUST				100.00
TO CHECK WIRING				60.00
TO REMOVE & INSTALL REVERSE SENSOR				150.00

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
 Sin Ming Autocare Complex
 Singapore 575721
 Tel : (65) 6455 0600
 Fax : (65) 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

FWD Singapore Pte. Ltd.
 6 Temasek Boulevard #18-01
 Suntec Tower 4 038986

Attention : Motor Claim Department
 Contact : 68208888

Estimate : E18/2464

Date : 12/10/2018
 Vehicle Num. : SKM818J
 Make/Model : TOYOTA ALPHARD-2016
 Chassis/Eng# : GGH300005812/2GRK108390
 Accident Date : 17/10/2018
 Claim No. : TP CLAIM
 Reference : BFG
 Policy No. : GA258270

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO DISMANTLE & REFIX ALL PARTS AS ABOVE		100.00 ?
		TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS		120.00 ✓
		TO CHECK WATER SEEPAGE		80.00 x
		Labour Total S\$:		2,610.00

E. & O.E.

Total S\$: 8,674.07

for Sin Ming Autocare BFG Pte Ltd