

SHB 6607E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating		\$ 1,500.00	800/-
	Spray Painting Charge		\$ 1,250.00	700/-
	Wiring Charge		\$ 50.00	30/-
	Tuff Kote		\$ 50.00	30/-
	Towing Charge		\$ 50.00	NH
	Remove/Refix Cushion & Upholstery Rear		\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass		\$ 120.00	80/-
	Remove/Refix Reverse Sensor		\$ 120.00	NH
	Remove/Refix Fuel Tank		\$ 150.00	NH
	Remove/Refix Exhaust Pipe		\$ 200.00	60/-
	Diagnostic & Resetting To Erase Fault Code		\$ 480.00	NH
	TOTAL LABOUR		\$ 4,120.00	
	ESTIMATE TOTAL		\$ 14,718.72	
22/10/2018 c 1100hrs Nkt Andrew 2/5mm Ryan LKK Auto 6 days.				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Y. Eels

FAX : 6542 6039

✓