

PDITUAS

NG HSING MEI, LINDA (WENG XINMEI) 6 LILAC DRIVE Singapore, 808196 Singapore

PDI TUAS

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. 199101494Z

Service Quote

Customer No.

CV037215

Quote No.

SER/QUO/1801751

QuoteDate

19/10/18

Salesperson

Bryan Toh Pee Tian

Page

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Volkswagen Passeng

License No. SLJ6060S

Engine Code

Model Description

GOLF A7 1.2 TL 81 (DSG) VIN

WVWZZZAUZGW222497

Labor Type

1T

Mileage 19,870

Initial Registration

11/05/17 Engine No. CYV 103999

Service Advisor Tang Shu Shi

Sales Advisor Bryan Toh Pee Tian

Model Code 5G12BZ

	No.	Description	Qty.	UoM Unit Pr	ice Amount
Р	B&P MACP LABOUR	TFR DOOR MECH	1	UNIT	420 840.00
P	B&P MACP LABOUR	LABOUR	4	UNIT	1260 3,360.00
Р	B&P MACP PAINT	SPRAY PAINT		UNIT	/600 3,200.00
Р	B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC		Time Un	480.00
P	B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un	280.00
		Sum Labor			8,160.00
Р	5G4831055AQ	LHF DOOR	1	Pieces	8 1,938.65
Р	5G4837651B	DOOR SEAL	1	Pieces	109.43
		Use Predecessor 5G4837651A			ner-
P	D 314D36M2	UNDERSEAL	1	Pieces	108.17
P	D 378500A2	LHF DOOR INSULATOR	1	Pieces	New 46.23
		Sum Item			2,202.48
				Sum Labor	8,160.00
				Sum Item	2,202.48
				Total SGD	10,362.48
				7% GST	10,362.48 725.37
				Total SGD Incl. GS	ST 11,087.85



PDITUAS

NG HSING MEI, LINDA (WENG XINMEI) 6 LILAC DRIVE Singapore, 808196 Singapore

PDI TUAS

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. 199101494Z

Service Quote

Customer No.

CV037215

Quote No

SER/QUO/1801751

QuoteDate

19/10/18

Salesperson

Bryan Toh Pee Tian

Page

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Volkswagen Passeng

License No.

SLJ6060S

Engine Code

Model Description

GOLF A7 1.2 TL 81 (DSG)

VIN

WVWZZZAUZGW222497

Labor Type

1T

Mileage 19,870

Initial Registration

11/05/17 Engine No. CYV 103999

Service Advisor Tang Shu Shi Sales Advisor

Bryan Toh Pee Tian

Model Code 5G12BZ

Explanations

P = Proportionately Charged

Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

To resurve before/after spray painting

To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resmy by puint