

CHUNNI MOTOR WORKS PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7594G (Supplementary)

DATE : 23.10.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

1/ Below

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender Apron Panel (RH) <i>Painted</i>			\$ 637.00 ✓
	SUB TOTAL			\$ 637.00
	LESS 20%			\$ 127.40
	DISCOUNTED TOTAL			\$ 509.60
<i>26/10/2018 @ 1330m</i> <i>not done</i> <i>Typo</i> <i>2kk Auto</i> <i>8</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				