

REPAIR ESTIMATE

VEHICLE NO : SH 9128P

MAKE :

MODEL : TOYOTA PRIUS

22/10/2018 15:27

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LAMP ASSY, FOG, RH <i>X su</i>			\$ 920.00
FRONT BUMPER COVER <i>- Panel</i>			\$ 499.90
FRONT BUMPER CLIPS <i>- ac</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER <i>X su</i>		\$ 77.00	\$ 154.00
UNIT ASSY, HEADLAMP, RH (LED) <i>- gross</i>			\$ 3,455.00
FENDER SUB-ASSY, FRONT RH <i>- Part</i>			\$ 945.30
FRONT FENDER SHIELD, RH <i>X su</i>			\$ 196.60
FRONT FENDER SHIELD CLIP <i>X su</i>			\$ 3.80
FRONT FENDER HYBRID EMBLEM, RH <i>- ac</i>			\$ 53.50
<i>Front Door (RH) X repair</i>			
SUB TOTAL			\$ 6,250.10
LESS 20% <i>25%</i>			\$ 1,250.02
DISCOUNTED TOTAL			\$ 5,000.08
FRONT DOOR COMFORT LOGO <i>- ac</i>			\$ 75.00
LABOUR CHARGE			
Panel Beating			\$ 800.00
Spray Painting Charge			\$ 900.00
Wiring Charge			\$ 30.00
Tuff Kote			\$ 50.00
TOTAL LABOUR			\$ 1,780.00
ESTIMATE TOTAL			\$ 6,855.08

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NETT

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.