

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT19000284	Page	1
	3 ANSON ROAD #16-00	Date	: 16. Jan 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLW8476U	Engine No	: L13B11030177		
Chassis No	: JHMGK3850JX205710	Date Time	: 16. Jan 2019 10:58:01 AM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: KAH MOTOR CO. SDN. BHD.	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 15/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
SUPPLEMENTARY PARTS & LABOUR							
04631-TAR-300ZZ	PANEL SET,R.SIDE <i>DS</i>	<i>20/21</i> 1	227.80	25	170.85	11.96	182.81
Sum Item					<u>170.85</u>	<u>11.96</u>	<u>182.81</u>
BKSP12R	CUT OFF & RENEW R SILL PANEL. STRAIGHTEN ALIGN 1		1400.00	<i>500</i>	1400.00	98.00	1498.00
Sum Labor					<u>1400.00</u>	<u>98.00</u>	<u>1,498.00</u>

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 1,570.85 109.96 1,680.81

Total (Inclusive of GST) 1,680.81

Printed on 16/1/2019 11:01:12 AM

This is a computer generated Invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)