

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 35J

AAD1810-209

Not Authorised
11 Sep 8/100d

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 35J
 VF1ABL15AUC280998
 RENAULT
 LATITUDE
 18.10.18
III

PART**LIST**

1	BUMPER COVER FRT	\$	<i>N</i> 1,259.42	} X
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68	
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77	
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88	
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83	
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80	
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21	
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08	
1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43	
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15	} X
1	FENDER PANEL FRT RH	\$	<i>N</i> 783.83	
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84	
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79	
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84	
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>N</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79	
1	LOWER ARM RH L70Y	\$	<i>Sn</i> 685.76	} X
1	KNUCKLE ARM RH L70Y	\$	<i>Sn</i> 846.98	
1	ABSORBER FRT RH L70Y	\$	<i>Sn</i> 360.54	
1	DRIVESHAFT RH	\$	<i>N</i> 1,747.45	
1	STABILIZER BAR FRT	\$	<i>Sn</i> 604.65	
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06	
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25	
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11	

TOTAL \$ 15,509.69
10% \$ 1,550.97

Trans-cab Auto Services Pte Ltd

AAD1810-209

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 35J

\$	13,958.72
----	-----------

Special Nett

1SET	BUMPER CLIP FRT	\$	nn	66.00	} X
1	BUMPER BRACKET CLIP FRT RH	\$	Sh	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	
1SET	Front licence plate with holder	\$	Sh	80.00	
1	FRONT RIGHT TYRE	\$	Sh	330.00	
1	FRONT RIGHT TYRE RIM	\$	Sh	380.00	
1	WINDSCREEN SEALANT	\$	nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	

TOTAL	\$	1,571.80
-------	----	----------

TOTAL PARTS	\$	15,530.52
-------------	----	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same.	\$	3,000.00	200/
Putty and spray painting of the affected portion.	\$	3,000.00	440/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To rust-proofing of the affected areas.	\$	170.00	30/

Trans-cab Auto Services Pte Ltd

AAD1810-209

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 35J

To transfer of front windscreen fittings and conduct water seepage test	\$	na	170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	na	380.00	X
To replace, refix and top up coolant for radiator	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	152
To vacuum, replace, refix and recharge Air Intercooler	\$	na	170.00	X

TOTAL	\$	9,140.00
--------------	-----------	-----------------

Over All Total	\$	24,670.52
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10~~ DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: