FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

24/10/18 24/10/18 2/5 # 11.000 12 dy.

VEHICLE NO: SJM	9181P	
QTY	PARTICULAR	. //
1 PCS	BOOTLID /149.30	3 9 4 D \$1 945 100
1 PCS	BOOTLID OUTER CHROME MOULDING 455.10	Sutlene \$1,845.10
2 PCS	BOOTLID HINGES @\$195.00	Ms Bert \$390.00 (A)
2PCS	BOOTLID HINGE GARNISHS @\$105.00	
1 PCS	BOOTLID REAR LOGO	\$210.00 pc
1 PCS	BOOTLID 'ALLION' EMBLEM	See \$68.20
1 PCS	BOOTLID 'ALS' EMBLEM	\$60.80
1 PCS	BOOTLID INNER LOCK	ly/In \$399.20
1 PCS	BOOTLID INNER TRIM	De/4011 \$385.10
1 SET	BOOTLID INNER TRIM CLIPS	\$50.00
1 PCS	BOOTLID WEATHERSTRIP	4N \$299.20
2 PCS	BOOTLID STOPPER @\$10.50	\$21.00 X
1 PCS	REAR WINDSCEEN /3/5.10	Shuthed \$1,560.10
1 PCS	REAR WINDSCREEN MOULDING	Nec \$166.50
1 PCS	REAR WINDSCREEN WIPER ARM	11 \$215.00
1 PCS	REAR WINDSCREEN WIPER MOTOR	\$620.10 ×
1 PCS	REAR BUMPER /355.00	ال \$1,450.10
2 PCS	REAR BUMPER SIDE RETAINERS @ \$105.00 for x2 = 170	Sy \$210.00
2 PCS	REAR BUMPER REFLECTORS @\$215.00 95 x2=180	310 \$430,00
1 PCS	REAR BUMPER BRACKET N/S	\$98.50
1 SET	REAR BUMPER CLIPS	rer \$50.00
2 PCS	TAILLAMPS @\$680.10 450 x 2 = 800 ASSAU	ols en \$1,360.20
1 PCS	TAILLAMP HOUSING PANEL N/S	Ms see \$485.10
1 PCS	REAR END PANEL 655	3-400 \$980.10
1 PCS	REAR END PANEL TOP GARNISH 199,80	tw/ \$450.10
1 PCS	REAR END PANEL LOCK SENSOR	cm \$385.00
2 PCS	REAR FENDERS @\$1500.00 1099.50 WS Buc	0/5/2 \$3,000.00/20
2 PCS	REAR FENDER INNER TRIMS @\$488.10	\$976.20 120
1 SET	REAR FENDER INNER TRIM CLIPS	¢50.00
2 PCS	REAR FENDER UNDER COVERS @\$92.50	\$40E 00
1 PCS	REAR CHASSIS MEMBER N/S	\$669.10
1 PCS	REAR FLOOR PANEL 1228.50	mples Suc \$1,420.10
1 PCS	REAR FLOOR PANEL TOP BOARD	Suc \$610.80 X
1 PCS	REAR DOOR N/S	\$1,245.10
1 PCS	REAR DOOR INNER LOCK N/S	\$433.10 ×
		\$21,500.40
	S.NETT	721,000.70
1 PCS	REAR LICENCE PLATE W/HOLDER	Self \$50.00 40
1 SET	REAR REVERSE CAMERA	shell \$380.00 350
		4000.00 340

120657

1 PCS 1 SET 1 PCS 1 SET 1 PCS	REAR END PANEL SEALANT REAR BUMPER REVERSE SENSOR REAR WINDSCREEN SEALANT REAR FLOOR PANEL INSULATOR REAR WINDSCREEN SOLAR FILM	shub rer rer	\$50.00 \$280.00 \$50.00 \$300.00 \$300.00	
	LABOUR CHRAGES: TO CHECK WIRING		7	
	The second secon		\$80.00	
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00 🕏	
	TO TRANSFER REAR DOOR MECHANISM	11	\$100.00 ×	
	TO DISMANTLE & REPLACING REAR WINDSCREEN		\$150.00 / 20	
	TO SPRAY RUST PROOFING		\$150.00 / 20	
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY		\$150.00 \$12	
	TO MOUNT VEHICLE ON CAR O-LINER	11		
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED		\$2,500.00	
	REPLACING PARTS		42,500.002000	
	TO PUTTY & SPRAY PAINTING		\$1.800.00 128	
		TOTAL	\$28,300.40	

4660 13791.52