

Volkswagen Centre Singapore



Biz Reg. No. 53103069E
GST No. M20098505-2

MSIG (WINNER): 20/11/18

* No VIDEO *

Letter of Claims Request for direct settlement.

We are submitting a claim on behalf of our customer BALAKRISHNAN JAYAPRAKASH
NRIC S1367191E insured of vehicle SLC 3542 A against
your insured vehicle number SMC 330C (AIG)
On the accident dated on 24-10-18 (ddmmyyy) along COMMONWEALTH
Ave

Dated this 24 OCT 2018 (day) of _____ (month) 2018 .

Charmaine Kong
Volkswagen Group Singapore
Accident Claims Dept.
charmaine.kong@vw.com.sg
DID : 63057176/ 63057299
HP: 92361399

PDI TUAS

PDI TUAS

BALAKRISHNAN JAYAPRAKASH
53 LIMAU GARDEN
Singapore, 467912
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV033655
Quote No. SER/QUO/1801777
QuoteDate 24/10/18
Salesperson Anthony Yong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| | | | |
|--------------------|-----------------------------|-----------------------------|------------------------|
| Make | Model Description | Mileage | Service Advisor |
| Volkswagen Passeng | GOLF A7 1.4 CL 92 (DSG) EQP | 63,274 | Kong Charmaine |
| License No. | VIN | Initial Registration | Sales Advisor |
| SLC3542A | WVWZZZAUZGW078408 | 11/05/16 | Anthony Yong |
| Engine Code | Labor Type | Engine No. | Model Code |
| | 1T | CZC 063815 | 5G13HZ |

| No. | Description | Qty. | UoM | Unit Price | Amount |
|-----------------------|----------------------------|------|---------|------------|------------------|
| P B&P ALEX LABOUR | R&R RIM & BALANCE | 1 | UNIT | | 50.00 |
| P B&P ALEX LABOUR | LABOUR | 8 | UNIT | | 6,720.00 |
| P B&P ALEX LABOUR | TRANSFER DOOR MECHANISM | 2 | UNIT | | 1,680.00 |
| P B&P ALEX PAINT | SPRAY PAINT | 8 | UNIT | | 6,400.00 |
| P B&P TYRE SALES | TYRE | 2 | Pieces | | 1,360.00 |
| | PURCHASE OF TIRE | | | | |
| P B&P WHEEL ALIGNMENT | B&P WHEEL ALIGNMENT -NETT | 1 | | | 360.00 |
| P B&P DIAG | PROGRAMMING & CALIBRATION | 1 | Time Un | | 480.00 |
| | COMPULSORY TO DO AFTER AC | | | | |
| P B&P MECH | CHECK WIRE HARNESS, ECU, S | 1 | Time Un | | 280.00 |
| | Nett | | | | |
| | Sum Labor | | | | 17,330.00 |
| P 5G0805912J | WHEEL HOUS RH | 1 | Pieces | | 43.25 |
| | Use Predecessor 5G0805912H | | | | |
| P 5G0805970G | FENDER LINER UPPER RH | 1 | Pieces | | 124.48 |
| P 5G0807050A | FRT BUMPER BRACKET RH | 1 | Pieces | | 22.15 |
| P 5G0807217BPGRU | FRT BUMPER COVER | 1 | Pieces | | 1,041.58 |
| P 5G0807724D | FRT BUMPER SUPP.PART RH | 1 | Pieces | | 58.69 |
| P 5G0810972D | WHEEL HOUS RHR | 1 | Pieces | | 203.46 |
| | Predecessor 5G0810972C | | | | |
| P 5G0821106A | FENDER RHF | 1 | Pieces | | 626.54 |
| | Use Predecessor 5G0821106 | | | | |
| P 5G0919491 | REAR SENSOR BRACKET | 1 | Pieces | | 15.49 |
| P 5G0919491 | REAR SENSOR BRACKET | 1 | Pieces | | 15.49 |
| P 5G0919491A | REAR SENSOR BRACKET | 1 | Pieces | | 15.49 |
| | Sum carried forward | | | | 19,496.62 |

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

BALAKRISHNAN JAYAPRAKASH
 53 LIMAU GARDEN
 Singapore, 467912
 Singapore

Phone No.
 Fax No.
 E-Mail

VAT Registration No. M20098505-2
 Tax No. 199101494Z

Service Quote

Customer No. CV033655
 Quote No. SER/QUO/1801777
 QuoteDate 24/10/18
 Salesperson Anthony Yong
 Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| | | | |
|--------------------|-----------------------------|-----------------------------|------------------------|
| Make | Model Description | Mileage | Service Advisor |
| Volkswagen Passeng | GOLF A7 1.4 CL 92 (DSG) EQP | 63,274 | Kong Charmaine |
| License No. | VIN | Initial Registration | Sales Advisor |
| SLC3542A | WVWZZZAUZGW078408 | 11/05/16 | Anthony Yong |
| Engine Code | Labor Type | Engine No. | Model Code |
| | 1T | CZC 063815 | 5G13HZ |

Continued 19,496.62

| | | | |
|------------------|-----------------------------|----------|----------|
| P 5G0919492A | REAR SENSOR BRACKET | 1 Pieces | 15.49 |
| P 5G0919493 | SENSOR Bracket FRT | 1 Pieces | 15.49 |
| P 5G0919493A | SENSOR Bracket FRT | 2 Pieces | 30.98 |
| P 5G0919494 | SENSOR Bracket FRT | 1 Pieces | 15.49 |
| P 5G0998399 GRU | SENSOR Bracket FRT | 1 Pieces | 27.89 |
| P 5G0998492 GRU | REAR SENSOR Bracket | 1 Pieces | 27.89 |
| P 5G4831056AQ | DOOR RHF | 1 Pieces | 1,942.49 |
| P 5G4833056AB | DOOR RHR | 1 Pieces | 1,650.63 |
| | Use Predecessor 5G4833056AA | | |
| P 5G4837652B | DOOR SEAL RHF | 1 Pieces | 109.43 |
| | Use Predecessor 5G4837652A | | |
| P 5G6807394 | REAR BUMPER BRACKET RH | 1 Pieces | 39.97 |
| P 5G6807394A | REAR BUMPER GUIDE RH | 1 Pieces | 39.97 |
| P 5G6807417APGRU | REAR BUMPER COVER | 1 Pieces | 996.45 |
| | Predecessor 5G6807417ARGRU | | |
| P 5G6839700D | DOOR SEAL RHR | 1 Pieces | 109.43 |
| | Use Predecessor 5G6839700C | | |
| P D 180KU2A1 | 2KADHESIVE | 1 Pieces | 89.84 |
| P D 378500A2 | DOOR INSULATOR RHF | 1 Pieces | 46.22 |
| P D 378500A2 | DOOR INSULATOR RHR | 1 Pieces | 46.22 |
| P D 822150A1 | BONDAGENT | 1 Pieces | 64.27 |

Sum carried forward 24,764.77

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

BALAKRISHNAN JAYAPRAKASH
53 LIMAU GARDEN
Singapore, 467912
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV033655
Quote No. SER/QUO/1801777
QuoteDate 24/10/18
Salesperson Anthony Yong
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng
Model Description GOLF A7 1.4 CL 92 (DSG) EQP
License No. SLC3542A
Engine Code VIN WVVZZZAUZGW078408
Labor Type 1T

Mileage 63,274
Initial Registration 11/05/16
Engine No. CZC 063815

Service Advisor Kong Charmaine
Sales Advisor Anthony Yong
Model Code 5G13HZ

Continued 24,764.77

Sum Item 7,434.77

Sum Labor 17,330.00

Sum Item 7,434.77

Total SGD 24,764.77

7% GST 24,764.77 1,733.53

Total SGD Incl. GST 26,498.30

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No..: