FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1/5 #22.000 25/10/16 1824.

	VEHICLE NO: SLD 30	036P	5
	QTY	PARTICULAR On .	_*
	1 PCS	BONNET & & .00	Buc \$915.00
	2 PCS	BONNET HINGES @\$78.10	1 \$170.00 X
	1 PCS	BONNET INSULATOR	Turn \$211.30
	1 SET	BONNET INSULATOR CLIPS	un \$35.00
	1 PCS	BONNET LOCK	Lw1 \$135.50
	2 PCS	BONNET RUBBERS @\$32.00	M \$64.00
	1 PCS	FRONT BUMPER Po/- 75	ひょ」 \$950.00 /
	1 PCS	FRONT BUMPER REINFORCEMENT 321.00	DIS \$480.00
	2 PCS	FRONT BUMPER SIDE RETAINERS@ \$65.00	34 \$130.00
	2 PCS	FRONT BUMPER BRACKETS @\$115.00	NSBU \$230.00 ipc
	1 PCS	FRONT BUMPER CENTRE GRILLE /62.3.	Yorn \$285.00
	1 PCS	FRONT BUMPER LOWER SPOILER 39/. 10	7 \$ \$525.00
	1 PCS	FRONT BUMPER UNDER COVER	11 \$480.00 X
	1 SET	FRONT BUMPER UNDER COVER CLIPS	11 \$35.00 ×
	1 PCS	FRONT BUMPER TOW COVER	12 \$45.00 X
	2 PCS	FRONT BUMPER FOG LAMP COVERS @\$180.00 65.00	MSTW1 \$360.00 17C
	2 PCS	FRONT BUMPER FOG LAMPS @\$445.00 327.00	Mscru \$890.00 pc
	1 SET	FRONT BUMPER CLIPS	w \$40.00
	1 PCS	FRONT GRILLE 291.30	Cm \$525.00 —
	1 PCS	FRONT GRILLE OUTER GARNISH 3 85.02	CN \$548.00
	1 PCS	FRONT GRILLE 'H' LOGO	\$38.80
	2 PCS	HEADLAMPS @\$2250 / 759.10 x 2 = 1518-20	(M \$4,500.00)
	2 PCS	HEADLAMP LOWER BRACKETS @\$85.00	\$170.00
	1 PCS	FRONT SUPPORT PANEL \$76.20	3ul \$745.11
	1 PCS	FRONT SUPPORT PANEL TOP GARNISH	1 1 \$322.30 X
	1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	\$50.00 \$
	2 PCS	FRONT FENDERS @\$688.00	\$1,376.00 X
	2 PCS	FRONT FENDER INNERSHIELDS @\$166.50	AM \$333.00 X
	2 PCS	FRONT FENDER OUTER PROTECTORS @\$295.00	\$590.00
	1 PCS	AIR CON CONDENSER #10.00	suffer \$1,568.00 -
	2 PCS	AIR CON CONDENSER SIDE GARNISH @\$148.00	MS70m \$296.00 LPC
	1 PCS	RADIATOR 1649-40	Sut/201 \$1,817.50
	1 PCS	RADIATOR FAN COWLING	17 \$288.30 X
8	1 PCS	RADIATOR FAN MOTOR	11 \$488.20
	1 PCS	RADIATOR FAN BLADE	17 \$101.50×
	1 PCS	FRONT FENDER INNER PANEL N/S	% \$525.30
	1 PCS	FRONT WHEEL HOUSING PANEL N/S	1 \$988.20 2
	1 PCS	FRONT LOCK CENTRE BRACKET	CM \$115.00
	1 PCS	AIR DUCT	1 ∕ \$215.00 √
		20%	-

1 PCS	AIR CLEANER BOX	11	\$788.00
1 PCS	FRONT WIPER PANEL GARNISH	11	\$344.20 X
1 PCS	RESONATOR BOX	11	\$385.20 🗶
2 PCS	FRONT GRILLE CHROME MOULDING @\$98.50	sca	\$197.00
1 PCS	BATTERY TRAY	11	\$180.20 X
1 PCS	WASHER TANK	11	\$305.20 A
1 PCS	FRONT WINDSCREEN	112:	\$1,488.20 X
1 PCS	 TAILGATE 95-3.00	rely m	\$1,100.90
1 PCS	TAILGATE 'H' LOGO	- ru	\$35.80
1 PCS	TAILGATE 'VEZEL' EMBLEM	ner	\$56.20
1 PCS	TAILGATE OUTER HANDLE GARNISH	sellon	\$399.20
2 PCS	TAILGATE REFLECTORS @\$460.50 2 fox ところっ	310	\$921.00
1 PCS	TAILGATE INNER LOCK	lui	\$198.50
1 PCS	TAILGATE INNER TRIM BOARD	1). {	\$321.70
1 SET	TAILGATE INNER TRIM BOARD CLIPS	ser	\$45.00
2 PCS	TAILGATE DAMPERS @\$299.10	NISTMI	\$598.20
1 PCS	TAILGATE WEATHERSTRIP	dui	\$135.70
1 PCS	TAILGATE REAR WIPER ARM	11	\$188.20 X
1 PCS	TAILGATE REAR WIPER MOTOR	Jm	\$695.00
1 PCS	TAILGATE KEYLESS SENSOR	cry	\$180.00
1 PCS	REAR WINDSCREEN /266./0	Shoffed	\$1,566.20
1 PCS	REAR WINDSCREEN MOULDING	ner	\$181.00
1 PCS	TAILGATE TOP SPOILER	cru	\$950.00
1 PCS	REAR BUMPER	りり	\$762.70
2 PCS	REAR BUMPER SIDES @\$285.10	NIST.S	\$570.20 PC
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20	311	\$70.40
2 PCS	REAR BUMPER REFLECTORS @\$85.00	Mscru	\$170.00 (20
1 PCS	REAR BUMPER DIFFUSER	17.5	\$348.20
1 SET	REAR BUMPER DIFFUSER CLIPS	ne	\$50.00
2 PCS	REAR BUMPER MUDFLAPS @\$145.00	Mc Ton	\$290.00 12
2 PCS	TAILLAMPS @\$485.20	510	\$970.40
2 PCS	TAILGATE HOUSING PANELS @\$195.00	NIM	\$390.00 12
1 PCS	REAR END PANEL	3000	\$514.00
1 PCS	REAR END PANEL TOP GARNISH	Tul	\$184.00
1 PCS	REAR FLOOR PANEL	emyled (sec	\$912.00
1 PCS	REAR FLOOR PANEL TOP BOARD	Tom	\$499.20
1 PCS	REAR FLOOR PANEL TOOLS SPONGE	TOIN	\$685.00
1 PCS	REAR FLOOR PANEL SIDE PANEL N/S 291-10	Kehin	\$399.20
1 PCS	REAR FLOOR PANEL SIDE TOP PANEL N/S /99. 20	4. 5500	\$299.20
2 PCS	REAR FENDERS @\$885.10	Missin oka	\$1,770.20 0
2 PCS	REAR FENDER OUTER PROTECTORS @\$264.00 /4: 642;		\$528.00
2 PCS	REAR FENDER INNER TRIM BOARD @\$645.30 295-30x2	,	\$1,290.60
1 PCS	REAR EXHAUST		\$899.20 X
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00	11	\$90.00 X
2 PCS	REAR SHOCK ABSORBERS @\$305.00	17	\$610.00 0
2 PCS	REAR WHEELHUB BEARINGS @\$450.00	11	\$900.00
1 PCS	REAR AXLE ARM		\$1,885.00 ×
1 PCS	REAR EXHAUST HEAT SHIELD	11	\$199.00
1703	MEAN EXHAUST HEAT OFFICED	71 -	,

		•
1 PCS	REAR WHEEL HOUSING PANELS N/S	1,150.00 X 1,150.00 X
.1 PCS	REAR END LOCK SENSOR	Cm \$288.50
1 PCS	REAR FENDER UNDER TRIM N/S	1011 \$299.30
1 PCS	REAR CHASSIS MEMBER N/S	1 \$699.20 X
2 PCS	REAR DOOR @\$998.20	\$1,996.40 X
		\$52,562.51
	S.NETT	
1 PCS	REAR WINDSCREEN SEALANT	ner \$50.00 40
1 PCS	REAR WINDSCREEN SOLAR FILM	nu \$250.00/80
1 PCS	REAR WINDSCREEN INNER SEAL	ney \$50.00 40
1 SET	REAR REVERSE CARMERA	should \$380.00 300
1 PCS	REAR LICENCE PLATE W/HOLDER	Serf \$50.00 40
1 PCS	REAR END PANEL SEALANT	\$50.00
1 SET	REAR FLOOR PANEL INSULATOR	11 \$200.00 X 11 \$50.00 X
1 PCS	FRONT LICENCE PLATE W/HOLDER	
1 PCS	BATTERY	
1 BOT	RADIATOR COOLANT	\$50.00
		700
	LABOUR CHRAGES:	* * *
	TOWING CHARGE	\$150.00 500
	TO CHECK WIRING	\$100.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$100.00 分
	TO TRANSFER TAILGATE MECHANISM	\$100.00 60
	TO DISMANTLE & REPLACING REAR WINDSCREEN	\$150.00 / 20
1841 2	TO DISMANTLE & REFIX REAR EXHAUST	\$100.00 60
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00 fo
	TO DISMANTLE & REFIX PETROL TANK	\$100.00 6,7
	TO DISMANTLE & REFIX PETROE TAIN. TO DISMANTLE & REFIX REAR UNDERCARRIAGE	11 \$380.00 X
		\$200.00 (5-0
	TO SPRAY RUSE PROOFING	\$150.00 /0.2
	TO REFILL AIR CON GAS	1380.00 × 1380.00 ×
	TO MOUNT VEHICLE ON CAR O-LINER	\$100.00 60
	TO CONDUCT WHEEL ALIGNEMENT	
	TO DISMANTLE & REFIX FRONT WINDSCREEN	\$150.00 ×
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN	\$4,500.00 2800
	& REPLACING PARTS	1000
	TO PUTTY & SPRAY PAINTING	\$3,800.00 1800
		TOTAL \$64,522.51
		Fin