

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Monday, 17 December 2018 7:50 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 77431, vehicle number SLN1976L

Re:<MANDATE IA> - S8M0109V [ACCIDENT INVOLVING SLX 6687K(OI) / SLN 1976L (TP) / OTHERS ON 23/10/2018]

Type

Question

Message

Hi LKK, pls propose global sum between \$19,000 to \$19,500. TY.

Reply

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Monday, 17 December 2018 12:27 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 77431, vehicle number SLN1976L

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: richard.angbs@axa.com.sg [mailto:richard.angbs@axa.com.sg]
Sent: Monday, 17 December 2018 12:26 PM
To: admin-d@lkkauto.com
Subject: New message for service request 77431, vehicle number SLN1976L

AXA Insurance has sent you a message for claim number S8M0109V.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Hsiao Tong (LKKAuto)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Sunday, 31 March 2019 12:26 PM
To: Hsiao Tong (LKKAuto)
Subject: APPEAL (1) - Our Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Hi Hsiao Tong.

Our propose repair cost (\$19260.00) and LOU (\$1440.00) on our LOD is reasonable.

Pls reconsider to settle accordingly.
Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Hsiao Tong (LKKAuto)
Sent: Sunday, March 31, 2019 11:41 AM
To: <mailto:chmotor@singnet.com.sg>
Subject: Your Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Your Ref: **SLN1976L** **Without Prejudice**
Our Ref: CC4/ASM18019422/Kpb3

ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$19,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Sunday, 31 March 2019 11:42 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg)
Subject: Your Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Your Ref: **SLN1976L**

Without Prejudice

Our Ref: CC4/ASM18019422/Kpb3

ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$19,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 **RE: Re:<MANDATE IA> - S8M0109V [ACCIDENT INVOLVING SLX 6687K(OI) / SLN 1976L (TP) / OTHERS ON 23/10/2018]**

Type

 Question

Message

Hi, Third party rejected our offer at \$19,500.00(all-in) and proposed g/s \$20,500.00(all-in). The breakdown of third party propose is as follows: - 1)Cost of Repair (w/GST):\$19,260.00 + 2.)Loss of Use (24days x \$60.00): \$1,440.00 + 3). LTA/GIA Search Fee: \$8.00. * For the number of repair days, surveyor recommended 20days. Kindly let us have your further mandate / instruction please. Hsiao Tong - 12 Oct 2019

[Reply](#)

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 14 October 2019 8:57 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 77431, vehicle number SLN1976L

14/10/19 8:39 AM *** Messagehi, our final revised on the offer at \$20,000 (all-in). please propose the offer. thanks. - TAN Jas

-----Original Message-----

From: jas.tan@axa.com.sg <jas.tan@axa.com.sg>
Sent: Monday, 14 October, 2019 8:40 AM
To: admin-d@lkkauto.com
Subject: New message for service request 77431, vehicle number SLN1976L

AXA Insurance has sent you a message for claim number S8M0109V.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Sunday, 24 November 2019 3:22 PM
To: Hsiao Tong (LKKAuto)
Subject: DV- Our Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Hi Hsiao Tong,

We confirm the revised offer sum S\$20000.00.

Pls forward DV.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: [Hsiao Tong \(LKKAuto\)](#)
Sent: Monday, October 14, 2019 10:42 AM
To: [Cheng Hoe Motor Pte Ltd \(Yishun-June\)](#)
Subject: RE: APPEAL (2) - Our Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to your below email.

We have our principal instruction to improve our offer at a global sum of \$20,000.00(all-in) as full and final.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>

Sent: Saturday, 21 September 2019 5:50 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: APPEAL (2) - Our Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Hi Hsiao Tong,

Your revised offer of S\$19,500.00 is rejected.

|

Counter propose all in S\$20,500.00.

Thank you.

Rgds

June Phua

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

From: [Hsiao Tong \(LKKAuto\)](mailto:Hsiao Tong (LKKAuto))

Sent: Saturday, June 22, 2019 11:48 AM

To: [Cheng Hoe Motor Pte Ltd \(Yishun-June\)](mailto:Cheng Hoe Motor Pte Ltd (Yishun-June))

Subject: RE: APPEAL (1) - Our Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to your below email.

We have our principal instruction to improve our offer at a global sum of **\$19,500.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>

Sent: Sunday, 31 March 2019 12:26 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: APPEAL (1) - Our Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Hi Hsiao Tong.

Our propose repair cost (\$19260.00) and LOU (\$1440.00) on our LOD is reasonable.

Pls reconsider to settle accordingly.

Thank you.

Rgds

June Phua

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

From: [Hsiao Tong \(LKKAuto\)](mailto:Hsiao Tong (LKKAuto))

Sent: Sunday, March 31, 2019 11:41 AM

To: <mailto:chmotor@singnet.com.sg>

Subject: Your Ref: SLN1976L *Our Ref: CC4/ASM18019422/Kpb3 [ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018]

Your Ref: **SLN1976L**

Without Prejudice

Our Ref: CC4/ASM18019422/Kpb3

ACCIDENT INVOLVING SLX 6687K(AXA)/ SLN 1976L/ OTHERS ON 23/10/2018

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$19,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 20 FEB 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SLN1976L & SLX6687K ON 23/10/2018
TPE TWDS SLE AFTER PUNGGOL RD.**

We are authorized by SLN1976L for their above matter.

Record reveals that you are the insurer of SLX6687K. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 19260.00
2. Loss of Use (S\$60.00 /- x 24 days)	S\$ 1440.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 20708.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Cheng Hoe Motor Pte Ltd

Bk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department
WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 23/10/2018
TP Veh Reg No: SLX6687K

NO: **CL8190030**
Date: 23 Jan 2019
Policy No: MT101628
Veh Reg No: **SLN1976L**
Make/Model: KIA FORTE K3 1.6A
Job No: JC1599037

Description	Quantity	List Price	PAGE:1 Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	<u>SS</u> SS 18,000.00	<u>SS</u> SS 18,000.00

Total SS 18,000.00
Add GST @ 7% 1,260.00
Total Amount payable SS 19,260.00

For Cheng Hoe Motor Pte Ltd

E. & O. E.


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18019422/Kpb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: RICHARD ANG

Date : 09-12-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 6687K	Veh. Inspected	SLN 1976L
Policy No.	VPAP2120779	Coverage (\$)	0.00
Claim No.	S8M0109V	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	25/10/2018

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MH5714264	Colour	METALLIC DARK BLUE
Odometer	55031	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	7 mm
L/H Front Tyre	195/65 R15	NEXEN	7 mm
R/H Rear Tyre	195/65 R15	NEXEN	7 mm
L/H Rear Tyre	195/65 R15	NEXEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/10/2018	Inspection Date	25/10/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **21 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 1976L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N) (CONSISTENT)	BENT / CRACKED	688.00	688.00
1	REAR BUMPER LOWER SKIRT (N) (CONSISTENT)	BENT	344.00	344.00
1	REAR BUMPER REINFORCEMENT (N) (CONSISTENT)	BENT	313.00	313.00
2	REAR BUMPER REFLECTORS @ \$65.00 (N) (CONSISTENT)	CRACKED	130.00	130.00
6	REAR BUMPER CLIPS @ \$3.50 (N) (CONSISTENT)	NECESSARY	21.00	21.00
1	REAR PANEL (N) (CONSISTENT)	BENT	315.00	315.00
1	REAR PANEL INNER TOP GARNISH (N) (CONSISTENT)	DENTED	58.00	58.00
1	REAR BOOT (N) (CONSISTENT)	BENT	1,297.00	1,297.00
1	REAR BOOT LOGO (N) (CONSISTENT)	NECESSARY	42.00	42.00
1	REAR BOOT EMBLEM (CERATO K3) (N) (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR BOOT INNER LOCK (N) (CONSISTENT)	TO REPAIR SEE LABOUR	110.00	-
1	REAR BOOT INNER RUBBER (N) (CONSISTENT)	SERVICEABLE	98.00	-
1	REAR SPARE TYRE COMPARTMENT (N) (CONSISTENT)	BENT / BUCKLED	372.00	372.00
1	REAR SPARE TYRE HOLDER (N) (CONSISTENT)	MISSING	18.00	18.00
1	REAR EXHAUST PIPE (N) (CONSISTENT)	BENT	480.00	480.00
1	FRONT BUMPER (N) (CONSISTENT)	CRACKED	735.00	735.00
1	FRONT BUMPER REINFORCEMENT (N) (CONSISTENT)	BENT	496.00	496.00
1	FRONT BUMPER SPONGE (N) (CONSISTENT)	CRACKED	85.00	85.00
1	FRONT BUMPER RH SIDE RETAINER (N) (CONSISTENT)	DISTORTED	16.00	16.00
6	FRONT BUMPER CLIPS @ \$3.50 (N) (CONSISTENT)	NECESSARY	21.00	21.00
1	FRONT GRILLE (N) (CONSISTENT)	MISSING	221.00	221.00
1	FRONT GRILLE LOGO BUMPER LOGO (N) (CONSISTENT)	MISSING	35.00	35.00
4	FRONT GRILLE CLIPS @ \$3.50 (N) (CONSISTENT)	NECESSARY	14.00	14.00
2	HEADLAMPS @ \$810.00 (N) (CONSISTENT)	O/S BROKEN / N/S MTG CRACKED	1,620.00	1,620.00
1	BONNET (N) (CONSISTENT)	BENT	835.00	835.00
1	BONNET INNER LOCK (N) (CONSISTENT)	BENT	65.00	65.00
1	BONNET INNER LOCK CABLE (N) (CONSISTENT)	JAMMED	68.00	68.00
2	BONNET HINGES @ \$42.00 (N) (CONSISTENT)	BENT	84.00	84.00
1	FRONT RH FENDER (N) (CONSISTENT)	BENT	325.00	325.00

Report Ref No. CC4/ASM18019422/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH FENDER TRIANGLE GLASS (N) (CONSISTENT)	CRACKED	233.00	233.00
1	FRONT RH DOOR (N) (CONSISTENT)	BENT	893.00	893.00
1	FRONT RH DOOR SIDE MIRROR (N) (CONSISTENT)	CRACKED	511.00	511.00
1	SET FRONT RH DOOR FRAME STICKER (N) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT WINDSCREEN GLASS (N) (CONSISTENT)	CRACKED	821.00	821.00
1	FRONT WINDSCREEN GLASS MOULDING (N) (CONSISTENT)	NECESSARY	60.00	60.00
2	FRONT WIPER ARMS @ \$108.00 (N) (CONSISTENT)	DENTED	216.00	216.00
2	FRONT WIPER BLADES @ \$75.00 (N) (CONSISTENT)	CUT	150.00	150.00
1	FRONT WIPER GARNISH (CENTRE) (N) (CONSISTENT)	CRACKED	80.00	80.00
2	FRONT WIPER GARNISHS (SIDES) @ \$25.00 (N) (CONSISTENT)	CRACKED	50.00	50.00
2	FRONT WIPER NOZZLES @ \$22.00 (N) (CONSISTENT)	NECESSARY	44.00	44.00
2	TOP ROOF RUBBERS @ \$48.00 (N) (CONSISTENT)	NECESSARY	96.00	96.00
1	AIR-CON CONDENSER (N) (CONSISTENT)	BENT / PUNCTURE	687.00	687.00
1	RADIATOR (N) (CONSISTENT)	BENT	493.00	493.00
1	RADIATOR FAN ASSY (N) (CONSISTENT)	CRACKED	567.00	567.00
1	AIR-CON GAS DISCHARGE HOSE (N) (CONSISTENT)	DENTED	617.00	617.00
1	AIR-FILTER DUCTING (N) (CONSISTENT)	CRACKED	94.00	94.00
1	AIR FILTER HOUSING (N) (CONSISTENT)	CRACKED	140.00	140.00
1	RADIATOR EXT PIPE (N) (CONSISTENT)	CUT	48.00	48.00
1	VACUUM PUMP (N) (CONSISTENT)	CRACKED	149.00	149.00
1	INLET MANIFOLD (N) (CONSISTENT)	CRACKED	906.00	906.00
1	FRT SUPPORT PANEL (N) (CONSISTENT)	BROKEN	662.00	662.00
2	AIRCON CONDENSER SIDE GARNISHS @ \$28.00 (N) (CONSISTENT)	CRACKED	56.00	56.00
1	DASHBOARD (N) (CONSISTENT) (ADDITIONAL)	DENTED / CUT	1,903.00	1,903.00
1	LH TAILLAMP (N) (CONSISTENT) (ADDITIONAL)	CRACKED	354.00	354.00
1	ENGINE OIL STICK (N) (CONSISTENT) (ADDITIONAL)	CRACKED	30.00	30.00
1	ENGINE OIL HOUSING (N) (CONSISTENT) (ADDITIONAL)	DENTED	70.00	70.00
5	REAR BUMPER REINFORCEMENT RETAINERS @ \$7.00 (N) (CONSISTENT) (ADDITIONAL)	NECESSARY	35.00	35.00
2	FRONT BUMPER FOG LAMP GARNISHS @ \$49.00 (N) (CONSISTENT) (ADDITIONAL)	DENTED	98.00	98.00

Report Ref No. CC4/ASM18019422/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR TOP HOSE (N) (CONSISTENT) (ADDITIONAL)	CUT	29.00	29.00
1	EXHAUST HEAT SEAL (N) (CONSISTENT) (ADDITIONAL)	BENT	109.00	109.00
1	REAR BUMPER RH LOWER COVER (N) (CONSISTENT) (ADDITIONAL)	DISTORTED	42.00	42.00
	LESS 10% DISCOUNT		-1,924.90	-1,904.10
			17,324.10	17,136.90
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CRACKED	35.00	35.00
1	REVERSE SENSOR (SN) (CONSISTENT)	CRACKED	200.00	200.00
1	FRONT WINDSCREEN GLASS GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	ERP BRACKET (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	UNIT COOLANT (2 LTRS) (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT CHASSIS PLATE (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	80.00	80.00
1	REAR SPARE TYRE PANEL TOP COAT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	150.00	80.00
			565.00	495.00
	LABOUR			
	TOWING.		50.00	50.00
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.		100.00	100.00
	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS.		100.00	100.00
	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, GRILLE, BONNET & ATTACHMENT, RADIATOR, FRT FENDERS, MOTOR, TO CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT LH FENDER, TOP ROOF PANEL, FRT FENDER INNER PANEL, PILLARS & REALIGN THE SAME.		1,200.00	1,000.00
	REMOVE & REFIX VACUUM PUMP, INLET MANIFOLD & CHECK ENGINE.		100.00	100.00
	PUTTY & RESPRAY ON TOP ROOF PANEL, FRT RH DOOR, FRT FENDER, FRT BUMPER, SUPPORT PANEL, FRT FENDER INNER PANELS, BONNET & ALL AFFECTED AREAS.		1,300.00	1,200.00
	REMOVE & REFIX DASHBOARD, METER ASSY & CHECK WIRING.		250.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET & WASH CUSHION.		120.00	120.00
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR PANEL, REAR SPARE TYRE COMPARTMENT, KNOCK & REPAIR REAR FENDERS, REAR CHASSIS & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BOOT INNER LOCK.		1,500.00	1,400.00
	PUTTY & RESPRAY REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR CHASSIS, REAR PANEL, BUMPER, BOOT.		1,300.00	1,200.00
	REMOVE & REFIX REAR UNDER CARRIAGE, REAR EXHAUST.		250.00	220.00
	TO MOUNT ON CAR-O-LINER & REALIGN REAR CHASSIS.		250.00	250.00
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		60.00	60.00
	RUSTPROOFING.		120.00	120.00
			6,700.00	6,170.00
	GRAND TOTAL		24,589.10	23,801.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,000.00

Report Ref No. CC4/ASM18019422/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.