

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 12 Nov 2018

Preliminary Advice

Vehicle No	: SLX9643S	Accident Date	: 22/10/2018
Make	: AUDI A3	Policy No.	: 1800035271
Assignment Date	: 25/10/2018	Excess	: S\$300.00
Date of Inspection	: 25/10/2018	Est. Duration of Repair	: 13 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: \$	77,187.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	: \$	52,903.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	: \$	6,445.00
Total	: \$	59,348.00
Lump Sum Repair		: \$

Total Loss Consideration

New for Old Value	: \$	
Pre-Accident Value	: \$	122,000.00
COE / PARF Rebate	: \$	49,547.00
Salvage Value	: \$	
Margin for Repair	: \$	72,453.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 302.00.