COMFORTDELGRO ENGINEERING PTE LTD

EPAIR ESTIMATE* CHICLE NO: SHA 1258S AKE:		DATE	22/10/2018 14:30		mWa
		/	merco		
DEL	: HYUNDAI i40		100		
Qty	Parts Description/ Labour	Type	Unit Price	=	mount
	E Wheel Hub Cap, RH			\$	107.10
	Ker				
	SUB TOTAL Rear Funger X (Pa) X Pan DISCOUNTED TOTAL Rear Funder (Ru) X Pan DISCOUNTED TOTAL			\$	107.10
	Pear Proper X1401 LESS 20%			\$	21.42
	par Fonder (RM) × Mon DISCOUNTED TOTAL	1		\$	85.68
	Labour Charge				300
	Panel Beating-Repair Fender			\$	400.00
	Spray Painting Charge-Fender/Bumper			\$	600.00
	Wiring			\$	50.00
	Rear Wheel Alignment			\$	80.00
	TOTAL LABOUR			\$	1,130.00
	ESTIMATE TOTAL			\$	1,215.68
	Kalini I Clery 23/10/18 1110hs 2 Pags				
	1 23/10/18 1110hs				
	2 Pags				
	Hs After Ryan pld	me Repaire	onsultants hence notify of the following:		7
	Affe Report prom	 To display da Parts prices a Third party su No illegal mod 	efore/after spray painting maged part(s) during resurvey re subject to confirmation way is on a "Without Prejudice" (Cation by is allowed)		
		15 540[01] 0 18	y and must be resurveyed as a approval from Insurance Cor	ne pany	
		Acknowledged : Signature: Date:	y reparet		

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.