

15/9/2019

INS. CASE OWNER:

Gerald.

CC 4 / LPC1801

9467, T1P6352

LKK:

IDAC:

Surveyor:

Tan Fitch

DOI:

ASSIGNMENT

19/11/18

Date / Time:

16/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PA 76937

Name of Insured:

ROCKY ENGINEERING PH

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

24/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: JAMIL BIN MUSA

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

4/18/18/1670/00055

Policy No.:

Make / Model:

TOYOTA

Place of Accident:

JLN BOON HAY

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SME 4866L

INSRS:
WSP:
Tel:
Liability:
RMKS:

Kah Motor

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
30/10/18	SME 4866L - 4	Non-Reporting ltr (1st):	
30/10/18	PA 76937	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
24/12/18	File pass to type mandate	Documentation Check List: Handler	Typist
9/1/19	File pass to sm per to close	Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	27	1) NO or B 28, Ass. Lia:
Repair Cost:	SS 8180.29			
Loss of Rental (LOR):	SS 480.00	(S 60 x 8 days)		
Loss of Use (LOU):	SS	(S x days)		
Loss of Income (LOI):	SS	(S x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>		[Tick only one]		
GIA/LTA Search	SS			
Medical:	SS			
Disbursement:	SS	(e.g. Tow/ Independent)		
Legal Cost	SS			
Total:	SS 8660.29	Global Sum SS:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 8660.29	Name 1:	Kah Motor Co sdn Bhd	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 21
3) Survey fee: \$4900

Tammy

REF:

LPC

p

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7. days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Juh

Veh No:

SM E 4866L

Yr Regn:

2018 oct

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hand Give 1.6 VT1

c.c. 1597

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

001269

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR HFC 5650JT 00643

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F: 215 / 35 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Handwork

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

19/11/18

Survey held at

Hand Motor Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PIP \$ 2645.14 (Red \$ 5415.59 / 41%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. S + PS. \$

2. Photos

3. Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18019467/pb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 26-10-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PA 7693J	Veh. Inspected	SME 4866L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/10/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18019467/T1pb3

Date: 21.11.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SME4866L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.11.2018 at the premises of M/s Kah Motor Co Sdn Bhd and have the following to report:-

Workshop Estimate Amount	: S\$	12,910.67
Revised Estimate Amount	: S\$	7,284.29
"Check" Items Amount	: S\$	528.61
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6-7 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

Registration No : SME4866L

Chassis No : MRHFC5650JT001643

Model : CIVIC 1.6 VTI YM2018

Owner's Name : HAO YANLIANG

Ins Policy No. :

Date of Accident : 24/10/2018

Document No. : SQT18004566 Page 1

Date : 24. Oct 2018

Customer No. : WZL009

Svc Advisor :

Engine No : R16B25501907

Date | Time : 24. Oct 2018 6:02:41 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:HAO YANLIANG						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:24/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:LONPAC INSURANCE						
	TP VEH:PO7693 J						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
33505-TEA-T01	REFLECTOR ASSY,RR.	1	7.00	25	5.25	0.37	5.62
33555-TEA-T01	REFLECTOR ASSYL,RR.	1	7.00	25	5.25	0.37	5.62
71503-TEA-T00	GARNISHR,RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10
71508-TEA-T00	GARNISHL,RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.00	25	10.50	0.74	11.24
75722-TBA-A00	EMBLEM SETRR.	1	11.50	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR.	1	10.60	25	7.95	0.56	8.51
75701-TBA-A10	EMBLEM,H-MARK	1	11.90	25	8.92	0.62	9.54
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	97.70	25	73.27	5.13	78.40
NMRS-4P	4 PCS REAR SENSOR	1	149.20	10	134.28	9.40	143.68
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR.	1	41.20	25	30.90	2.16	33.06
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	210.40	25	157.80	11.05	168.85
66100-TEC-307ZZ	PANEL SETRR. - photo	1	236.00	25	177.00	12.39	189.39
Sum Item					1590.67	111.35	1,702.02

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

Registration No : SME4866L
Chassis No : MRHFC5650JT001643
Model : CIVIC 1.6 VTI YM2018
Owner's Name : HAO YANLIANG
Ins Policy No. :
Date of Accident : 24/10/2018

Document No. : SQT18004566
Date : 24. Oct 2018
Customer No. : WZL009
Svc Advisor :
Engine No : R16B25501907
Date | Time : 24. Oct 2018 6:02:41 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30% net	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	100.00	X m	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	✓	280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00	✓ 282	280.00	19.60	299.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA(N)	1	380.00	✓	380.00	26.60	406.60
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM(N)	1	380.00	✓	380.00	26.60	406.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	560	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	560	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	5000.00	2520	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	1575	3000.00	210.00	3210.00
Sum Labor					11320.00	792.40	12,112.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 12,910.67 903.75 13,814.42

Total (Inclusive of GST) 13,814.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 24/10/2018 6:17:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****6611G / HAO YANLIANG
Chassis No: MRHFC5650JT001643
License No: SME4866L
Mileage: 1268
Engine No: R16B25501907

Document No: SVO18068673
Printed By: JACKNG
Order Date: 19. November 2018
Order Time: 3:06:15 PM
Service Advisor:

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42	bt -
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	25	6.52	0.46	6.98	de -
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17	bt -
SUM PARTS:					150.06	10.51	160.57	
TOTAL SGD					150.06	10.51	160.57	
Total Payable (SGD)							160.57	

GST Amount is calculated from individual line(s)

12060.73



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZL009 / LONPAC INSURANCE
Chassis No: MRHFC5650JT001643
License No: SME4866L
Mileage: 1268
Engine No: R16B25501907

Document No: SVO18068673
Printed By: JACKNG
Order Date: 19. November 2018
Order Time: 3:06:15 PM
Service Advisor:

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:HAO YANLIANG OWNER INSURER:TOKIO MARINE ACC DATE:24/10/2018 SURVEYED BY: DATE: REF NO: TP INSURER:LONPAC INSURANCE TP VEH:PC 7693 J ADDITIONAL PART						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
75701-TBA-A10	EMBLEM,H-MARK	1	12.20	25	9.15	0.64	9.79
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66154-TBA-A00ZZ	STIFFENERL,RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
71506-TEX-Y00	COVERRR.TOWING HOOK	1	6.70	25	6.52	0.46	6.98
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
	SUM PARTS:				878.14	61.46	939.60
BOSUN	1610 SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	1610 BODY JOINT SEALANT FOR END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	1610 BODY JOINT SEALANT FOR TAILGATE	1	100.00		100.00	7.00	107.00
BML02I	0669 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	280.00		280.00	19.60	299.60
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	282.00		282.00	19.74	301.74
BOMISC1	1757 REMOVE & INSTALL REAR VIEW CAMERA(N)	1	380.00		380.00	26.60	406.60
BOMISC1	1757 RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	380.00		380.00	26.60	406.60
BMI03D	0669 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	0669 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00		560.00	39.20	599.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZL009 / LONPAC INSURANCE
Chassis No: MRHFC5650JT001643
License No: SME4866L
Mileage: 1268
Engine No: R16B25501907

Document No: SVO18068673
Printed By: JACKNG
Order Date: 19. November 2018
Order Time: 3:06:15 PM
Service Advisor:

BKRP02M	0669 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS. ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,520.00	2,520.00	176.40	2,696.40
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,575.00	1,575.00	110.25	1,685.25
			SUM LABOUR:	6,767.00	473.69	7,240.69
			TOTAL SGD	7,645.14	535.15	8,180.29
Total Payable (SGD)						8,180.29

GST Amount is calculated from individual line(s)

Hsiao Tong (LKKAuto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Thursday, 6 December 2018 7:16 PM
To: Hsiao Tong (LKKAuto)
Subject: FINALIZATION FOR SME 4866 L
Attachments: 0629_001.pdf; Resurvey B4 Paint & Item _ SME 4866 L; B4 Repair _ SME 4866 L

Importance: High

Dear Hsiao Tong,

We enclosed the total final repair costs for,

Vehicle No.	SME 4866 L
Final Repair Costs (exclude GST)	S\$7,645.14
Repair Period* (Days)	7 WORKING DAYS

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '7' items and supplementary parts (if any) for your records.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 24 October, 2018 2:46 PM
To: Jack Ng; assignments@lkkauto.com; Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J Our Ref: TBA
Attachments: GIA REPORT.PDF

Without Prejudice

Dear Jack

Please liaise with LKK Auto Consultants Pte Ltd for survey and liability.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Jack Ng [mailto:jackng@honda.com.sg]
Sent: Wednesday, 24 October, 2018 2:19 PM
To: MT_Claim_SG
Cc: CHEW BENG KEE
Subject: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J
Importance: High

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report. We propose 100% direct settlement in our client favour.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg

24.10.2018 @ 2:54pm


Jack veh not in



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

THE BIG STORY or VISA only) to pay for selected LTA eServices at One.Motoring. | eServices@ONE.MOTORING is accessible via Internet Explorer version

[Home](#) / [LTA eServices](#) / [Online Enquiries](#) / [Enquire Vocational Licence Status](#)

ENQUIRE VOCATIONAL LICENCE STATUS

[PRINT THIS ARTICLE](#)
[EMAIL THIS ARTICLE](#)

Enquiry E-Service for Vocational Licence Holders

Welcome to LTA eService for Vocational Licence Holders

This e-service allows Vocational Licence (VL) holders and other interested parties to check on the status of a VL. To use this enquiry feature, you will need to enter both the NRIC/Foreign Identification Number (FIN) and the date of birth of the VL holder.

You can enquire on the status of all types of VL, as listed below:

- Private Hire Car Driver's Vocational Licence
- Taxi Driver's Vocational Licence
- Omnibus Driver's Vocational Licence
- General Bus Driver's Vocational Licence
- Bus Attendant's Vocational Licence
- Trishaw Rider's Vocational Licence

* **NRIC No/FIN** (e.g. S1234567A, F1234567A)

* **Date of Birth** - - (Format: DD-MM-YYYY)

[PROCEED](#) [RESET](#)

Fields marked * are required.

STATUS OF VOCATIONAL LICENCE

The information contained herein is correct as at 26-Oct-2018

Name JAMIL BIN MUSA

Licence Number S1751013D

Date of Birth 25-Oct-1966

TYPE OF VOCATIONAL LICENCE

VL Type	Status	Expiry Date
General Bus Driver's Vocational Licence	Expired	18-07-2018
Bus Attendant's Vocational Licence	Expired	18-07-2018

[FAQs](#)

[BACK TO TOP](#)

I WANT TO ...


drive

buy

sell

maintain

participate



ONE.MOTORING wins Silver Award
in 2013 W³ Awards.



ONE.MOTORING is the Winner of
2 Outstanding Achievement Award
in 2013 Interactive Media Award.

Thank you for your support!

See ONE.MOTORING's other awards.

Copyright © Land Transport Authority. All Rights Reserved.

[Privacy Statement](#) | [MSI Privacy Statement](#) | [Terms & Conditions](#)

POWERED BY OPERATED BY



Hsiao Tong (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 28 November 2018 9:22 AM
To: Hsiao Tong (LKKAUTO)
Cc: MT_Claim_SG
Subject: FW: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J *LKK REF: CC4/LPC18019467/pb3

Dear Hsiao Tong,

We are agreeable to a direct settlement subject to our insured driver not breaching LTA's driving requirements for bus drivers.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, 2 November, 2018 4:38 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J *LKK REF: CC4/LPC18019467/pb3

Hi Gerald,

We refer to your below email.

Kindly advise if there is any policy issue as third party is chasing for update/outcome.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 26 October 2018 11:19 AM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J *LKK REF: CC4/LPC18019467/pb3

Dear Hsiao Tong,

We shall seek clarifications and revert to you.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Friday, 26 October, 2018 11:02 AM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG; Admin A

Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J *LKK REF: CC4/LPC18019467/pb3

Hi Mr Gerald,

As spoken earlier, we noted that the status of vocational licence for our insured driver had expired on 18/07/2018. Kindly refer to the attached for your easy reference.

Kindly advise if there is any policy issue and whether we can proceed DS.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Friday, 26 October 2018 8:59 AM

To: Shu Pei (LKKAuto) <shupe@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J Our Ref: TBA

Our Ref : 17/18/18/VC30/021055

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Friday, 26 October, 2018 8:45 AM
To: ONG LI LI; GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Hsiao Tong (LKKAuto)
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J Our Ref: TBA

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 24 October 2018 2:54 PM
To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J Our Ref: TBA

Dear Li Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Wednesday, 24 October, 2018 2:46 PM
To: Jack Ng <jackng@honda.com.sg>; assignments@lkkauto.com; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J Our Ref: TBA

Without Prejudice

Dear Jack

Please liaise with LKK Auto Consultants Pte Ltd for survey and liability.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Jack Ng [mailto:jackng@honda.com.sg]

Sent: Wednesday, 24 October, 2018 2:19 PM

To: MT_Claim_SG

Cc: CHEW BENG KEE

Subject: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Importance: High

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report. We propose 100% direct settlement in our client favour.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



BLUT ANGEFÜR
OUR CHILDREN




Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 28 November 2018 11:38 AM
To: 'Jack Ng'
Cc: bkchew@lonpac.com; Admin A
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Without Prejudice

Dear Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng <jackng@honda.com.sg>
Sent: Wednesday, 28 November 2018 11:05 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: bkchew@lonpac.com; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J
Importance: High

Dear Hsiao tong,

Any update regarding this case?

Best regards
Jack

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Thursday, November 22, 2018 3:53 PM
To: Jack Ng <jackng@honda.com.sg>
Cc: bkchew@lonpac.com; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Without Prejudice

Hi Jack,

We are pending for reply from LTA.

You may advise your client to claim OD if he need to repair his car urgently.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng <jackng@honda.com.sg>
Sent: Thursday, 22 November 2018 2:18 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: bkchew@lonpac.com; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J
Importance: High

Dear Hsiao tong,

Any update regarding this case?

Best regards
Jack

From: Jack Ng
Sent: Thursday, November 08, 2018 1:55 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: bkchew@lonpac.com; Admin A <admin-a@lkkauto.com>
Subject: Re: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Dear Hsiao tong,

Any update regarding this case?

Best regards
Jack

Get [Outlook for iOS](#)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Monday, November 5, 2018 17:48
To: Jack Ng
Cc: bkchew@lonpac.com; Admin A
Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Without Prejudice

Hi Jack,

Thank you for your email.

Please be informed that our principal is seeking clarification from our insured driver's driving license on this matter. We are unable to comment on liability at this moment.

We will get back to you once we receive instruction.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng <jackng@honda.com.sg>
Sent: Monday, 5 November 2018 4:44 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: bkchew@lonpac.com

Subject: RE: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Importance: High

Dear Hsiao Tong,

Kindly advice on this case liability status.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Jack Ng

Sent: Wednesday, October 24, 2018 2:19 PM

To: 'MT_CLAIM@LONPAC.COM' <MT_CLAIM@LONPAC.COM>

Cc: 'bkchew@lonpac.com' <bkchew@lonpac.com>

Subject: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J

Importance: High

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report. We propose 100% direct settlement in our client favour.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg




Visit our
Facebook page




Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended

recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAuto)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Thursday, 31 January 2019 2:43 PM
To: Hsiao Tong (LKKAuto)
Cc: Sum Wai Teck; Jerome Tan; Winson Chow
Subject: FW: LOD Submission of TPDS - Accident Involving SME4866L and PA7693J on 24.10.2018
Attachments: 1314_001.pdf

Your Ref: PA7693J

Our Ref: SME4866L

M/s: Lonpac Insurance Bhd
100 Beach Road #19-00
Shaw Towers
Singapore 189702
Attn: Motor Claims Department / Hsiao Tong

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards
Desmond Toh
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 2 February 2019 3:24 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: <Seek Mandate> Lonpac Ref: 17/18/18/VC30/021055 [ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J] *LKK REF: CC4/LPC18019467/T1pb3s2
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos.pdf; TP LOD-SME4866L.pdf

Lonpac Ref: **17/18/18/VC30/021055**
LKK Ref: CC4/LPC18019467/T1pb3s2

Dear Sirs/Madam,

We refer to the above matter.

We have highlighted to your good office on 24/10/2018 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

This is a head-to-rear collision. Liability is not in our driver's favour.

Summary to offer to third party repairer, "**KAH MOTOR CO SDN BHD**" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 13,985.31	\$ 8,180.29
2. Loss of Use (8days x \$60.00)	\$ 480.00	\$ 480.00(8days x \$60.00)
Total	\$ 14,465.31	\$ 8,660.29

**07days recommendation for repair + 1sunday = 8days.

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 28 November 2018 9:22 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: ACCIDENT BETWEEN SME 4866 L AND YOUR INSURED PA 7693 J *LKK REF: CC4/LPC18019467/pb3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18019467/T1pb3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 12-04-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 7693J	Veh. Inspected	SME 4866L
Policy No.	Z/17/VC30/100863	Coverage (\$)	0.00
Claim No.	17/18/18/VC30/021055	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	26/10/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.6 VTI	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MRHFC5650JT001643	Colour	GREY
Odometer	001269	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R16	HANKOOK	6 mm
L/H Front Tyre	215/55R16	HANKOOK	6 mm
R/H Rear Tyre	215/55R16	HANKOOK	6 mm
L/H Rear Tyre	215/55R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/10/2018	Inspection Date	19/11/2018
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 4866L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE ASSY, RR.BUMPER (SN)	DEFORMED	462.90	462.90
1	GARNISH,RR.BUMPER LOWER (SN)	DEFORMED	28.65	27.30
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	5.25	-
1	REFLECTOR ASSYL.RR. (SN)	NOT NECESSARY	5.25	-
1	GARNISHR.RR.BUMPER SIDE (SN)	NOT NECESSARY	5.70	-
1	GARNISHL.RR.BUMPER SIDE (SN)	NOT NECESSARY	5.70	-
1	SPACER.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	SPACER.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	EMBLEM SETRR. (SN)	NOT NECESSARY	8.85	8.85
1	EMBLEMRR. (SN)	NOT NECESSARY	8.25	8.25
1	EMBLEM,H-MARK (SN)	NOT NECESSARY	9.15	9.15
1	LIP COMP TRUNK (SN)	TO REPAIR SEE LABOUR	354.07	-
1	WEATHERSTRIPTRUNK LID (SN)	NOT NECESSARY	52.50	-
1	GARNISH ASSYRR.LICENCE (SN)	NOT NECESSARY	73.27	-
4	REAR SENSOR (SN)	NOT NECESSARY	134.28	-
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	44.17	-
1	STIFFENEREE.SHELF FR. (SN)	NOT NECESSARY	30.90	-
1	PAN COMPSPARE TIRE (SN)	NOT NECESSARY	157.80	-
1	PANEL SETRR. (SN)	NECESSARY	182.32	182.32
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	STIFFENER.RR.PANEL SIDE (SN) (ADDITIONAL)	BENT	20.02	20.02
1	COVERRR.TOWING HOOK (SN) (ADDITIONAL)	DEFORMED	6.52	6.52
1	BEAM COMPRR.BUMPER (SN) (ADDITIONAL)	BENT	123.52	123.52
			1,848.38	908.14
LABOUR				
	BODY JOINT SEALANT FOR TAILGATE.		100.00	100.00
	BODY JOINT SEALANT FOR END PANEL.		100.00	100.00
	BODY JOINT SEALANT FOR FLOOR PANEL.	NOT NECESSARY	100.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		280.00	280.00
	REMOVE & RENEW REVERSE SENSORS.		282.00	282.00
	REMOVE & INSTALL REAR VIEW CAMERA.		380.00	380.00
	RESET & CALLIBRATE SMART ENTRY SYSTEM.		380.00	380.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		800.00	560.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		800.00	560.00
	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF LIP COMP TRUNK.		5,000.00	2,520.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,000.00	1,575.00
			11,222.00	6,737.00
GRAND TOTAL			13,070.38	7,645.14
RECOMMENDED COST OF REPAIRS				7,645.14

Report Ref No. CC4/LPC18019467/T1pb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.