



CarCrafters Singapore Pte Ltd

48 Toh Guan Road East

#05-155, Enterprise Hub

Singapore 608586

Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 Singapore 079120

Our Client

Tan Yock Sem

Date : 24/10/2018

Vehicle Num : SGQ 2182Y

Make/Model : BMW 116D 5DR Hatchback

Chassis No : WBA1V72050V723147

Accident Date : 22 Octpber 2018 @ 1130Hrs

S/N		PARTS	QTY	PRICE	TOTAL
1	RH Headamp		1	\$ 3,230.00	\$ 3,230.00
2	Front bumper		1	\$ 1,102.00	\$ 1,102.00
3					
4					
5					
6					
7					
8					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					

Taufik 97495749
 'wp'
 02/11/18 @ 10am
 Resurvey before repair
 02 days.