

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 5 September 2019 8:04 AM  
**To:** Janet Tan  
**Cc:** Admin A  
**Subject:** <Seek Mandate> EQ ref : DM18HO02830/JT \*LKK ref : CC3/EQ18019470/Npb3s2 [ACCIDENT INVOLVING SLG7272G(EQ-OI) & SHB577Y(TP) ON 20/10/2018]  
**Attachments:** LKK Survey Report & Photos.pdf; TP Docs\_SHB577Y.pdf

EQ ref : **DM18HO02830/JT**  
LKK ref : CC3/EQ18019470/Npb3s2

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLG7272G(EQ-OI) & SHB577Y(TP) ON 20/10/2018**

We refer to the above matter.

It is a head-to-rear collision. Liability is down against our insured driver.

We seek your approval to offer Third Party repairer "**SMRT AUTOMOTIVE SERVICES PTE LTD**" at **\$23,519.34(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 71,676.18	\$19,850.00
2. Loss of Rental (37days x \$106.47)	\$ 3,939.39	\$ 2,342.34 (22days x \$106.47)
3. Loss of Income (37days x \$60.00)	\$ 2,220.00	\$ 1,320.00 (22days x \$60.00)
4. LTA/ GIA Search Fee	\$ 7.00	\$ 7.00
Total	\$ 77,842.57	<b><u>\$23,519.34</u></b>

Surveyor recommended 16 days for repair + 4Sunday + 1PH + 1PRS =22days.

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)