ASS. REC. BY	GUO QIONO ASSIGNMENT (Office)
From (Person	w) Christina Word of MSIG Date/Time: 25/10/2018@4.2
Estimated Co.	out Bill to:
OD (TP)/W	VS/TP RES / OD RES / EVA / INV / MV 7 CS
	/ehicle No: SHD 1007 J Insured: SkG 8617B
	premier taxis Tel 66446689
of	23 Changi South Ave 2 # 03-02
	29073131 AVW Claim No:
Sum Insured	Excess:
Make of Veh. (Client's Recen	
	/ REP. / REV 24 HRS (UP)
Date/Time:	9.09am 0.26/10/18 Person Contacted: Vincent Vehicle IN OUT
Date/Time	Action/Instruction (/) Estimate
	SHD10071-05/TE10022002/Kfg1 00A-23/6/2010
	3KG 8617B-x.
15/11/18	Royart 1A ma ermil.
23/11/15	(onfirm with Vincent LK \$500 @ 2 days (Red: \$515.26,51%)

...CLAIM SUBFOLDER...(New Assignment)

Cited	Notified	Est Submitted	Adj Assigned	Adl Rpt	Ad) Sul	bmittest	Jas Autmed	Status		
	25 Oct 2018 09:55		25 Oct 2018 16:23 Assign					New As	STATE OF THE PERSON NAMED IN COLUMN	nt
,	Hain	Re	ference		Claim Details		Docume	nts		Show All
CLAIM SU	BFOLDER DE	TAILS				[Creat	ed by insurer]			
Insured:	PANG KIN	HUEY (FENG JI	NHUI), ID: S7	7170203						
Main Claimant:	PREMIER	TAXIS PTE LTD,	Co. Reg. No.:	200304975	н					
Vehicle Reg No.:	SHD100	73			Date of Loss	24/10/2018 00:00 - :59 [33 Months and 24 Days From LTA Reg Date (Man			Man Yr)]	
Claim Type:	TP				Policy/Cover Note No.:	The transfer of the property of the second s				
Vehicle Reg. No. (Insured):	SKG8617	В			Policy No. (Claimant):					
		process and the same			Excess:					
Repairer:	Premier T	axis Pte Ltd - Ch	angi (HQ) 23 (hangi Sout	h Ave 2 #03-02,	486443 (Changi - Tel:			
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	IQ) - Tel: +	65 6827 7888	. [Handled	by Christina Wo	ong - 6643 1	311]	
Adjuster:	LKK Auto	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 26/10/2018]								
Adj Asg. Remarks:	Liability ur	iclear, Non Reporti	ng. TP agree to	use LKK as	the SJE. Contact	Person: \	/incent / 6544 668	9 / 9155 00	72	
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose	Case Mai
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	ks⊟				View	All Search Tasks	Create No	on Their I	Complete

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Christina Wong

15 Nov 2018 Date:

Preliminary Advice

Insured Vehicle No : SKG8617B

TP Vehicle No

: SHD1007J

Accident Date

: 24/10/2018

Make

: KIA OPTIMA

Assignment Date

: 25/10/2018

Date of Inspection

: 26/10/2018

Est. Duration of Repair

: 2.00

Inspection At

: PREMIER TAXIS PTE LTD - CHANGI (HQ)

23 CHANGI SOUTH AVE 2 #03-02

SINGAPORE 486443

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,013.26
Revised Amount	:S\$	266.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	266.90

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for Investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by Interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

sforesaid	
	ACCIDENT STATEMENT
Date Of Report	24/10/2018 10:13
Date Of Accident	24/10/2018 08:20
Exact Location Of Accident	WOODLANDS AVE 3 // WOODLANDS AVE 5
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD1007J
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used a time of accident	Device and the second of the Second s
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	
Driver	
Name of Driver	PEK BOON HUA
NRIC No	S7728387J
Date Of Birth	14/10/1977
Occupation	OUTDOOR
Date Of Driving Pass	20/11/1995
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90088089
Fax Number	
Contact Number	

NOEMAIL

Address

BLK 20 #38-109

TEBAN GARDENS ROAD

Postcode

600020

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

VEH. A - NO PAX VEH. B - 1 PAX

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

SKG8617B

Vehicle Registration Number Vehicle Make/Model/Colour

VOLKSWAGON

DETAILS OF OTHER VEHICLE PROPERTY 1

Details Of Properties

VEH. B

Vehicle Category

PRIVATE CAR

Name of Driver

SOH WEE KUAN

NRIC/Passport Number Contact Number

S7810571B 84986513

Address

Postcode

Insurance Company Name

Nature Of Damage

DAMAGED ON THE FRONT PORTION

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PEK BOON HUA - DRIVER OF VEH. A

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

WILL SEEK FOR MEDICAL TREATMENT

SHD1007J

YES

NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the datails of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) Investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:

Peporting Centre Personnel's Signature


NRIC/FIN No.:

Z 574D 1007 J

SMAKE HARTESHARE TO

S+722387-J

Sketch Plan Pg. 2



Describe Circumstance of the Accident.

ON 24/10/2018 @ 0820 HRS, I WAS DRIVING MY TAXI (SHD 1007 J) - TRAVELLING ALONG THE TRAFFIC LIGHT JUNCTION OF WOODLANDS AVE 3 & WOODLANDS AVE 5, IN THE EXTREME LEFT LANE.

I STOPPED MY TAXI AS VEHICLES AHEAD OF ME STOPPED – DUE TO RED TRAFFIC LIGHT.

WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.


WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SKG 8617 B - VOLKS) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT PORTION.

AS A RESULT, I FELT SOME DISCOMFORT & WILL SEEK FOR MEDICAL TREATMENT SOON. NO AMBULANCE AT SCENE.

NO PASSENGERS ONBOARD MY TAXI & VEHICLE B HAD A PASSENGER ONBOARD.

*VIDEO FOOTAGE CAPTURED & SCENE PHOTOS TAKEN.



Text size +

Enquire Transaction History

Transaction History Details

Log Date/Time:

30 Dec 2015 / 09:05:18

Receipt No.:

AACCK001-AX239-151230-000010

Asset Type:

Vehicle

Transaction Amount:

\$68,909.00

Asset ID:

SHD1007J

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction

01.02 Register New Vehicle (AA)

Reference No.:

20151230090518433905

Vehicle No.:

SHD1007J

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 30 Dec 2015

Original Registration

30 Dec 2015

KIA

Vehicle Make: Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5658196

Engine No.:

D4FDFH314375

Motor Na.:

Propellant:

Trailer Chassis No.:

Diesel

Passenger Capacity:

4

Engine Capacity:

1685

Power Rating:

1584

Unladen Weight: Maximum Laden

Weight

2050

Primary Color:

Silver

Secondary Color

2015

Manufacturing Year:

Open Market Value:

\$22,359.00

Minimum PARF Benefit \$13,981.00

PARF Eligibility: No. of Transfer.

Υ

Effective Ownership

Date/Time:

30 Dec 2015 09:05:18

COE No:

2015123001003576D

COE Expiry Date:

29 Dec 2023

COE 8id Category:

Actual QP/PQP Paid

Amount:

\$45,465.00

Lifespan Expiry Date

29 Dec 2023

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	4975H
Vehicle Details	
Vehicle No.:	SHD1007J
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	D4FDFH314375
Chassis No.:	KNAGM414MF5658196
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$22,359.00
Original Registration Date:	30 Dec 2015
First Registration Date:	30 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$23,303.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2023
PARF Rebate Amount:	\$17,477.00
Intended COE Rebate Details	20.0 2022
COE Expiry Date:	29 Dec 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,466.00
COE Rebate Amount: Total Rebate Amount:	\$29,363.00 \$46,840.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Oct 2018

#01-02, Singapore 486443

Assessment Number: MSIG0050

Assessor Report Printed: 26/10/2018 Version: PREMIERA/1

Summary Information

Claim

Claim Reference:

SHD1007J

Insured:

Policy Number: Date of Decision:

26/10/2018

Third Party:

Repairer:

Estimated Repair Time

0.0

Able to Authorise Repairs: TBA Repairs Authorised? TBA

(Working Days):

Insured's Liability

TBA

Customer Contribution:

\$0.00 (excl GST)

Vehicle Details

Vehicle

Excess:

Registration:

SHD1007J

VIN/Chassis Number:

Manufacturer:

KIA December Model:

Optima 2015

Unknown

Registration Month: Odometer:

Not Known

Registration Year: Colour:

Build Date:

Model Specs

FROM 05/2015

PREPARE OFF VEHICLE

BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Date of Incident:

Pre-Accident Condition:

24/10/2018

Market Value:

Salvage Value: Date of Inspection:

Place of Inspection:

Unknown 26/10/2018

Pre-Accident Damage:

Steering Rim Ply: Brake Pedal Travel:

Vehicle Status:

Damage Severity:

Tyres Condition:

Tread Depth LHF:

Tread Depth LHR:

Tread Depth RHF: Tread Depth RHR:

Repair Information

LABOUR Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details wu Cost Price (\$) 86520R00 RENEW REAR BUMPER (REMOVED) 11.0 55.00 LABOUR COST

Total Work Units 11.0 Corrosion Protection External Labour 0.0HRS 0.00 Corrosion Protection Internal Labour 0.0HRS 0.00 Sub Total **1.1HRS** \$55.00 Paint Labour **2.9HRS** \$145.00 Total Labour 4.0HRS \$200.00

#01-02, Singapore 486443

Assessment Number: MSIG0050

Assessor Report Printed: 26/10/2018 Version: PREMIERA/1

PAINT WORK	(Time Basis 10 WU =	1 HR. Price =	\$50.00/HR
Guide Numb	er Description		wu	Cost Price (\$)
	- PREPARE OFF VEHICLE			
	- BASECOAT CLEAR			
2583	REAR BUMPER NEW PART PAINT K1	R	14.0	
	BOUR COST - PAINT			
5=7	TIME(PAINT)		14.0	
	Preparation Main Work Plastic		15.0	
	Preparation Work Multi Layer Pa	aint	0.0	
	Total Work Units (10WU/HR)		29.0	
	Total Paintwork Labour		2.9HRS	\$145.00
M/	TERIAL COST - PAINT		Z.JIIKJ	Cost Price
1110	New Part Painting - Plastic K1R			\$70.36
	Material-Const Main Work Plasti	is .		\$28.60
	Total Excluding Pearlescent Upli			\$98.96
	Pearlescent Uplift @ 0.0%			\$0.00
	Total Paint Material Cost			\$98.96
PARTS	Total Pallit Material Cost			\$90.90
ARIS			Price Va	alid: 01/06/2015
Guide No. Ot	Description Part	Number Supplie		
2583 1	REAR BUMPER X REGION - 8661	12T500	0%	696.00*
2770 1			0%	206.00*
: OEM Parts	REAR BUMPER SPOILER 48661	Sub Total	0 70	\$902.00
g: Original		Deduction from RRP	(35 %)	-\$315.70
		Deduction Hom RR	(33,70)	-3313.70
h: Secondhan	1			
	1	Total Parts	,	\$586.30
p: Parallel	1			
p: Parallel		Total Parts		
p: Parallel x: Exchange	NB - COLOUR CODED ITEMS/	Total Parts		
p: Parallel x: Exchange	NB - COLOUR CODED ITEMS/	Total Parts TRIM - PART NUMBERS		133.9
p: Parallel x: Exchange	NB - COLOUR CODED ITEMS/	Total Parts TRIM - PART NUMBERS Betterment		\$586.30 (33, 9 Price
p: Parallel x: Exchange	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST	Total Parts TRIM - PART NUMBERS		\$586.30 (33.9 Price \$48.00
p: Parallel x: Exchange	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP SPECIALIST	Total Parts TRIM - PART NUMBERS Betterment		\$586.30 (33, 9 Price
p: Parallel x: Exchange	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST	Total Parts FRIM - PART NUMBERS Betterment 0%		\$586.30 (33.9 Price \$48.00 \$80.00
p: Parallel x: Exchange Extras	NB - COLOUR CODED ITEMS/TO PROTECTOR / WC .	Total Parts TRIM - PART NUMBERS Betterment		\$586.30 (33.9 Price \$48.00
p: Parallel x: Exchange Extras Final Calcu	NB - COLOUR CODED ITEMS/TO PROTECTOR / WC .	Total Parts FRIM - PART NUMBERS Betterment 0%		\$586.30 (33.9 Price \$48.00 \$80.00
p: Parallel x: Exchange Extras Final Calcu Total Parts	NB - COLOUR CODED ITEMS/TO PROTECTOR / WC .	Total Parts FRIM - PART NUMBERS Betterment 0%		\$586.30 (33.9 Price \$48.00 \$80.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR & SPECIALIST PROTECTOR & SPECIALIST	Total Parts FRIM - PART NUMBERS Betterment 0%	MAY DIFFER	\$586.30 (33.9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Tot	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR ACC. Iation	Total Parts FRIM - PART NUMBERS Betterment 0%	MAY DIFFER	\$586.30 (33.9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Tot	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR & SPECIALIST PROTECTOR & SPECIALIST	Total Parts FRIM - PART NUMBERS Betterment 0%	MAY DIFFER	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Tot Total Labour	Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST	Total Parts FRIM - PART NUMBERS Betterment 0%	MAY DIFFER	\$586.30 (33.9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Tot Total Labour Additional Co	Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$3 \$145.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Tot Total Labour Additional Co	Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR SPECIALIST Iation al Panel/Mechanical al Paintwork osts r Prot Materials External	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$145.00 \$0.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Total Labour Additional Con	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR SPECIALIST PROTECTOR SPECIALIST PROTECTOR SPECIALIST PROTECTOR SPECIALIST SPECI	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$3 \$145.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Total Labour Additional Con	Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR SPECIALIST Iation al Panel/Mechanical al Paintwork osts r Prot Materials External	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$145.00 \$0.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00
p: Parallel x: Exchange Extras Final Calcu Total Parts Labour Tot Total Labour Additional Cor	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR SPECIA	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$145.00 \$0.00 \$0.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00 \$586.30
p: Parallel x: Exchange Extras Final Calcul Total Parts Labour Tot Total Labour Additional Cor Cor Cor Cor Cor Total of Addi	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR SPECIA	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$145.00 \$0.00 \$0.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00 \$586.30
Total Labour Additional Con Con Con Con Total of Addi Total Paint/I	NB - COLOUR CODED ITEMS/ Description REAR BUMPER CLIP SPECIALIST BUMPER TOP PROTECTOR SPECIALIST PROTECTOR SPECIALIST Internal Panel/Mechanical	Total Parts FRIM - PART NUMBERS Betterment 0%	\$55.00 \$145.00 \$0.00 \$0.00	\$586.30 (33, 9 Price \$48.00 \$80.00 \$128.00 \$586.30

PREMIER AUTOMOTIVE SERVICES PTE LTD 23 Changi South Ave 2 #01-02, Singapore 486443

Assessment Number: MSIG0050

Version: PREMIERA/1

Assessor Report Printed: 26/10/2018

\$1,084.19

Grand Total Includes GST

Assessment Notes

2Days. Wishils 128-21 beful Ather repair phtos.

Guo Giag - 82880282

26/10/18.

L-CK Auto Consultants hence notify

- = Repairer of the following:
- . It is unvey before after spray painting
- " asplay damaged partis) during resurvey
- THE THESE are subject to confirmation
- " Third party survey is on a "Without Prejudice" basis
- + "in lilegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and sisubject to final approval from Insurance Company

-conowledged by Repairer

Synature

Date:

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

408933

Claim Reference: SHD1007J Assessment Number: MSIG0050

Version: PREMIERA/1

Date Calculated: 15/11/2018 01:33

Full Report - V1 Registration: SHD1007J

Printed: 15/11/2018 09:35

SGD

TBA

24/10/2018

PREPARE OFF VEHICLE

Summary Information

Claim

Location:

Printed by:

Authorisation Status: Work Provider:

Claim Reference: Policy Number:

Other Reference: Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

LKK AUTO Interim

MSIG Insurance (Singapore) Pte

SHD10073

KIA

Optima

2836 01 SHD1007J

December

Not Known

2015

9/6

BASE MODEL

Estimated Repair Time: Quote Due Date: Actual Repair Days:

Able to Authorise Repairs: TBA

Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

Vehicle Condition **Vehicle Status**

Pre-Accident Condition:

Steering:

Brakes Pedal Travel:

Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Model Specs

Currency:

Date of Incident:

Repairs Authorised:

FROM 05/2015

BASECOAT CLEAR

Severity of Impact: Vehicle Status on Inspection:

Date of Inspection:

26/10/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHD1007J

Full Report - V1


Assessment Number: MSIG0050


Registration: SHD1007J

Version: PREMIERA/1

Printed: 15/11/2018 09:35

Date Calculated: 15/11/2018 01:33





Addresses

Cost Summary

Total Labour	\$5.00
Total Parts	\$133.90
Total of Additional Costs	\$128.00
Excess:	TBA
Grand Total Exc GST:	\$266.90
7 % GST:	\$18.68
Grand Total Inc GST:	\$285.58

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Renair /

inchested /			
Guide Numbe	er Repair Details	wu	Cost Price (\$)
NO NUMBER	R + R REAR BUMPER SPOILER	1.0	5.00
LA	BOUR COST		
	Total Work Units	1.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	0.1HRS	\$5.00
	Total Labour	0 1HPS	\$5.00

PAI	NT	wo	RK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

- PREPARE OFF VEHICLE

Cost Price (\$)

BASECOAT CLEAR

LABOUR COST - PAINT

TIME(PAINT)

0.0

Total Work Units (10WU/HR)

0.0

Total Paintwork Labour

0.0HRS \$0.00 **Cost Price**

Price Valid: 01/06/2015

MATERIAL COST - PAINT **Total Excluding Pearlescent Uplift**

\$0.00

Pearlescent Uplift @ 0.0% **Total Paint Material Cost**

\$0.00 \$0.00

PARTS

					ine amile	, orlool rore
Guide No. Qty	Description	Part Number	Supplier		Bet.	Price (\$)
2770 1	REAR BUMPER SPOILER	866122T500	2-2000/10-2007/12-		0%	206.00*
f: OEM Parts		Sub Total				\$206.00
g: Original		Deduction t	from RRP	(35 %)		-\$72.10
h: Secondhand		Total Part	s	8 8		\$133.90
p: Parallel						

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHD1007J Full Report - V1

Assessment Number: MSIG0050 Registration: SHD1007J Version: PREMIERA/1 Printed: 15/11/2018 09:35

Date Calculated: 15/11/2018 01:33

x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

EXUAS			
Description		Betterment	Price
REAR BUMPER CLIP	SPECIALIST	0%	\$48.00
BUMPER TOP	SPECIALIST		\$80.00
PROTECTOR			13420000
		Total Extras	\$128.00
Final Calculation			
Total Parts			\$133.90
Labour			
Total Panel/Mechanical			\$5.00
Total Paintwork			\$0.00
Total Labour			\$5.00
Additional Costs			(Tages)
Corr Prot Materials External			\$0.00
Corr Prot Materials Internal			\$0.00
Cost of Specialist		\$1	28.00
Total of Additional Costs		100	\$128.00
Total Paint/Material Costs			\$0.00
Grand Total Excludes GST			\$266.90
GST @ 7 %			\$18.68
Grand Total Includes GST			\$285.58

Assessment Notes

#01-02, Singapore 486443

Assessment Number: MSIG0050

Assessor Report Printed: 22/11/2018 Version: PREMIERA/1

Summary Information

Claim Reference:

SHD1007J

Insured:

Policy Number:

Third Party:

Date of Decision: Repairer:

(Working Days):

26/10/2018

Able to Authorise Repairs: TBA

Estimated Repair Time

Repairs Authorised?

TBA

Insured's Liability

Excess:

TBA

0.0

Customer Contribution:

\$0.00 (excl GST)

Vehicle Details

Vehicle

Registration: Manufacturer: SHD1007J KIA

VIN/Chassis Number:

Model: Registration Year: Optima 2015

Registration Month: Odometer:

December Not Known

Colour:

Build Date:

Model Specs

FROM 05/2015

24/10/2018

PREPARE OFF VEHICLE BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Date of Incident:

Pre-Accident Condition:

Pre-Accident Damage:

Steering Rim Ply: Brake Pedal Travel: Vehicle Status:

Damage Severity:

Market Value:

Salvage Value:

Date of Inspection:

Unknown Unknown

26/10/2018

Place of Inspection:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Tread Depth RHF: Tread Depth RHR:

Repair Information

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR LABOUR Price/Dent = \$50.00/HR

Repair / wu Cost Price (\$) **Guide Number Repair Details** 5.00 R + R REAR BUMPER SPOILER 1.0 NO NUMBER 100.00 20.0* REPAIR REAR BUMPER 2583 LABOUR COST

21.0 **Total Work Units** 0.00 Corrosion Protection External Labour 0.0HRS 0.00 0.0HRS **Corrosion Protection Internal Labour 2.1HRS** \$105.00 Sub Total \$210.00 **4.2HRS** Paint Labour \$315.00 **6.3HRS Total Labour**

#01-02, Singapore 486443

Assessment Number: MSIG0050

Assessor Report Printed: 22/11/2018 Version: PREMIERA/1

Mark Carl Hornor and Arthur Carl	Time Basis	10 WU = 1	1 HR. Price =	\$50.00/HR Cost Price (\$)
Description			WU	Cost Price (\$)
- BASECOAT CLEA	AR		17.0	
	IT PLASTIC		17.0	
	VOICE-CO			
Preparation Main Work P	lastic			
Preparation Work Multi L	ayer Paint		15.77.70	
	/HR)			\$210.00
			4.2HRS	Cost Price
				\$57.92
Repair Painting Plastic				The second secon
				\$28.60
Total Excluding Pearlesc	ent Uplift			\$86.52
Pearlescent Uplift @ 0.00	Va			\$0.00
Total Paint Material Cost				\$86.52
			Price Va	lid: 01/06/2015
Description	Part Number	Supplier	Bet.	Price (\$)
PEAR RUMPER SPOTLER			0%	206.00
REAR BOTH ER ST STEET				\$206.00
		from RRP	(35 %)	-\$72.10
		S. S. San, S. S. S. S. S. S. S. S.		
	Total Par	ts		\$133.90
	Total Par	ts		\$133.90
	Total Par	ts		\$133.90
			MAY DIFFER	\$133.90
NB - COLOUR CODED	ITEMS/TRIM - PART	NUMBERS N	MAY DIFFER	\$133.90
NB - COLOUR CODED Description	ITEMS/TRIM - PART		MAY DIFFER	Price
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC	ITEMS/TRIM - PART Bet IALIST 0%	NUMBERS N	MAY DIFFER	Price \$48.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC	ITEMS/TRIM - PART	NUMBERS N	MAY DIFFER	Price \$48.00 \$80.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC BUMPER TOP SPEC	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	MAY DIFFER	Price \$48.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC BUMPER TOP SPEC	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	MAY DIFFER	Price \$48.00 \$80.00 \$128.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC BUMPER TOP SPEC PROTECTOR	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	MAY DIFFER	Price \$48.00 \$80.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC BUMPER TOP SPEC PROTECTOR	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N		Price \$48.00 \$80.00 \$128.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPECE BUMPER TOP SPECE PROTECTOR at Panel/Mechanical	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00	Price \$48.00 \$80.00 \$128.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPEC BUMPER TOP SPEC PROTECTOR	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N		Price \$48.00 \$80.00 \$128.00 \$133.90
NB - COLOUR CODED Description REAR BUMPER CLIP SPECTOR BUMPER TOP SPECTOR PROTECTOR at Panel/Mechanical Paintwork	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00	Price \$48.00 \$80.00 \$128.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPECT	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00 \$210.00	Price \$48.00 \$80.00 \$128.00 \$133.90
NB - COLOUR CODED Description REAR BUMPER CLIP SPECT	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00 \$210.00 \$0.00	Price \$48.00 \$80.00 \$128.00 \$133.90
NB - COLOUR CODED Description REAR BUMPER CLIP SPECT	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00 \$210.00 \$0.00 \$0.00	Price \$48.00 \$80.00 \$128.00 \$133.90
NB - COLOUR CODED Description REAR BUMPER CLIP SPECT	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00 \$210.00 \$0.00	Price \$48.00 \$80.00 \$128.00 \$133.90 \$315.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPECE BUMPER TOP SPECE PROTECTOR All Panel/Mechanical all Paintwork sts r Prot Materials External r Prot Materials Internal t of Specialist tional Costs	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00 \$210.00 \$0.00 \$0.00	Price \$48.00 \$80.00 \$128.00 \$133.90 \$315.00
NB - COLOUR CODED Description REAR BUMPER CLIP SPECT	ITEMS/TRIM - PART Bet HALIST 0% HALIST	NUMBERS N	\$105.00 \$210.00 \$0.00 \$0.00	Price \$48.00 \$80.00 \$128.00 \$133.90 \$315.00
	- PREPARE OFF VE - BASECOAT CLEAR REAR BUMPER REPAIR PAIN OUR COST - PAINT TIME(PAINT) Preparation Main Work P Preparation Work Multi L Total Work Units (10WU, Total Paintwork Labour TERIAL COST - PAINT Repair Painting Plastic Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00	- PREPARE OFF VEHICLE - BASECOAT CLEAR REAR BUMPER REPAIR PAINT PLASTIC OUR COST - PAINT TIME(PAINT) Preparation Main Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour PERIAL COST - PAINT Repair Painting Plastic Material-Const Main Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0% Total Paint Material Cost Description REAR BUMPER SPOILER Part Number 866122T500 Sub Total	- PREPARE OFF VEHICLE - BASECOAT CLEAR REAR BUMPER REPAIR PAINT PLASTIC OUR COST - PAINT TIME(PAINT) Preparation Main Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour ERIAL COST - PAINT Repair Painting Plastic Material-Const Main Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0% Total Paint Material Cost Description Part Number Supplier REAR BUMPER SPOILER 866122T500	- PREPARE OFF VEHICLE - BASECOAT CLEAR REAR BUMPER REPAIR PAINT PLASTIC OUR COST - PAINT TIME(PAINT) Preparation Main Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour PERIAL COST - PAINT Repair Painting Plastic Material-Const Main Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0% Total Paint Material Cost Price Va Description REAR BUMPER SPOILER Part Number Supplier Bet. 0%

#01-02, Singapore 486443

Assessment Number: MSIG0050

Version: PREMIERA/1

Grand Total Includes GST

Assessment Notes

Assessment Notes

Assessment Notes

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2 #01-02, Singapore 486443

Claim Reference: SHD1007J Assessment Number: MSIG0050

Version: PREMIERA/2

Date Calculated: 22/11/2018 07:23

Full Report - V1

Registration: SHD1007J

Printed: 23/11/2018 10:16

SGD

TBA

24/10/2018

Summary Information

Claim

Location:

Printed by:

Work Provider:

Authorisation Status:

Interim

MSIG Insurance (Singapore) Pte

Claim Reference: Policy Number: Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired:

Currency: Singapore (SG) Date of Incident:

LKK AUTO

SHD1007J

Estimated Repair Time: Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Repairs Authorised:

Able to Authorise Repairs: TBA

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

%

KIA

Optima

2836 01 SHD1007J

2015

December

Not Known

BASE MODEL

Model Specs

FROM 05/2015 BASECOAT CLEAR PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

26/10/2018

Tread Depth RHF: Tread Depth RHR: Direction of Impact:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Claim Reference: SHD1007J


Assessment Number: MSIG0050


Version: PREMIERA/2

Date Calculated: 22/11/2018 07:23

Full Report - V1 Registration: SHD1007J

Printed: 23/11/2018 10:16





Addresses

Cost	Sun	nma	ary
------	-----	-----	-----

Total Labour	\$315.00
Total Paint/Material	\$86.52
Total Parts	\$133.90
Total of Additional Costs	\$128.00
Excess:	TBA
Grand Total Exc GST:	\$663.42
7 % GST:	\$46.44
Grand Total Inc GST:	\$709.86

Repair Information LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair / Guide Number NO NUMBER 2583	R + R REAR BUMPER SPOILER REPAIR REAR BUMPER	WU 1.0 20.0*	Cost Price (\$) 5.00 100.00
	BOUR COST Total Work Units Corrosion Protection External Labour Corrosion Protection Internal Labour Sub Total Paint Labour Total Labour	21.0 0.0HRS 0.0HRS 2.1HRS 4.2HRS 6.3HRS	0.00 0.00 \$105.00 \$210.00 \$315.00

PAINT W	ORK	Time Basis 10 WU = 1 HR. Price	= \$50.00/HR
	umber Description	WU	Cost Price (\$)
oulue iii	- PREPARE OFF VEHICLE - BASECOAT CLEAR		
2583	REAR BUMPER REPAIR PAINT PLASTIC	17.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	17.0	
	Preparation Main Work Plastic	25.0	
	Preparation Work Multi Layer Pair	nt 0.0	
	Total Work Units (10WU/HR)	42.0	
	Total Paintwork Labour	4.2HRS	\$210.00
	MATERIAL COST - PAINT		Cost Price
	Repair Painting Plastic		\$57.92
	Material-Const Main Work Plastic		\$28.60
	Total Excluding Pearlescent Uplift		\$86.52
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$86.52

PREMIER AUTOMOTIVE SERVICES PTE LTD

Claim Reference: SHD1007J

Full Report - V1

Assessment Number: MSIG0050

Registration: SHD1007J Printed: 23/11/2018 10:16

BILLIAND MARKET

Version: PREMIERA/2

Date Calculated: 22/11/2018 07:23

PARTS

				Pr	ice Valid	: 01/06/2015
Guide No. Qty	Description REAR BUMPER SPOILER	Part Number 866122T500	Supplier		Bet.	Price (\$) 206.00*
f: OEM Parts	REAR DOTTERS DE CILER	Sub Total				\$206.00
g: Original		Deduction f	rom RRP	(35%)		-\$72.10
h: Secondhand	1	Total Parts		Actor (See		\$133.90

p: Parallel x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description REAR BUMPER CLIP	SPECIALIST	Betterment 0%	Price \$48.00 \$80.00
PROTECTOR	SPECIALIST	Total Extras	\$128.00

Final Calculation	
Total Parts	\$133.90
Labour	
Total Panel/Mechanical	\$105.00
Total Paintwork	\$210.00

\$315.00 **Total Labour** Additional Costs \$0.00 Corr Prot Materials External \$0.00

Corr Prot Materials Internal \$128.00 Cost of Specialist \$128.00 **Total of Additional Costs** \$86.52 Total Paint/Material Costs \$663.42 Grand Total Excludes GST \$46.44 GST @ 7 %

\$709.86 **Grand Total Includes GST**

Assessment Notes

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Friday, November 23, 2018 10:36 AM

To:

'Vincent Chua'

Cc:

Goh Wee Dek; Gary Shi; Guo Qiang (LKKAuto)

Subject:

RE: SHD 1007J

Dear Vincent,

As spoken, confirm L/S \$500/- @ 2 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vincent Chua [mailto:vincent.chua@premiertaxi.com]

Sent: Thursday, November 22, 2018 4:40 PM

To: Janice Lee (LKKAuto) < JaniceLee@lkkauto.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Gary Shi <gary.shi@premiertaxi.com>; Guo Qiang (LKKAuto)

<GuoQiang@lkkauto.com> Subject: RE: SHD 1007J

Dear Janice,

As requested, we have amended the adjusted figures and shared it to LKKAuto In Audatex. Please refer to this latest copy.

L/S Repair \$650.00/-, 02 Repair days (before GST)

Please confirm.

Thank you.

Regards

Vincent Chua Operations Assistant

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRAC	KING					
Case	Natified	Est Submitted	Adj Assigned	Adj Rpt	Ad) Submitted	Ins Auth'ed	Status
Main	25 Oct 2018 09:55		25 Oct 2018 16:23 Edit Adj Rpt	S\$500.00 Edit Estimates	\$\$500.00 View Rpt		Pending for Survey Report Cancel Case
	Main	Ref	erence	Claim De	tails	Documents	Show All
CLAIM SU	BFOLDER DE	TAILS			[Created	by insurer]	
Insured:	PANG KIM	HUEY (FENG JIN	HUI), 10: 577170	203			
Main Claimant:	PREMIER	TAXIS PTE LTD.	Co. Reg. No.: 2003	04975H			
Vehicle Reg No.:	SHD100	73		Date of		8 00:00 - :59 s and 24 Days Fron	LTA Reg Date (Man Yr)]
Claim Type	TP			Policy/C Note No		AVW 19/02/2018 - 18/0	2/2019
Vehicle Reg No. (Insured):	SKG86178			Policy N (Claima	2007		
4307				Excess:			
Repairer:	Premier To	axis Pte Ltd - Cha	ngi (HQ) 23 Chang	South Ave 2 #03	-02, 486443 Char	ngi - Tel:	
Handling Insurer:	356,550,000) Pte. Ltd. (HQ) -				
Adjuster:	LKK Auto	Consultants Pte L	td (HQ) - Tel: 6256	-3561 [Handle	d by XING GUO	[Final] [Final]	Rpt due 24/11/2018]
Adj Asg. Remarks:	Liability und	dear. Non Reportin	g. TP agree to use L	KK as the S3E. Co	ntact Person: Vinc	ent / 6544 6689 / 5	155 0072
ASSOCIA	TED MAIL REG	CEIVED				View	All Compose Case Mail
There are o	o mail for this	case.					-
ALL ASSO	CIATED TAS	ks⊟			View All	Search Tasks Cr	eate New Task Complete
Due Dat No results.	0.0000000000000000000000000000000000000	Type Task 0	roup Subject	Handler	Assigned By	Completed On	Created On Done

Claim Documents

*SHD1007J
[SKG8617B]
TP
PREMIER TAXIS PTE LTD
Oct 24 2018 12:00AM
[PANG KIM HUEY (FENG JINHUI)]
Premier Taxis Pte Ltd - Changi

_		licad Photos Compose New Letter	100001	View in Brows	_
	essment Reports		1 per i		V
Na.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	0	Thumbnail Load HTM	Print
1	15/11/18 11:26	Adjuster Immediate Advice		Load HIM	
Pho	otos/Images		3 per	page V	V
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/18 11:27	General View	0	Load JPG	V
2	15/11/18 11:27	General View	0	Load JPG	V
3	15/11/18 11:27	General View	0	Load JPG	V
4	15/11/18 11:27	General View	0	Load JPG	V
5	15/11/18 11:27	General View	0	Load JPG	V
6	15/11/18 11:27	General View	0	Load JPG	V
7	15/11/18 11:27	General View	0	Load JPG	V
8	15/11/18 11:27	General View	0	Load JPG	N.
9	15/11/18 11:27	General View	0	Load JPG	V
10	15/11/18 11:27	General View	0	Load JPG	V
11	15/11/18 11:27	General View	0	Load JPG	2
12	15/11/18 11:27	General View	0	Load JPG	V
13	15/11/18 11:27	General View	0	Load JPG	V
14	15/11/18 11:27	General View	0	Load JPG	V
15	15/11/18 11:27	General View	0	Load JPG	N.
16	15/11/18 11:27	General View	0	Load JPG	V
17	15/11/18 11:27	General View	0	Load JPG	8
18	15/11/18 11:27	General View	0	Load JPG	V
19	15/11/18 11:27	General View	0	Load JPG	4
20	15/11/18 11:27	General View	0	Load JPG	50
21	23/11/18 10:45	Reinspection Photo	0	Load JPG	V
22	23/11/18 10:45	Reinspection Photo	0	Load JPG	V
23	23/11/18 10:45	Reinspection Photo	0	Load JPG	V
24	23/11/18 10:45	Reinspection Photo	0	Load JPG	V
	1.00				
Doc	cumentation		1 per	-	100
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/10/18 10:07	PRI, TP GIA Rpt, GIA Search	0	Load PDF	
2	25/10/18 10:11	Fax to TP our SJE list and Fax transmission report	9	Load PDF	-

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print	ĺ
				1

Merimen e-Claims Page 2 of 2

There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	v
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18019487/GRD3E2

Date:

28/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29073131AVW

Claimant Vehicle SHD1007J

Insured Vehicle No :

SKG8617B

No: Date of Loss:

24/10/2018

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD1007J

Make & Model:

KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDFH314375

477408 km

Reg. Date: Colour

30/12/2015 (Man. Year. 2015) Silver

Chassis No: Odometer:

KNAGM414MF5658196

Engine Capacity:

1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side:

Maxxis 6 mm

Rear Left Side: Rear Right Side: Maxxis 6 mm Maxxis 6 mm

Front Right Side: Maxxis 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	714.30	261.90	452.40	63.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	413.96	401.52	12.44	3.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,128.26	663.42	464.84	41.20
Approved Total (Overridden) (S\$)		500.00		
(S\$)	1,128.26	500.00	628.26	55.68
+ GST 7.00/7.00% (S\$)	78.98	35.00	43.98	55.68
Nett Amount (S\$)	1,207.24	535.00	672.24	55.68

INSPECTION

Date of Assignment:

25/10/2018

Date Inspected:

26/10/2018 Inspected At:

Premier Taxis Pte Ltd - Changi (HQ)

23 Changi South Ave 2 #03-02

Singapore 486443

Estimated Period of Repair:

2.0 days

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Ve

Version: 1.0 (Last Synchronised: 28 Nov 2018)

Parts: 143 KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD1007J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairers	Amount
1	1		*REAR BUMPER	Repair	696.00 FL	*-FL
2	1		*REAR BUMPER SPOILER	Cut	206.00 FL	*206.00 FL
3	1		*REAR BUMPER CLIP	Necessary	48.00 FS	*48.00 FS
4	1		*BUMPER TOP PROTECTOR	Necessary	80.00 FS	*80.00 FS
F=Fr	anchise	part. S=SpcNe	tt. L=ListtlemDisc.	_	111411 mercurian and an	
				Sub Total (S\$)	1,030.00	334.00
			 List Item Discount on L Items 3 	315.70	72.10	
				Total Parts (S\$)	714.30	261.90

Condition

Danalanda

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		17-00-13-00	
1	TOTAL PANEL / MECHANICAL	New	105.00	105.00
2	TOTAL PAINTWORK	New	210.00	210.00
3	TOTAL PAINT / MATERIAL COSTS	New	98.96	86.52
		Gross Labour Cost (S\$)	413.96	401.52
	Report wa	as unsubmitted during this print-out.		

< END OF ESTIMATES >