

PDI TUAS

Tarfin 97445749
WP

26/10/18 @ 3:50pm

Phone No.

Fax No.

E-Mail

PDI TUAS

KHOO SWEE YIN
(QIU RUIYIN)
124B BUKIT MERAH VIEW
#06-394
Singapore, 152124
Singapore

using before paint.
SWE (Luan) 15.11.18
98 days

VAT Registration No. M20098505-2

Tax No. 199101494Z

Service Quote

Customer No. CV036746
Quote No. SER/QUO/1801793
QuoteDate 26/10/18
Salesperson Ian Yeo
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Beetle NF 1.2 (A) SR HID	9,822	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKK7977Y	WVWZZZ16ZGM608799	30/05/17	Ian Yeo
Engine Code	Labor Type	Engine No.	Model Code
	M5	CBZ K15341	5C13D7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	8	UNIT	4200	6,720.00
P B&P ALEX LABOUR	RE+REINSTALLED UPHOLDSTR	1	UNIT	420	840.00
P B&P ALEX PAINT	SPRAY PAINTING	8	UNIT	4000 3600	6,400.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT	1	Time Un		360.00
	Sum Labor				15,080.00
P 311601361	RUBBER VALVE Use Predecessor 281601361	1	Pieces		2.28
P 5C0601025AKAX1	18" 'TWISTER' RIM ONLY BLACK GLOSSY	1	Pieces		1,905.95
P 5C5807393F	BUMPER BRACKET LHS Predecessor 5C5807393D	1	Pieces		171.75
P 5C5807417ADGRU	REAR BUMPER Use Predecessor 5C5807417AEG	1	Pieces		1,689.63
P 5C5809843	LHR FENDER - Section	1	Pieces		991.70
P 5C5810969D	WHEEL HOUSING LINNING LHS Predecessor 5C5810969C	1	Pieces		310.57
P 5C5821305C	FENDER LHS Predecessor 5C5821305B	1	Pieces		972.24
P 5C5837379	LHS CHROME MOLDING	1	Pieces		176.47
P 5C5839379	LHR MOLDING	1	Pieces		176.47
P 5C5854931R GRU	STRIP LHR Use Predecessor 5C5854931P GR	1	Pieces		163.56

5C5821305A Foil

48.19

Sum carried forward

21,640.62

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

KHOO SWEE YIN
(QIU RUIYIN)
124B BUKIT MERAH VIEW
#06-394
Singapore, 152124
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV036746
Quote No. SER/QUO/1801793
QuoteDate 26/10/18
Salesperson Ian Yeo
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Beetle NF 1.2 (A) SR HID	9,822	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKK7977Y	WVWZZZ16ZGM608799	30/05/17	Ian Yeo
Engine Code	Labor Type	Engine No.	Model Code
	M5	CBZ K15341	5C13D7

Continued			21,640.62
P 5C5854939P GRU	LHS STRIP	1 Pieces	? 285.48
	Use Predecessor 5C5854939L GR		
P D 007600A1	INOXSPRAY	1 Pieces	67.97
P D 180003M2	2KADHESIV	1 Pieces	286.20
P D 476KD1M2	SEALANT	1 Pieces	77.38
P D 506KD1A3	2K FOAM	1 Pieces	157.96
	Sum Item		7,435.61

Sum Labor	15,080.00
Sum Item	7,435.61
Total SGD	22,515.61
7% GST	22,515.61 1,576.09
Total SGD Incl. GST	24,091.70

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No..: