LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd 7 Temasek Boulevard 51 Ubi Ave 1 #01-25 #10-01 Suntec Tower One Singapore 038987 Paya Ubi Industrial Park Singapore 408933

Attn: Janice Goh Date: 23 Nov 2018

Preliminary Advice

Vehicle No : SLK3193G Accident Date : 23/10/2018

Make : OPEL ASTRA ST Policy No. : MPC18A00048900

Assignment Date : 26/10/2018 Excess : \$\$500.00 Date of Inspection : 29/10/2018 Est. Duration of Repair : 6 days

Inspection At : 1st Autoworks Pte Ltd (HQ)

23 Kaki Bukit Ave 4, #04-01

Singapore 415933

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 22,312.05 (INCLUSIVE SUPPLEMENTARY)
Revised Amount :S\$ 10,855.60 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated) :S\$ 4,789.50

Check Items (Estimated) :\$\$ 4,789.50

Total :\$\$ 15,645.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$
 78,000.00

 COE / PARF Rebate
 :S\$
 45,752.00

Salvage Value :S\$

Margin for Repair :S\$ 32,248.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

-) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 304.00