

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SLK3193G	Accident Date	: 23/10/2018
Make	: OPEL ASTRA ST	Policy No.	: MPC18A00048900
Assignment Date	: 26/10/2018	Excess	: S\$0.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 6 days
Inspection At	: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,008.05
Revised Amount	:S\$	10,551.60
Check Items (Estimated)	:S\$	4,789.50
Total	:S\$	15,341.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	45,752.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,248.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :