

REPAIR ESTIMATE*

MAKE :

China Taipei
DATE 25/10/2018 12:05

DATE 25/10/2018 12:05

L.R.K. - Kabinen

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Wheel Hub Cap (LH) <i>/ changed</i>			\$ 107.10
	Front Bumper x repair			
	Front Fender (LH) x repair			
	SUB TOTAL			\$ 107.10
	LESS 20%			\$ 21.42
	DISCOUNTED TOTAL			\$ 85.68
	Front Door Comfort Logo (LH) <i>/ acc</i>			\$ 75.00
	Rear Door Comfort delgro & Apps Sticker (LH) <i>/ acc</i>			\$ 80.00
				\$ 155.00
	Labour Charge			
	Panel Beating			\$ 400.00 <i>200</i>
	Spray Painting Charge			\$ 1,300.00 <i>1000</i>
	Tuff Kote			\$ 50.00 <i>X 2</i>
	FRT Wheel Alignment			\$ 80.00 <i>X 2</i>
	TOTAL LABOUR			\$ 1,830.00
	ESTIMATE TOTAL			\$ 2,070.68
	Ka / wh 16/11/18 N 25/10/18 1505 hr 2 Days P/P After Repair photo			
	LKK Auto Consultants hence notify the Reparer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Reparer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.