



PDI TUAS

PDI TUAS

ONG THIAM HUAT, STEPHEN
2 JALAN TIGA RATUS
#01-20
Singapore, 488067
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037392
Quote No. SER/QUO/1801804
QuoteDate 26/10/18
Salesperson Steve Hung
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Tiguan NF 1.4 TSI CL110 D6EQP	17,334	
License No.	VIN	Initial Registration	Sales Advisor
SLP199J	WVGZZZ5NZHW909006	26/05/17	Steve Hung
Engine Code	Labor Type	Engine No.	Model Code
	1H	CZE 434617	AD13PY

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	4	UNIT		840.00
P B&P MACP LABOUR	R&R REAR SILENCER	1	UNIT		420.00
P B&P MACP PAINT	SPRAY PAINT	3	UNIT		800.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				7,360.00
P 1K0253141S	CLAMP	1	Pieces		124.41
P 3G0854719	NUT	4	Pieces		5.28
P 3Q0919133 9B9	SENSOR O-RING	1	Pieces		1.64
P 3Q0919275 GRU	SENSOR	1	Pieces		202.91
P 5NA253609Q	SILENCER	1	Pieces		1,072.99
P 5NA807305A	REINFORCEMENT	1	Pieces		433.75
P 5NA807393	BUMPER SIDE BRACKET LH	1	Pieces		38.68
P 5NA807393A	TAILLIGHT LOWER BRACKET LH	1	Pieces		38.68
P 5NA807394	BUMPER SIDE BRACKET RH	1	Pieces		38.68
P 5NA807394A	TAILLIGHT LOWER BRACKET RH	1	Pieces		38.68
P 5NA807421 GRU	REAR BUMPER (UPPER)	1	Pieces		1,091.07
P 5NA807521 9B9	REAR BUMPER SPOILER	1	Pieces		183.45
P 5NA807863	BUMPER CENTRE BRACKET	1	Pieces		61.26
P 5NA919491	SENSOR BRACKET	1	Pieces		18.33
P 5NA919491A	SENSOR BRACKET	1	Pieces		18.33
P 5NA919492	SENSOR BRACKET	1	Pieces		18.33
P 5NA919492A	SENSOR BRACKET	1	Pieces		18.33

Sum carried forward

10,764.80

Payments to:

- BBN: - Acc.-No.:



PDI TUAS

PDI TUAS

ONG THIAM HUAT, STEPHEN
2 JALAN TIGA RATUS
#01-20
Singapore, 488067
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037392
Quote No. SER/QUO/1801804
QuoteDate 26/10/18
Salesperson Steve Hung
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Tiguan NF 1.4 TSI CL110 D6EQP	17,334	
License No.	VIN	Initial Registration	Sales Advisor
SLP199J	WVGZZZ5NZHW909006	26/05/17	Steve Hung
Engine Code	Labor Type	Engine No.	Model Code
	1H	CZE 434617	AD13PY

		Continued	10,764.80
P 5NA945103	LHS REFLECTOR OUTER	1 Pieces	78.22
P 5NA945105A	LHS REFLECTOR INNER	1 Pieces	78.22
P D 180KU2A1	2KADHESIVE	1 Pieces	89.84
P D 822150A1	BONDAGENT	1 Pieces	64.27
P WHT005348	RIVET	6 Pieces	6.84
	Sum Item		3,722.19

Sum Labor	7,360.00
Sum Item	3,722.19

Total SGD	11,082.19
7% GST	11,082.19 775.75
Total SGD Incl. GST	11,857.94

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resme
Hp 90010068
3-4 days
29/10/18 @ 1555hrs
Resmy 64 part

Payments to: - BBN: - Acc.-No..: