FASTECT AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Not Authorist

LICH

1/5 9 / 7,000/c

6 41.

VEHICLE NO: SCG	B88A Date:	
QTY	DADTICULAD	
1 PCS	FRONT BUMPER 2932.60	913 \$3,888.12 -
1 PCS	FRONT BUMPER SIDE HOLDER N/S	3ey \$85.10
1 SET	FRONT BUMPER CLIPS	rec \$60.00
1 PCS	FRONT BUMPER PDC SENSOR N/S	17 \$217.80 X
1 PCS	FRONT BUMPER FOG LAMP COVER N/S 369.60	cu 7 \$399.50
1 PCS	FRONT BUMPER REINFORCEMENT	11 \$957.00 ~
1 PCS	BONNET LIFI 4:30	2/3uc \$6,814.00
1 PCS	BONNET LOCK	117 \$202.40 X
1 PCS	FRONT FENDER N/S	30 Jypo \$1,266.30
1 PCS	FRONT FENDER INNER SHIELD N/S 392.00	Zo-A \$488.20
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S	, ju \$60.00
1 PCS	FRONT FENDER INNER FRAME BRACKET N/S 1660-00	serfline \$1,882.50
1 PCS	FRONT GRILLE 1661.00	(\$1,950.00
1 PCS	FRONT SUPPORT PANEL 98/-20	(N \$981.00
1 PCS	HEADLAMP N/S 3546.40	3/13 \$6,800.00
1 PCS	HEADLAMP LOWER BRACKET N/S /5'	(M. 3245.50
1 PCS	INTER COOLER	\$9/2/ \$1,010.00
1 PCS	FRONT SPORT RIM N/S 19 INCH	2,200.00 ×
1 PCS	FRONT SHOCK ABSORBER NS/	17 \$991.00 X
1 PCS	FRONT KNUCKLE ARM N/S	11 \$1,450.00
1 PCS	FRONT KNUCKLE ARM BEARING N/S 545	Dye \$620.00
1 PCS	FRONT DOOR N/S	1 \$3,899.00 ≥
		\$36,467.42
	LABOUR CHRAGES:	
	TO CHECK WIRING	\$80.00 20
	TO DISMANTLE & REFIX PDC SENSOR	\$80.00
	TO REFILL AIR CON GAS	\$150.00 (12.2)
	TO CONDUCT WHEEL ALIGNMENT	\$150.00
	TO DISMANTLE & REPALCING FRONT UNDERCARRIAGE	\$380.00 /20
	TO SPRAY RUSF PROOFING	11 \$150.00 ×
	TO MOUNT VEHICLE ON CAR O-LINER	11 \$380.00 ☆
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00 /000
	TO PUTTY & SPRAY PAINTING	\$1,800.00 900
	H	TOTAL \$41,437.42

1951-17 1951-17 1951-17