

# **FASTECH AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 /

Tax Reg No : 20-0006262-D

*Not Authorized*  
*date*

*29/10/18*  
*1/55 6600*  
*6dy.*

Qty Particular **GBH5087B** Amount S\$

## List Item :

- 1 pc Rear boot
- 1 pc Rear boot logo
- 1 pc Rear boot outer handle
- 1 pc Rear boot inner lock
- 1 pc Rear boot lock stricker
- 1 pc Rear boot sticker ( hiace )
- 1 pc Rear boot inner trim board
- 1 set Rear boot inner trim board clips
- 1 pc Rear boot weatherstrip
- 1 pc Rear window inner seal
- 1 pc Rear boot sticker ( toyota )
- 2 pc Rear tail lamp @ 352.30
- 2 pc Rear tail lamp garnish @ 109.50
- 2 pc Rear tail lamp hoousing panel @ 349.10
- 1 pc Rear bumper
- 1 pc Rear air vent nls
- 4 pc Rear bumper lower support brackets @ 56.20
- 1 set Rear bumper clips
- 1 pc Rear end panel inner
- 1 pc Rear end panel outer
- 1 pc Rear end panel top steel plate
- 1 pc Rear fender nls
- 1 pc Rear spare tyre bracket
- 1 pc Rear exhaust

List Item Total :

|              |    |           |            |
|--------------|----|-----------|------------|
| <i>body</i>  | \$ | 2,150.10  | <i>—</i>   |
| <i>ner</i>   | \$ | 48.60     | <i>—</i>   |
| <i>11</i>    | \$ | 241.10    | <i>X</i>   |
| <i>20/5m</i> | \$ | 395.60    | <i>—</i>   |
| <i>11</i>    | \$ | 40.10     | <i>X</i>   |
| <i>ner</i>   | \$ | 60.35     | <i>—</i>   |
| <i>to 11</i> | \$ | 288.30    | <i>—</i>   |
| <i>ner</i>   | \$ | 45.00     | <i>—</i>   |
| <i>ner</i>   | \$ | 292.30    | <i>—</i>   |
| <i>ner</i>   | \$ | 45.00     | <i>—</i>   |
| <i>ner</i>   | \$ | 35.20     | <i>—</i>   |
| <i>nls</i>   | \$ | 704.60    | <i>12C</i> |
| <i>nls</i>   | \$ | 219.00    | <i>12C</i> |
| <i>nls</i>   | \$ | 698.20    | <i>12C</i> |
| <i>205</i>   | \$ | 596.20    | <i>—</i>   |
| <i>215</i>   | \$ | 165.40    | <i>—</i>   |
| <i>ner</i>   | \$ | 224.80    | <i>—</i>   |
| <i>ner</i>   | \$ | 50.00     | <i>—</i>   |
| <i>ner</i>   | \$ | 850.00    | <i>—</i>   |
| <i>ner</i>   | \$ | 486.50    | <i>—</i>   |
| <i>11</i>    | \$ | 228.10    | <i>X</i>   |
| <i>11</i>    | \$ | 1,452.20  | <i>X</i>   |
| <i>ner</i>   | \$ | 263.10    | <i>—</i>   |
| <i>ner</i>   | \$ | 971.00    | <i>X</i>   |
|              | \$ | 10,550.75 |            |

*(25%)*

*6807.35*

## Special Nett Item :

- 8pax sticker
- 70 km/h sticker
- 1250 sticker
- Rear windscreen sealant
- Reverse sensor *1 set*
- Rear end panel sealant
- Rear reverse camera
- Rear floor panel insulator

|             |    |          |            |
|-------------|----|----------|------------|
| <i>ner</i>  | \$ | 20.00    | <i>—</i>   |
| <i>ner</i>  | \$ | 20.00    | <i>—</i>   |
| <i>ner</i>  | \$ | 20.00    | <i>X</i>   |
| <i>ner</i>  | \$ | 50.00    | <i>40</i>  |
| <i>shut</i> | \$ | 280.00   | <i>200</i> |
| <i>ner</i>  | \$ | 50.00    | <i>—</i>   |
| <i>shut</i> | \$ | 500.00   | <i>300</i> |
| <i>11</i>   | \$ | 200.00   | <i>X</i>   |
|             | \$ | 1,140.00 |            |

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 /

Tax Reg No : 20-0006262-D

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| Qty                    | Particular                             | Policy No : | Amount S\$       |
|------------------------|----------------------------------------|-------------|------------------|
| <b>Labour Charge :</b> |                                        |             |                  |
|                        | Remove and replace rear windscreen     |             | \$ 150.00 120    |
|                        | Remove and replace rear reverse sensor |             | \$ 80.00 50      |
|                        | To check wiring                        |             | \$ 50.00 30      |
|                        | To spray rust proofing                 |             | \$ 120.00 80     |
|                        | Remove and replace tailgate mechanism  |             | \$ 100.00 60     |
|                        | Labour for panel beating               |             | \$ 1,500.00 1200 |
|                        | To putty & spray painting              |             | \$ 1,500.00 1000 |
|                        | Labour charge total :                  |             | \$ 3,500.00      |

P225.51  
6620

E (Total Amount : \$ 15,190.75

FASTECH AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: