

ASS. REC. BY:

REF:

CS/CTI/18019705/Ng d3b

Special Instruction:

Survivor

menmen

NA2

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time: 30/10/2018 @ 10.09 am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBH 752Y

Insured:

at Workshop m/s

Sin Yew Hup

Tel:

67600819

of

Blk D4 Woodlands Rd 393M, Yew Tee Ind.

Policy No:

DMCVSN1801101800

Claim No:

SNM18D05053C01

Sum Insured:

Excess:

\$350.00

Make of Veh:

(Client's Record)

D.O.A.

22/10/2018

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1013am @ 30/10/18

Person Contacted:

Edwin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 752Y - CS/CTI/18019404/G/d3
1/11 -	Report via menmen
02/11/18 @ 8.45am	Afred informed via 3 ex: \$350 via menmen.
05/11/18 @ 9.26am	Informed Edwin via 3 ex: \$350 by email.

REF:

CTI

Assignment: NA2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$350.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 65K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBH 752Y Yr Regn: 28 DGC 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV200 C.C. 1,461

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 8,664 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM 2020149550

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14 C

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 22/10/18 U.O.I. 30/10/18

Survey held at S.W. YEW HUP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COE rebate \$42,919
	MV 165,000
	Single 3 Repairs \$22,051.00
21/1/19	FINALIZED PART BY PART REPAIR \$6365.00 / 4 DAY
	(Per \$640, 7%)
RECEIVED 25 JAN 2019	

Date/Time, File Pass to? ☐ : Preli. Report

1) 25/1/19 ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: MER-01

Lump Sum / I.B.I: (\$ 6365)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee: 220

Transportation: _____

\$ + RS. _____

Photos: _____

Others: _____

Weekend (\$ _____)

TOTAL 220

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	29 Oct 2018 Sendback Est	29 Oct 2018 09:27 S\$5,172.00	30 Oct 2018 10:09 Assign			
						New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	SENG LEONG STEEL (ENT) PTE LTD, Co. Reg. No.: 200617184M			
Vehicle Reg. No.:	GBH752Y	Date of Loss:	22/10/2018 22:00 - :59 [9 Months and 24 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / SNM18D05053C01	Policy/Cover Note No.:	DMCVSN1801101800 (Comprehensive)	
		Excess:	S\$350.00	
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/11/2018]			
Driver/Custodian:	WONG JING WEN (24 / Female), NRIC: S9427412E, Tel: +6596546780			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	29 Oct 2018 09:19	Clim Veh Model Changed	(202059) NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A).		[R] Edwin Yap Kiat Beng
2	29 Oct 2018 09:19	Clim Created	Reg No: GBH752Y, Policy No: DMCVSN1801101800, Acct Date: 2018/10/22, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd, (HQ). Workshop: Sin Yew Hup Auto Pte Ltd (HQ). Created from SAS:MSYH18137878		[R] Edwin Yap Kiat Beng
3	29 Oct 2018 09:27	Clim Submitted	5172.00.		[R] Edwin Yap Kiat Beng
4	30 Oct 2018 10:09	Clim Registration Modified	Excess: -> 350.00.		[I] Catherine Thia
5	30 Oct 2018 10:09	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[I] Catherine Thia
6	30 Oct 2018 10:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/09		[I] Catherine Thia
7	30 Oct 2018 10:09	Adj Mandate Set	Approved:0.00.		[I] Catherine Thia
8	30 Oct 2018 10:11	Assignment 1st Accessed			[A] Nivitha Govindasamy
9	30 Oct 2018 12:07	Adj Adjuster Assigned	[None] -> Muhammad Nazril Bin Abdullah		[A] Nivitha Govindasamy
10	01 Nov 2018 16:51	Adj Rpt Initiated			[A] DENISE TAY KWEE CHENG
11	01 Nov 2018 16:53	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/09		[A] DENISE TAY KWEE CHENG
12	01 Nov 2018 16:56	Adj Mandate Request	Cur.Req:4550.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL		[A] DENISE TAY KWEE CHENG
13	02 Nov 2018 08:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/09. Mandate Remarks: Please proceed to authorize repairs UP TO \$4,550.00 before Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED.		[I] Alfred Toh
14	02 Nov 2018 08:47	Adj Mandate Set	Approved:4550.00:Please proceed to authorize repairs UP TO \$4,550.00 before Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED.Reinsp:Adj decides.		[I] Alfred Toh
15	12 Nov 2018 12:22	Clim Supp Created (S:761390)			[R] Edwin Yap Kiat Beng
16	12 Nov 2018 12:23	Clim Submitted (S:761390)	1420.00.		[R] Edwin Yap Kiat Beng
17	12 Nov 2018 12:23	Adj Co Assigned (S:761390)	LKK Auto Consultants Pte Ltd (HQ):		[R] Merimen Administrator
18	13 Nov 2018 09:08	Supp Combined (S:761390)			[A] SHIAU CHAN
19	03 Dec 2018 11:59	Clim Supp Created (S:768385)			[R] Edwin Yap Kiat Beng
20	03 Dec 2018 12:00	Clim Submitted (S:768385)	35.00.		[R] Edwin Yap Kiat Beng
21	03 Dec 2018 12:00	Adj Co Assigned (S:768385)	LKK Auto Consultants Pte Ltd (HQ):		[R] Merimen Administrator
22	03 Dec 2018 16:13	Supp Combined (S:768385)			[A] SHIAU CHAN
23	23 Jan 2019 11:32	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/09		[A] SHIAU CHAN
24	23 Jan 2019 11:32	Adj Mandate Request	Cur.Req:6365.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.		[A] SHIAU CHAN
25	25 Jan 2019 09:27	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/11/09. Mandate Remarks: Please proceed to authorize repairs UP TO \$4,550.00 before Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED. . PLS REFER TO APPROVALMANDATE \$6365		[I] Chong Boon Sen
26	25 Jan 2019 09:27	Adj Mandate Set	Approved:6365.00:Please proceed to authorize repairs UP TO \$4,550.00 before Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED. . PLS REFER TO APPROVALMANDATE \$6365		[I] Chong Boon Sen

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1958379	29/10/2018 09:19	Motor	Sin Yew Hup Auto Pte Ltd	Sin Yew Hup Auto Pte Ltd	GBH752Y		xx.xx

				(HQ)			
1963854	01/11/2018 16:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBH752Y		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 23 Jan 2019

Preliminary Advice

Vehicle No	: GBH752Y	Accident Date	: 22/10/2018
Make	: NISSAN NV200	Policy No.	: DMCVSN1801101800
Assignment Date	: 30/10/2018	Excess	: S\$350.00
Date of Inspection	: 31/10/2018	Est. Duration of Repair	: 5.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,005.00	(ESTIMATE \$5,550.00 + SUPP 1 \$1,420.00 + SUPP 2 \$35.00)
Revised Amount	:S\$	6,365.00	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	6,365.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	42,919.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,081.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 5 November 2018 9:26 AM
To: sinyewhup@gmail.com
Cc: SUR
Subject: VEHICLE GBH 752Y (DOA: 22/10/2018)

Dear Edwin,

As instructed by our client , please proceed to repair the insured vehicle GBH 752Y on part by part basis (Excess \$350/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	29 Oct 2018 09:19	Cim Veh Model Changed	(202059) NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A).	[R] Edwin Yap Kiat Beng
2	29 Oct 2018 09:19	Cim Created	Reg No: GBH752Y, Policy No: DMCVSN1801101800, Acct Date: 2018/10/22. Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Sin Yew Hup Auto Pte Ltd (HQ), Created from SAS:MSYH18137878	[R] Edwin Yap Kiat Beng
3	29 Oct 2018 09:27	Cim Submitted	5172.00.	[R] Edwin Yap Kiat Beng
4	30 Oct 2018 10:09	Cim Registration Modified	Excess: -> 350.00.	[I] Catherine Thia
5	30 Oct 2018 10:09	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Catherine Thia
6	30 Oct 2018 10:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/09	[I] Catherine Thia
7	30 Oct 2018 10:09	Adj Mandate Set	Approved:0.00.	[I] Catherine Thia
8	30 Oct 2018 10:11	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	30 Oct 2018 12:07	Adj Adjuster Assigned	[None] -> Muhammad Nazril Bin Abdullah	[A] Nivitha Govindasamy
10	01 Nov 2018 16:51	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	01 Nov 2018 16:53	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/09	[A] DENISE TAY KWEE CHENG
12	01 Nov 2018 16:56	Adj Mandate Request	Cur.Req:4550.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
13	02 Nov 2018 08:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/09. Mandate Remarks: Please proceed to authorize repairs UP TO \$4,550.00 before Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED.	[I] Alfred Toh
14	02 Nov 2018 08:47	Adj Mandate Set	Approved:4550.00:Please proceed to authorize repairs UP TO \$4,550.00 before Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED.Reinsp:Adj decides.	[I] Alfred Toh

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1958379	29/10/2018 09:19	Motor	Sin Yew Hup Auto Pte Ltd	Sin Yew Hup Auto Pte Ltd (HQ)	GBH752Y		xx.xx
1963854	01/11/2018 16:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBH752Y		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 01 Nov 2018

Preliminary Advice

Vehicle No	: GBH752Y	Accident Date	: 22/10/2018
Make	: NISSAN NV200	Policy No.	: DMCVSN1801101800
Assignment Date	: 30/10/2018	Excess	: S\$350.00
Date of Inspection	: 31/10/2018	Est. Duration of Repair	: 5.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,172.00
Revised Amount	:S\$	2,055.00
Check Items (Estimated)	:S\$	2,495.00
Total	:S\$	4,550.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	42,919.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,081.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7184M

Vehicle Details

Vehicle No.: GBH752Y

Vehicle to be Exported: No

Intended Deregistration Date: 01 Nov 2018

Vehicle Make: NISSAN

Vehicle Model: NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Primary Colour: White

Manufacturing Year: 2017

Engine No.: K9KC400D057758

Chassis No.: VSKYBAM20Z0149550

Maximum Power Output: -

Open Market Value: \$20,119.00

Original Registration Date: 28 Dec 2017

First Registration Date: 28 Dec 2017

Transfer Count: 1

Actual ARF Paid: \$1,006.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Dec 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$46,890.00

COE Rebate Amount: \$42,919.00

Total Rebate Amount: \$42,919.00

The information contained herein is correct as at 01 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 19:10
Date Of Accident	22/10/2018 22:40
Exact Location Of Accident	ULU PANDAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH752Y
Insured/Policyholder	
Name Of Registered Owner	SENG LEONG STEEL (ENT) PTE LTD
Co Reg No	200617184M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65666639

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200-1.5 D MT ABS AIRBAG 2WD 6DR (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1801101800
Cover Note Number	

Driver

Name of Driver	WONG JING WEN
NRIC No	S9427412E
Date Of Birth	27/04/1994
Occupation	OUTDOOR
Date Of Driving Pass	08/02/2014
Driving Experience	4 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96546780
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 547 CHOA CHU KANG ST 52 #04-19
Postcode	680547
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE HONG ZHEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR9790G
Vehicle Make/Model/Colour	HONDA GRACE / WHITE
Details Of Properties	REAR
Vehicle Category	PRIVATE CAR
Name of Driver	NOR EKHSAN BIN HOSNI
NRIC/Passport Number	
Contact Number	87678730
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


most left lane of
 Was driving along Ulu Pandan road, car 'B' had to emergency stop due to
 taxi in front sudden stop without signalling to left to turn into T-junction
 of pinegrove towards Clementi road, ~~car~~ step jam brake but car cannot
 stop in time. bang into car 'B'.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200206384E

HS309/C

H SH

A00033A

Cov. Type: C

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

PLM 307389

ORIGINAL

CERTIFICATE No.

DEK75N1801191892

Engine No. : E3ED4000057759

Chassis No. : VSEYRANGC00349592

1. Index Mark and Registration
Number of Vehicle

GRH752V

2. Name of Policy Holder

SING LONG STEEL (MKT) PTE LTD

3. Effective date of the Commencement of
insurance for the purposes of the Regulations,
Ordinance or Enactment

04 January 2019

Excess Seat 1 S\$350.00

EX ON WINDSCREEN S\$150.00

4. Date of Expiry of Insurance

03 January 2019

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or
regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a
Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

(1) Use in connection with the Policyholder's business.

(2) Use for the carriage of passengers (other than for hire or reward) in connection with the
Policyholder's business.

(3) Use for social, domestic or pleasure purposes.

The Policy does not cover.

(1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : UNITED OVERSEAS BANK LIMITED AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the
provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road
Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

Authorised Officer

Authorised Signatory



Dear All,

Mr. Lim called me and wants to finalize these cases. He said he was unable to reach our surveyors.

CYS email address is cysauto@singnet.com.sg

Please finalise and acknowledge once done.

Thanks.

TP Veh No.	DOA	LKK REF	Surveyor	Handler
SKU 7371S	22/03/2018	CC4/ASM18005621/M1wa3	Ma (Simon / Lim TG)	Vivian
SJD 2414L	25/07/2018	CC4/ASM18020249/Npa3	Naz	HT - parking photo
SLS 4732C	21/08/2018	CC4/AIG18015396/Nhb3	Naz	Vic - parking photo
GBA 6170Z	13/09/2018	CS/FCI18017073/T1td3	Taufikh	Denise - parking photo

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./GST Regn. No. 2009210750

Specialise in Insurance Claims and General Motor Repair Work

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN1801101800	Date of Loss:	22/10/2018
Vehicle Reg. No.:	GBH752Y	Driveable?	
Driver Age/Info:	24 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SENG LEONG STEEL (ENT) PTE LTD		
Driver:	WONG JING WEN		
Make/Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Vehicle Reg. Date:	28/12/2017
Vehicle Colour:	WHITE		
Engine No:	K9KC400D057758	Chassis No:	VSKYBAM20Z0149550
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	3,522.00
Miscellaneous Items	0.00
Labour	1,650.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,172.00
+ GST 7.00% (S\$)	362.04
Nett Amount (S\$)	5,534.04

This claim is handled by: **EDWIN YAP KIAT BENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Oct 2018)

Parts: N/A NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/GBH752Y/29/10/2018 09:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	4200 *42.00 F ✓
2	1		*BONNET LOCK	0.00	0.00	*55.00 F ✓
3	2		*BONNET HINGE	0.00	0.00	*100.00 F XSV ✓
4	2		*HEADLAMP	0.00	0.00	*520.00 F ✓
5	1		*FRONT GRILLE	0.00	0.00	*275.00 F ? ✓
6	8		*FRONT GRILLE CLIP	0.00	0.00	*40.00 F ? ✓
7	1		*FRONT GRILLE LOGO EMBLEM	0.00	0.00	*50.00 F ✓
8	1		*FRONT BUMPER	0.00	0.00	*330.00 F ✓
9	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*320.00 F ✓
10	2		*FRONT BUMPER TOP SIDE GARNISH	0.00	0.00	*340.00 F ? ✓
11	1		*FRONT SUPPORT PANEL	0.00	0.00	*500.00 F ✓
12	1		*AIRCON CONDENSER	0.00	0.00	*460.00 F ? ✓
13	1		*RADIATOR	0.00	0.00	420 *460.00 F ? ✓
14	1		*FRONT NUMBER PLATE	0.00	0.00	*30.00 F ✓

F=Franchise part.

(include frame)

Total Parts (S\$)

3,760

3,522.00

Sin Yew Hup Auto Pte Ltd/GBH752Y/29/10/2018 09:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE ALL DAMAGED PARTS, CUT/WELD FRONT SUPPORT PANEL, PANEL BEAT / STRAIGHTEN ALL DENTS, CHECK, ADJUST, REPLACE AND RE-ALIGN THE ABOVE PARTS	New	600 800.00
2	TO PUTTY AND SPRAY PAINT BONNET IN & OUT, FRONT BUMPER SIDE GARNISH *2, FRONT SUPPORT PANEL, FRONT FENDER *2 AND ALL AFFECTED PORTIONS	New	500 750.00
3	TO REMOVE AND REPLACE AIRCON CONDENSER AND REFILL GAS	New	SD 100.00?
Gross Labour Cost (S\$)			1150 1,650.00

Sin Yew Hup Auto Pte Ltd/GBH752Y/29/10/2018 09:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKIC

30/10/18 1030

P/P

3-5 days.

- check item photos

- before paint photos.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8480 9158

NAZ @ lkkan to. com



Co./OST Regn. No. 2009210750

新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN1801101800	Date of Loss:	22/10/2018
Vehicle Reg. No.:	GBH752Y	Driveable?	
Driver Age/Info:	24 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SENG LEONG STEEL (ENT) PTE LTD		
Driver:	WONG JING WEN		
Make/Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Vehicle Reg. Date:	28/12/2017
Vehicle Colour:	WHITE		
Engine No:	K9KC400D057758	Chassis No:	VSKYBAM20Z0149550
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,420.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,420.00
+ GST 7.00% (\$\$)	99.40
Nett Amount (\$\$)	1,519.40
+ Previous Estimates (\$\$)	5,534.04
Claim Total (\$\$)	7,053.44

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 12 Nov 2018)**Parts:** N/A NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sin Yew Hup Auto Pte Ltd/GBH752Y/12/11/2018 12:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR DUCT	0.00	0.00	*145.00 F
2	1		*FRONT BUMPER SPONGE	0.00	0.00	*175.00 F
3	1		*INTERCOOLER	0.00	0.00	*1,100.00 F
Total Parts (S\$)						1,420.00

F=Franchise part.

Sin Yew Hup Auto Pte Ltd/GBH752Y/12/11/2018 12:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sin Yew Hup Auto Pte Ltd/GBH752Y/12/11/2018 12:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN1801101800	Date of Loss:	22/10/2018
Vehicle Reg. No.:	GBH752Y	Driveable?	
Driver Age/Info:	24 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SENG LEONG STEEL (ENT) PTE LTD		
Driver:	WONG JING WEN		
Make/Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Vehicle Reg. Date:	28/12/2017
Vehicle Colour:	WHITE		
Engine No:	K9KC400D057758	Chassis No:	VSKYBAM20Z0149550
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	35.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	35.00
+ GST 7.00% (S\$)	2.45
Nett Amount (S\$)	37.45
+ Previous Estimates (S\$)	7,053.44
Claim Total (S\$)	7,090.89

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 03 Dec 2018)**Parts:** N/A NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sin Yew Hup Auto Pte Ltd/GBH752Y/03/12/2018 12:00**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR GUIDE LOWER RH	0.00	0.00	*35.00 F
Total Parts (S\$)						35.00

F=Franchise part.

Sin Yew Hup Auto Pte Ltd/GBH752Y/03/12/2018 12:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sin Yew Hup Auto Pte Ltd/GBH752Y/03/12/2018 12:00. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

PARTS	\$3,760
SUPPLEMENTARY	\$1,455
	<u>\$5,215</u>
LABOUR	\$ 650
SPRAY	\$ 500
TOTAL	<u>\$6365.00 / 4 DAYS</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018 Sendback Est	29 Oct 2018 09:27 \$55,172.00	30 Oct 2018 10:09 Edit Adj Rpt	\$56,365.00 Edit Estimates	\$56,365.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	12 Nov 2018 12:22	12 Nov 2018 12:23 \$51,420.00	12 Nov 2018 12:23			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	03 Dec 2018 11:59	03 Dec 2018 12:00 \$535.00	03 Dec 2018 12:00			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SENG LEONG STEEL (ENT) PTE LTD , Co. Reg. No.: 200617184M									
Vehicle Reg. No.: GBH752Y		Date of Loss: 22/10/2018 22:00 - :59 [9 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D05053C01		Policy/Cover Note No.: DMCVSN1801101800 (Comprehensive)							
		Excess: \$5350.00							
Reparer: Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 09/11/2018]									
Driver/Custodian: WONG JING WEN (24 / Female), NRIC: S9427412E, Tel: +6596546780									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (25/01/2019): Alert - Adj Mandate Approved (\$56365.00) - GBH752Y - Claim Handler: Catherine Th... - CHINA_TAIPING (02/11/2018): Alert - Adj Mandate Approved (\$54550.00) - GBH752Y - Claim Handler: Catherine Th...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBH752Y (SNM18D05053C01)
 OD
 Oct 22 2018 10:00PM
 [SENG LEONG STEEL (ENT) PTE LTD]
 Sin Yew Hup Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print	
1	29/10/18 09:27	Repairer Estimates	 Load HTM		
2	12/11/18 12:23	Repairer Estimates Suppl. #1	 Load HTM		
3	03/12/18 12:00	Repairer Estimates Suppl. #2	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	01/11/18 16:53	Adjuster Immediate Advice	 Load HTM		
2	23/01/19 11:32	Adjuster Immediate Advice	 Load HTM		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	30/10/18 17:53	General View	 Load JPG	☒	
2	30/10/18 17:53	General View	 Load JPG	☒	
3	30/10/18 17:53	General View	 Load JPG	☒	
4	30/10/18 17:53	General View	 Load JPG	☒	
5	30/10/18 17:53	General View	 Load JPG	☒	
6	30/10/18 17:53	General View	 Load JPG	☒	
7	30/10/18 17:53	General View	 Load JPG	☒	
8	30/10/18 17:53	General View	 Load JPG	☒	
9	30/10/18 17:53	General View	 Load JPG	☒	
10	30/10/18 17:53	General View	 Load JPG	☒	
11	30/10/18 17:53	General View	 Load JPG	☒	
12	30/10/18 17:53	General View	 Load JPG	☒	
13	30/10/18 17:53	General View	 Load JPG	☒	
14	30/10/18 17:53	General View	 Load JPG	☒	
15	30/10/18 17:53	General View	 Load JPG	☒	
16	30/10/18 17:53	General View	 Load JPG	☒	
17	30/10/18 17:53	General View	 Load JPG	☒	
18	30/10/18 17:53	General View	 Load JPG	☒	
19	30/10/18 17:53	General View	 Load JPG	☒	
20	30/10/18 17:53	General View	 Load JPG	☒	
21	30/10/18 17:53	General View	 Load JPG	☒	
22	30/10/18 17:53	General View	 Load JPG	☒	
23	30/10/18 17:53	General View	 Load JPG	☒	
24	30/10/18 17:53	General View	 Load JPG	☒	
25	30/10/18 17:53	General View	 Load JPG	☒	
26	30/10/18 17:53	General View	 Load JPG	☒	
27	30/10/18 17:53	General View	 Load JPG	☒	
28	30/10/18 17:53	General View	 Load JPG	☒	
29	30/10/18 17:53	General View	 Load JPG	☒	
30	21/01/19 16:48	Dismantled Parts	 Load JPG	☒	
31	21/01/19 16:48	Dismantled Parts	 Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
32	21/01/19 16:48	Dismantled Parts		☒
33	21/01/19 16:48	Dismantled Parts		☒
34	21/01/19 16:48	Dismantled Parts		☒
35	21/01/19 16:48	Dismantled Parts		☒
36	21/01/19 16:48	Dismantled Parts		☒
37	21/01/19 16:48	Dismantled Parts		☒
38	21/01/19 16:48	Dismantled Parts		☒
39	21/01/19 16:48	Dismantled Parts		☒
40	21/01/19 16:48	Dismantled Parts		☒
41	21/01/19 16:48	Dismantled Parts		☒
42	21/01/19 16:48	Dismantled Parts		☒
43	21/01/19 16:48	Dismantled Parts		☒
44	21/01/19 16:48	Dismantled Parts		☒
45	21/01/19 16:48	Dismantled Parts		☒
46	21/01/19 16:48	Dismantled Parts		☒
47	21/01/19 16:48	Dismantled Parts		☒
48	21/01/19 16:48	Dismantled Parts		☒
49	21/01/19 16:48	Dismantled Parts		☒
50	21/01/19 16:48	Dismantled Parts		☒
51	21/01/19 16:48	Dismantled Parts		☒
52	21/01/19 16:48	Dismantled Parts		☒
53	21/01/19 16:48	Dismantled Parts		☒
54	21/01/19 16:48	Dismantled Parts		☒
55	21/01/19 16:48	Dismantled Parts		☒
56	21/01/19 16:48	Dismantled Parts		☒
57	21/01/19 16:48	Dismantled Parts		☒
58	21/01/19 16:48	Dismantled Parts		☒
59	21/01/19 16:48	Dismantled Parts		☒
60	21/01/19 16:48	Dismantled Parts		☒
61	21/01/19 16:48	Dismantled Parts		☒
62	21/01/19 16:48	Dismantled Parts		☒
63	21/01/19 16:48	Dismantled Parts		☒
64	21/01/19 16:48	Dismantled Parts		☒
65	21/01/19 16:48	Dismantled Parts		☒
66	21/01/19 16:48	Dismantled Parts		☒
67	21/01/19 16:48	Dismantled Parts		☒
68	21/01/19 16:48	Dismantled Parts		☒
69	21/01/19 16:48	Dismantled Parts		☒
70	21/01/19 16:48	Dismantled Parts		☒
71	21/01/19 16:48	Dismantled Parts		☒
72	21/01/19 16:48	Dismantled Parts		☒
73	21/01/19 16:48	Dismantled Parts		☒
74	21/01/19 16:48	Dismantled Parts		☒
75	21/01/19 16:48	Dismantled Parts		☒
76	21/01/19 16:48	Dismantled Parts		☒
77	21/01/19 16:48	Dismantled Parts		☒
78	21/01/19 16:48	Dismantled Parts		☒
79	21/01/19 16:48	Dismantled Parts		☒
80	21/01/19 16:48	Dismantled Parts		☒
81	21/01/19 16:48	Dismantled Parts		☒

Assessment Reports			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
82	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
83	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
84	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
85	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
86	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
87	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
88	21/01/19 16:48	Dismantled Parts	 Load JPG	☒
89	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
90	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
91	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
92	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
93	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
94	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
95	25/01/19 10:40	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/18 16:56	ESTIMATE	 Load PDF	
2	23/01/19 11:25	SUPPLEMENTARY LIST 1	 Load PDF	
3	23/01/19 11:25	SUPPLEMENTARY LIST 2	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 19:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 19:19	Accident Photo	 Load JPG	☒
2	23/10/18 19:19	Accident Photo	 Load JPG	☒
3	23/10/18 19:19	Accident Photo	 Load JPG	☒
4	23/10/18 19:19	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 19:17	Sketch Plan	 Load TIF	
2	23/10/18 19:17	Sketch Plan #2	 Load TIF	
3	23/10/18 19:17	Sketch Plan #3	 Load TIF	
4	23/10/18 19:17	Sketch Plan #4	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18019705/NQD3E2

Date: 28/01/2019

REFERENCE

Insured/Claimant:	SENG LEONG STEEL (ENT) PTE LTD	Policy No:	DMCVSN1801101800	Claim No:	SNM18D05053C01
Date of Loss:	22/10/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH752Y		Engine No:	K9KC400D057758
Make & Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)		Chassis No:	VSKYBAM20Z0149550
Reg. Date:	28/12/2017 (Man. Year: 2017)		Odometer:	8664 km
Colour:	White			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	S\$65,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,977.00	5,215.00	-238.00	-4.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,150.00	500.00	30.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,627.00	6,365.00	262.00	3.95
- Excess (S\$)	0.00	350.00	-350.00	
(S\$)	6,627.00	6,015.00	612.00	9.23
+ GST 7.00/7.00% (S\$)	463.89	421.05	42.84	9.23
Nett Amount (S\$)	7,090.89	6,436.05	654.84	9.23

INSPECTION

Date of Assignment:	30/10/2018 Present Location:	Sin Yew Hup Auto Pte Ltd (HQ)
Date Inspected:	30/10/2018 Inspected At:	Sin Yew Hup Auto Pte Ltd (HQ)
		Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate
		Singapore 677981
Estimated Period of Repair:	4.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2019)	
Parts:	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH752Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Deformed	42.00 F	*420.00 F
2	1		*BONNET LOCK	Deformed	55.00 F	*55.00 F
3	2		*BONNET HINGE	Serviceable	100.00 F	*. F
4	2		*HEADLAMP	Cracked	520.00 F	*520.00 F
5	1		*FRONT GRILLE	Cracked	275.00 F	*275.00 F
6	8		*FRONT GRILLE CLIP	Necessary	40.00 F	*40.00 F
7	1		*FRONT GRILLE LOGO EMBLEM	Missing	50.00 F	*50.00 F
8	1		*FRONT BUMPER	Cracked	330.00 F	*330.00 F
9	1		*FRONT BUMPER REINFORCEMENT	Bent	320.00 F	*320.00 F
10	2		*FRONT BUMPER TOP SIDE GARNISH	Cracked	340.00 F	*340.00 F
11	1		*FRONT SUPPORT PANEL	Bent	500.00 F	*500.00 F
12	1		*AIRCON CONDENSER	Deformed	460.00 F	*460.00 F
13	1		*RADIATOR	Deformed	460.00 F	*420.00 F
14	1		*FRONT NUMBER PLATE	Deformed	30.00 F	*30.00 F
Supplementary #1						
15	1		*AIR DUCT	Cracked	145.00 F	*145.00 F
16	1		*FRONT BUMPER SPONGE	Deformed	175.00 F	*175.00 F
17	1		*INTERCOOLER	Cracked	1,100.00 F	*1,100.00 F
Supplementary #2						
18	1		*AIR GUIDE LOWER RH	Cracked	35.00 F	*35.00 F
Total Parts (S\$)					4,977.00	5,215.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ALL DAMAGED PARTS, CUT/WELD FRONT SUPPORT PANEL, PANEL BEAT / STRAIGHTEN ALL DENTS, CHECK, ADJUST, REPLACE AND RE-ALIGN THE ABOVE PARTS	New	800.00	600.00
2	TO PUTTY AND SPRAY PAINT BONNET IN & OUT, FRONT BUMPER SIDE GARNISH *2, FRONT SUPORT PANEL, FRONT FENDER *2 AND ALL AFFECTED PORTIONS	New	750.00	500.00
3	TO REMOVE AND REPLACE AIRCON CONDENSER AND REFILL GAS	New	100.00	50.00
Gross Labour Cost (S\$)			1,650.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >