ACE AUTOLUTION PTE LTD

13,KAKI BUKIT ROAD 4 ,BARTLEY BIZ CENTRE #03-29,SINGAPORE 417807.

COMPANY REG. NO: 201403869W EMAIL: admin@aceauto.com.sg

TEL: 6844 1184 FAX: 6702 4202

NAME

ADDRESS

NEO YONG HUI NICHOLAS

HDB PUNGGOL EMERALD

265A PUNGGOL WAY #16-316

DATE :

22/11/2018

PROFORMA INVOICE:

ACE-259-2018

JOB NO .

VEHICLE NO.

SJS 1599 P

MAKE & MODEL :

MASERATI

SINGAPORE 821265

GRANTURISMO

PHOTOCOPY

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	COST OF REPAIR			\$ 8,200.00
		TOTAL		\$8,200.00

IMPORTANT

Please remit payment within 7 days from the due date An interest of 1.5% per month will be levied on all overdue amounts All cheques must be made payable to ACE AUTOLUTION PTE LTD (WE ARE NOT GST REGISTERED)

This a computer generated document. No signature is required.

PHOTOCOPY

Invoice

BIII To: NEO YONG HUI NICHOLAS

C/o ACE Autolution Pte Ltd 13 Kaki Bukit Road 4 #03-29

Bartley Biz Centre Singapore 417807

Invoice No:	2018598		
Date:	16/11/2018		
Our Ref	TP/018/0598SK		

	Description		Amount (S\$)
PARTICULARS			
Vehicle Registration No.	: SJS 1599P		400.00
Date of Accident	: 21/10/2018		
Date of Inspection	: 30/10/2018		
SERVICES:			
Assessment with report (inclusive of transport cha	arges and photographs etc)		
		Total	400.00
		Balance Due	400.00

We would appreciate your cheque crossed and made payable to: S K AUTO CONSULTANTS

Authorized Signature

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference:

TP/018/0598SK

Your Reference:

TBA

Date:

16/11/2018

TO:

NEO YONG HUI NICHOLAS

C/o ACE Autolution Pte Ltd 13 Kaki Bukit Road 4 #03-29

Bartley Biz Centre Singapore 417807

Assessment of Vehicle No

: SJS 1599P

Date of Accident

: 21/10/2018

Date of Inspection

: 30/10/2018

We have carried out a physical assessment of SJS 1599P at ACE Autolution Pte Ltd according to your instructions on 30/10/2018 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.

SJS 1599P

Make & Model

MASERATI GRANTURISMO

Year of Registration

29/1/2010

Engine Capacity (cc)

4691

Chassis Na

Chassis No.

ZAMHH45C000048345

Engine No.

M145148708

Colour

BLACK

Mileage (km)

95596

Good

2. VEHICLE CONDITION

Body Paint:

Steering

Serviceable

Foot Brake

Serviceable

Parking Brake

Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size

:

PIRELLI 245/35R20 - 80%

LH Make/Size

PIRELLI 245/35R20 - 80%

Rear

RH Make/Size

PIRELLI 245/35R20 - 80%

LH Make/Size

PIRELLI 245/35R20 - 80%

Note: % denotes the remaining percentage of the tyre

Page No. 2

Our Reference

TP/018/0598SK


Vehicle No.

SJS 1599P

4.DESCRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the Right side front portion

Please see attached schedule for details.



Estimated Amount

: \$\$10,874.54

Adjusted Amount

: \$\$8,200/-

Estimated Repair Days

: 5 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within <u>14 Days</u> from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **S K AUTO CONSULTANTS** for any reliance on this report by any third party.

Page No. 3

Our Reference

TP/018/0598SK

Vehicle No.

SJS 1599P

QTY	DESCRIPTION	CONDITION	19 19 19 19 19	PAIRER'S MATE(S\$)		OUR SMENT(S\$)
7 1	PARTS (LIST ITEMS)		7.1774			
1	RH Front fender	Dented		8563.00		8563.00
1	RH Front fender side light	Refix		27.75		0.00
3	RH Front fender Air intake @51.28	Necessary		153.84		153.84
1	RH Front fender "Pininfarina" inscription	Necessary		38.00		38.00
1	RH Front wheel shield	Refix		244.68	C. Co.	0.00
				9027.27		8754.84
	1	less	10%	902.73	10%	875.48
				8124.54		7879.36
		TOTAL PARTS		8124.54		7879.36

Page No. 4

Our Reference

TP/018/0598SK

Vehicle No.

SJS 1599P


s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts and components (Labour inclusive of removing and refix RH front door to facilitate replacement of RH Front fender - part of work process- refer to photos)	1400.00	1200.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced (special coating of paint to have even colour to blend with other body panel of car)	1000.00	800.00
3	To clear fault code with diagnostic computer and reset to specification	350.00	300.00
	Labour Total :	2750.00	2300.00
	TOTAL (PARTS & LABOUR):	10874.54	10179.36

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements). The final adjusted Lump Sum contract amount is \$\$8,200/-

S.Kumanan
















> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 23 Nov 2018

Singapore NRIC

8637J

SJS1599P

Yes

23 Nov 2018

MASERATI

GRANTURISMO CAMBIOCORSA

Black

2009

M145148708

ZAMHH45C000048345

323.0 kW (433 bhp)

\$120,702.00

29 Jan 2010

29 Jan 2010

2

\$120,702.00

Yes

28 Jan 2020

\$66,386.00

28 Jan 2020

E - Open Category

10

\$21,899.00


\$2,584.00


\$68,970.00

Driving License



Driving License





Driving License

