

Surveyor:

Raisul

DOI:

ASSIGNMENT

31/10/18

Date / Time:

30/10/18

Registered in Merimen:

30/10/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SKA 39930

Claim No. : \_\_\_\_\_

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_

HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II : S\$ \_\_\_\_\_

D.O.A: 21/10/18

Place of Accident : \_\_\_\_\_

Is driver the owner? (YES / NO) ☒ YES

Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_

Driver Tel No. : \_\_\_\_\_

(V/L: YES / NO) ☒ YESOI GIA REPORT ☒ YES / NO ; TP GIA REPORT ☒ YES / NO

Insured Liability : % Final ? Yes / No

SJD 2892 X



INSRS:

WSP: Shu Fatt

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_



INSRS:

WSP: \_\_\_\_\_

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_



INSRS:

WSP: \_\_\_\_\_

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_



INSRS:

WSP: \_\_\_\_\_

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_

Date / Time

31/10  
CH1SJD 2892 X - M/A 180 1745 / pl : DVA: 31/10/18  
SKA 39930 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

24/11/18

After call ltr to OI:

Documentation Check List: Handler Tylist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

30/11/18 - pls refer to views.

07/12/18 - DVCA

13/12/18 - file → Merimen An

RECEIVED 13 DEC 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:		Confirm by:	
FINALIZATION		Date/Time:	Confirm with:		Confirm by:	
Repair Cost:	S\$	( ) days	Reduction:	%	Email	Call
FINAL SETTLEMENT		Date/Time:	Confirm with:		Email	
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:	NIL	If NO or B 28, Ass. Lis:	
Repair Cost:	S\$	1979.50	(airman hit up.)			
Loss of Rental (LOR):	S\$	31.00	( 3 days)	x 100		
Loss of Use (LOU):	S\$	( \$ - x - days)				
Loss of Income (LOI):	S\$	( \$ - x - days)				
LOR only	<input checked="" type="checkbox"/>	LOU only	<input type="checkbox"/>	LOR + LOU	<input type="checkbox"/>	LOR + LOI
GIA/LTA Search	S\$	2.00	(Tick only one)			
Medical:	S\$	-				
Disbursement:	S\$	-	(e.g. Tow/ Independent)			
Legal Cost	S\$	-				
Total:	S\$	2302.50	Global Sum S\$:			
FINAL PAYMENT		Date/Time:	Confirm with:		Email	
Payee 1:	S\$	2302.50	Name 1:	Shu Fatt Auto Works		
Payee 2: (Strike if N.A.)	S\$	-	Name 2:			
Payee 3: (Strike if N.A.)	S\$	-	Name 3:			

Surveyor

*Form*

REF: AIG

19715/140

27968

# ASSIGNMENT

From: Date: 31/10/2018

Estimated Cost

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: 31Q 2892X  
at Workshop m/s: Shu Fatt Auto  
of Blk 1009, Blk Merah Lane 3 # 01-90

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

10am - 12pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

13K

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

31Q 2892X

Yr Regn: 2009 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN LATI 3B 1.5L 1458

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading:

70927

T/Radio: Insured / Std / NI / NA

Eng/No:

JN1FAAC1120010555

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/10/18

D.O.I.

31/10/18

Survey held at

SHU FATT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

U/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

U/S # 1850 Check # 2599.20 / 5840

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 S + RS 51

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	2796B
Vehicle Details	
Vehicle No.:	SJQ2892X
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D
Primary Colour:	Red
Secondary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	HR15093636B
Chassis No.:	JN1FAAC11Z0010555
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,002.00
Original Registration Date:	30 Apr 2009
First Registration Date:	30 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$19,002.00
PARF Eligibility Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2019
PARF Rebate Amount:	\$9,501.00
Intention to Deregister Details	
COE Expiry Date:	29 Apr 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,789.00
COE Rebate Amount:	\$375.00
<b>Total Rebate Amount:</b>	<b>\$9,876.00</b>

The information contained herein is correct as at 01 Nov 2018

OK

13,000  
9876  
3124



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref. SF/WSK/jw/SF-quo

30 October 2018

AIG - TP

510 SKD 2892 X NISSAN LATIO

S\$

Spare Parts	front bumper <del>DE</del> ✓	470.00 nett ✓
	Front bumper retainer <del>RE</del> ✓	25.00 nett ✓
	Front bumper clips @\$4.40 x 10 <del>RE</del> ✓	44.00 nett ✓
	Right front headlamp ? <del>CDA</del> ✓	390.00 nett ✓
	Right front headlamp holder ? <del>X</del> <del>su</del> ✓	30.00 nett X
	Right front fog lamp ? <del>X</del> <del>su</del> ✓	350.00 s.nett X
	Right front fender repair <del>X</del> ✓	650.00 nett ✓
	Right front fender cowling <del>X</del> <del>su</del> ✓	85.00 nett ✓
	Right front fender cowling clips @\$4.40 x 8 pcs <del>X</del> <del>su</del> ✓	35.20 nett ✓

2,079.20

Labour To knock, straighten front inner panel, front lower panel, Frt side panel, right front wheelhouse, front support Panel, renew front bumper, front right headlamp, right Front fender and assembly.

~~900.00~~ for f100 = 500

To respray damaged parts.

~~750.00~~ for

S\$3,729.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue  
by 9000008  
3 days  
4/8  
31/10/18 P 1145  
Resurvey after repair



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref. SF/WSK/jw/SF-quo

30 October 2018

AIG - TP

SJQ 2892 X NISSAN LATIO

Spare Parts	front bumper	470.00 nett	✓
	Front bumper retainer	25.00 nett	✓
	Front bumper clips @\$4.40 x 10	44.00 nett	✓
	Right front headlamp	390.00 nett	✓
	Right front headlamp holder	30.00 nett	
	Right front fog lamp	350.00 s.nett	
	Right front fender	650.00 nett	
	Right front fender cowling	85.00 nett	
	Right front fender cowling clips @\$4.40 x 8 pcs	35.20 nett	
		-----	
		2,079.20	

Labour	To knock, straighten front inner panel, front lower panel, Frt side panel, right front wheelhouse, front support Panel, renew front bumper, front right headlamp, right Front fender and assembly.	900.00	500
	To respray damaged parts.	750.00	400
		-----	
		S\$3,729.20	
		=====	

Supplementary (31.10.2018)

Front bumper foam  
Bumper reinforcement

220.00 nett CM ✓  
450.00 nett PA ✓

670.00 nett  
=====

Re-Surveyed by Razul  
on 11/11/18 @ 11:45 am

1,599  
1,599  
1,439.15

Labour 900.00

4399.20

1/5 20%

1850

3 days

2%

2,057.10  
462.8  
1,871.2  
130.9  
2,002.1



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref. SF/WSK/jw/SF-quo

30 October 2018

AIG - TP

SKD 2892 X NISSAN LATIO

S\$

Spare Parts	front bumper <del>DE</del> ✓	470.00 nett
	Front bumper retainer <del>RE</del> ✓	25.00 nett
	Front bumper clips @\$4.40 x 10 <del>RE</del> ✓	44.00 nett
	Right front headlamp ?	390.00 nett
	Right front headlamp holder ?	30.00 nett
	Right front fog lamp ?	350.00 s.nett
	Right front fender <del>Repair</del>	650.00 nett
	Right front fender cowling ✕	85.00 nett
	Right front fender cowling clips @\$4.40 x 8 pcs ✕	35.20 nett
		<u>2,079.20</u>

Labour	To knock, straighten front inner panel, front lower panel, Frt side panel, right front wheelhouse, front support Panel, renew front bumper, front right headlamp, right Front fender and assembly.	<del>900.00</del> 400
...	To respray damaged parts.	<del>750.00</del> 400
		<u>S\$3,729.20</u>

LISC Auto Consultants hence notify the Receiver of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue  
49 900008  
3 days

48

31/10/18 @ 1145

Resurvey after repair

## Hsiao Tong (LKKAUTO)

---

**From:** Julia - Shu Fatt Auto Works <shufatt@singnet.com.sg>  
**Sent:** Wednesday, 14 November 2018 10:33 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: accident involving SJQ 2892 X and SKA 3993 D on 25/10/2018 \*LKK REF: CC6/AIG18019715/pa3  
**Attachments:** img-181114095537.pdf; img-181114095657.pdf

Miss Chew Hsiao Tong  
Without prejudice

We refer to the above and forward our LOD with supporting documents herewith.

We look forward to your payment of \$2,302.50 soon.

Thank you  
樹發汽車修理廠  
Shu Fatt Auto Works  
Julia Wong  
Tel: 62730119

---

**From:** Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]  
**Sent:** Tuesday, October 30, 2018 5:30 PM  
**To:** Julia - Shu Fatt Auto Works  
**Cc:** Admin A; assignments  
**Subject:** RE: accident involving SJQ 2892 X and SKA 3993 D on 25/10/2018 \*LKK REF: CC6/AIG18019715/pa3

Without Prejudice

Hi Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Julia - Shu Fatt Auto Works <[shufatt@singnet.com.sg](mailto:shufatt@singnet.com.sg)>

**Sent:** Tuesday, 30 October 2018 5:17 PM

**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** FW: accident involving SJQ 2892 X and SKA 3993 D on 25/10/2018

Miss Chew

Without prejudice

As requested, we forward photos depicting damages to our client's vehicle.

Pls confirm liability asap.

Thank you

---

**From:** Julia - Shu Fatt Auto Works [<mailto:shufatt@singnet.com.sg>]

**Sent:** Tuesday, October 30, 2018 12:11 PM

**To:** Hsiao Tong ([chewht@lkkauto.com](mailto:chewht@lkkauto.com))

**Subject:** FW: accident involving SJQ 2892 X and SKA 3993 D on 25/10/2018

Miss Chew

Without prejudice

We also forward our request letter for survey with supporting documents herewith to you.

Pls confirm liability asap.

Thank you

樹發汽車修理廠

Shu Fatt Auto Works

Julia Wong

Tel: 62730119

---

**From:** Julia - Shu Fatt Auto Works [<mailto:shufatt@singnet.com.sg>]

**Sent:** Tuesday, October 30, 2018 12:08 PM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Subject:** accident involving SJQ 2892 X and SKA 3993 D on 25/10/2018

To : LKK Auto

Without prejudice

We forward our request for survey.



Pls arrange and confirm liability asap.

Thank you

樹發汽車修理廠

*Shu Fatt Auto Works*

*Julia Wong*

*Tel: 62730119*



樹發汽車修理廠  
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7085

Email: shufatt@pacific.net.sg

Co. Reg. No. 09082400M GST Reg. No. 09-062400-M

Our Ref. SF/091/2018

13<sup>th</sup> November 2018

without prejudice

AIG Asia Pacific Insurance Pte. Ltd.,  
78 Shenton Way, #07-16,  
Singapore 079120.

Dear Sirs,

ACCIDENT INVOLVING SJQ 2892 X AND SKA 3993 D ON 25/10/2018

We refer to the above matter.

We act for the owner of SJQ 2892 X whose vehicle was involved in the above accident with your insured driver of SKA 3993 D due to his/her gross negligence. Our client holds your insured driver responsible for all the outlay they had incurred we now forward the claim as follows:-


Repair costs	\$1,979.50
Loss of use	\$
Loss of use (\$100 x 3days x 7%)	\$ 321.00
Loss of income	\$
Survey fee	\$
Towing fee	\$
GIA search fee	\$ 2.00
LTA search fee	\$
GIA report fee for TP report	\$
Miscellaneous	\$
Off-peak e-day licence	\$
Seal for off-peak car	\$
Photocopies/postages/admin	\$
	<hr/>
	\$2,302.50
	=====

To facilitate your investigation, we forward repair bill, accident report, certificate of insurance and Letter of Authorisation, GIA search, rental agreement and invoice for your necessary action.

The above pertains to property damage claim only and should not prejudice injury claim, if any.

We thank you for your prompt assistance and we look forward to your early settlement.

Yours faithfully,  
SHU FATT AUTO WORKS

  
Julia Wong (Claims)

Encs.

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.  
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
 Tel +65 6827 7888, Fax +65 6827 7800  
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
 (REPUBLIC OF SINGAPORE)  
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
 Individual Ownership

**MOTOR MAX**  
**Comprehensive**

Certificate No. A 27691974 QMX

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle  
 SJQ2892X

2. Name of Policyholder  
 Tan Wei Ping

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
 30/04/2018

4. Date of Expiry of Insurance  
 29/04/2019

5. Persons or Classes of Persons entitled to drive\*

Tan Wei Ping

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Golden Prime Insurance Agency  
 20 Ubi Road 4  
 #01-07 Think One Building  
 Singapore 408622  
 Tel: 6842 6788 Fax: 6842 6789

MSIG Insurance (Singapore) Pte. Ltd.  
 Approved Insurers

for Chief Executive Officer



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18019715/pa3

31 OCT 2018

**LIM ZHI CHEN KENNETH**  
150 MEILING STREET  
#04-59  
SINGAPORE 141150

Dear Sir/Madam,

**ACCIDENT INVOLVING SKA 3993D & SJQ 2829X ALONG/AT 184 MEILING STREET MULTI STOREY CARPARK ON 25/10/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJQ 2829X against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

**CHEW HSIAO TONG**  
Case Handler  
DID: 6742 3197  
FAX: 6741 4108  
Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## LETTER OF AUTHORISATION

VEHICLE NO. SJD 2892 X

Name of owner Tan Wei Ping NRIC No. S 7332796 B

Address Blk 1009 Bukit Merah Lane 3 #01-90 SE 159723

Name of driver as above NRIC No. \_\_\_\_\_

Address as above

ACCIDENT INVOLVING SJD 2892 X AND SKA 3993 D

ON 05/10/2018 ALONG MSCP @ Blk 148A Mei Ling Street

In consideration of M/S. SHU FATT AUTO WORKS repairing my/our vehicle no. SJD 2892 X at my/our request, I/we, the abovenamed owner/driver of the said vehicle hereby irrevocably instruct and authorize SHU FATT AUTO WORKS to demand/claim/settle/receive whatever amount settled/payable by the insurance company and/or third party insurance company and all amount claimed and/or settled shall belong to SHU FATT AUTO WORKS to give an absolute discharge on my/our behalf. The settlement cheque should be made in favour of SHU FATT AUTO WORKS directly.

Dated this 3rd day of Nov 2018

Signature : 

Name : TAN WEI PING

Car No. : SJD 2892 X

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, SHU FATT AUTO WORKS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,979.50 (Repair Cost), S\$321.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. SJO 2892X that was damaged pursuant to the accident which occurred on 25/10/2018 (date) along MSCP @ BLK 148A MEI LING STREET (location) involving vehicle no/s SKA 3993D. This is pursuant to the inspection conducted on 31/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN WEI PING (the third party claimant") of vehicle no. SJO 2892X make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJO 2892X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10<sup>th</sup> (day) of December (month) 20 18 (year)



M.P.B.

Signed by appointed surveyor



Signed by "the workshop" (with chop)



樹發汽車修理廠  
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065  
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

TAX INVOICE NO: SF/091/2018  
12 November 2018

AIG Asia Pacific Insurance Pte Ltd  
(Third Party)

SJQ 2892 X NISSAN LATI

The repair costs of the above vehicle has been agreed  
upon a lump sum figure of S\$1850.00

7% GST

S\$

1850.00

129.50

-----  
1979.50  
=====

S'PORE DOLLARS: ONE THOUSAND NINE  
HUNDRED SEVENTY-NINE & CENTS FIFTY ONLY.

樹發汽車修理廠  
SHU FATT AUTO WORKS



# TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
TAN WEI PING BLK 145 MEI LING STREET #05-131 SINGAPORE 140145

DATE	INVOICE NO.
13-Nov-2018	A 38569

	VHA NO.	DUE DATE	VEH. NO.
	A 38569	13-Nov-2018	SGP 7523 U
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 31 OCTOBER 2018 TO 03 NOVEMBER 2018 YOUR REF: SJQ 2892 X	3	100.00	300.00
GST @ 7%			\$21.00
TOTAL			\$321.00

All cheques must be made payable to BKW Rent A Car Pte Ltd.  
Please write the vehicle and invoice number on the reserve.

**BKW Rent-A-Car Pte Ltd**  
120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg  
A subsidiary of BKW Automobile Pte Ltd



**bizSAFE**



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-166368  
Date of Request: 26/10/2018

Your Ref No: Online Purchase

Shu Fatt Auto Works  
Block 1009 Bukit Merah Lane 3  
#01-90  
Singapore 159723

Dear Sir/Madam,

Enquiry Date 26/10/2018  
Enquiry By JULIA WONG POH CHOO  
TP Vehicle No. SKA3993D  
Accident Date 25/10/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKA3993D	AIG Asia Pacific Insurance Pte. Ltd.	27/11/2017-26/11/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-166368  
 Date of Request: 26/10/2018

Your Ref No: Online Purchase

Shu Fatt Auto Works  
 Block 1009 Bukit Merah Lane 3  
 #01-90  
 Singapore 159723

Dear Sir/Madam,

Enquiry Date 26/10/2018  
 Enquiry By JULIA WONG POH CHOO  
 TP Vehicle No. SKA3993D  
 Accident Date 25/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	
GST Amount	1.87
Total Amount Due (GST Inclusive)	0.13
	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING












Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2018 <a href="#">Edit Reg</a>		31 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$S\$1,850.00</b> <a href="#">Edit Estimates</a>	<b>\$S\$1,850.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>LIM ZHI CHEN KENNETH</b> , ID: S7107774H								
Main Claimant:	<b>TAN WEI PING</b> , ID: S73327968								
Vehicle Reg. No.:	<b>SJQ2892X</b>	Date of Loss:	25/10/2018 18:00 - :59 [113 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4542275705SG</b>	Policy/Cover Note No.:	2100358362 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKA3993D</b>	Policy No. (Claimant):	A27691974QMX						
		Excess:							
Repairer:	<b>Shu Fatt Auto Works (HQ)</b> Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] <a href="#">Kianmeng.Chan1@aig.com</a>								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 09/11/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (30/10/2018): Re: Request for OI GIA [SKA 3993D; DOA: 25/10/2018]									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJQ2892X (4542275705SG)  
[SKA3993D]  
TP  
TAN WEI PING  
Oct 25 2018 6:00PM  
[LIM ZHI CHEN KENNETH]  
Shu Fatt Auto Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	(Draft)		Third Party Express Settlement - Payment Breakdown												1		Edit			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	07/11/18 12:56		Odometer Reading												1		Load JPG	<input checked="" type="checkbox"/>		
2	07/11/18 12:56		Chassis Number												1		Load JPG	<input checked="" type="checkbox"/>		
3	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
4	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
5	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
6	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
7	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
8	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
9	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
10	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
11	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
12	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
13	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
14	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
15	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
16	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
17	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
18	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
19	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
20	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
21	07/11/18 12:56		General View												1		Load JPG	<input checked="" type="checkbox"/>		
22	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
23	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
24	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
25	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
26	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
27	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
28	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
29	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
30	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
31	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
32	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
33	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		
34	07/11/18 12:57		Reinspection Photo												1		Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	07/11/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	07/11/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 13:36	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	 Load PDF	
2	01/11/18 18:36	TP ESTIMATE - MARKED	 Load PDF	
3	17/12/18 10:59	WORKSHOP INVOICE	 Load PDF	
4	17/12/18 10:59	AUTHORISATION TO ACT FORM	 Load PDF	
5	17/12/18 10:59	Release Voucher	 Load PDF	
6	17/12/18 10:59	RENTAL RECEIPT	 Load PDF	
7	17/12/18 10:59	GIA SEARCH	 Load PDF	
8	17/12/18 10:59	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/10/18 16:08	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKA3993D (Insd veh)	Model:	NISSAN LATIO 1.5 SPORTS
	SJQ2892X (TP veh)		(A)
Date of Accident:	25/10/2018		

Global Sum Settlement	: [ ] Yes	[ X ] No
Repair Estimate	: \$	4,707.14
Final Repair Cost	: \$	1,979.50
Loss of Use	: \$	days at \$0.00 per day
Rental (if any)	: \$	321.00 3 days
LTA / GIA Search Fee	: \$	2.00
Others:	: \$	0.00
	: \$	
Final Settlement Sum	: \$	2,302.50

Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Shu Fatt Auto Works	: \$	2,302.50
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

17 Dec  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18019715/R1PA3Q2  
Date: 17/12/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100358362  
Claimant Vehicle No: SJQ2892X Insured Vehicle No: SKA3993D  
Date of Loss: 25/10/2018 Nature of Claim: TP Claim No: 4542275705SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJQ2892X  
Make & Model: NISSAN LATIO, 1.5 Sports (A) Engine No: HR15093636B  
Reg. Date: 30/04/2009 (Man. Year: 2008) Chassis No: JN1FAAC11Z0010555  
Colour: Brown Odometer: 70927 km  
Engine Capacity: 1498 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,749.20	1,439.10	1,310.10	47.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	900.00	750.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,399.20</b>	<b>2,339.10</b>	<b>2,060.10</b>	<b>46.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,850.00</b>		
(S\$)	4,399.20	1,850.00	2,549.20	57.95
<b>+ GST 7.00/7.00% (S\$)</b>	<b>307.94</b>	<b>129.50</b>	<b>178.44</b>	<b>57.95</b>
<b>Nett Amount (S\$)</b>	<b>4,707.14</b>	<b>1,979.50</b>	<b>2,727.64</b>	<b>57.95</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		<b>321.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>2,302.50</b>		

### INSPECTION

Date of Assignment: 31/10/2018  
Date Inspected: 31/10/2018 Inspected At: Shu Fatt Auto Works (HQ)  
Block 1009 Bukit Merah Lane 3, #01-90  
Singapore 159723

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	470.00 F	*470.00 FN
2	1		*FRONT BUMPER RETAINER	Necessary	25.00 F	*25.00 FN
3	10		*FRONT BUMPER CLIPS	Necessary	44.00 F	*44.00 FN
4	1		*RIGHT FRONT HEADLAMP	Cracked	390.00 F	*390.00 FN
5	1		*RIGHT FRONT HEADLAMP HOLDER	Serviceable	30.00 F	*- FN
6	1		*RIGHT FRONT FOG LAMP	Serviceable	350.00 FS	*- FS
7	1		*RIGHT FRONT FENDER	Repair	650.00 F	*- FN
8	1		*RIGHT FRONT FENDER COWLING	Not Necessary	85.00 F	*- FN
9	8		*RIGHT FRONT FENDER COWLING CLIPS	Not Necessary	35.20 F	*- FN
10	1		*FRONT BUMPER FOAM	Cracked	220.00 F	*220.00 FN
11	1		*BUMPER REINFORCEMENT	Bent	450.00 F	*450.00 FN
					<b>Sub Total (S\$)</b>	<b>2,749.20 1,599.00</b>
					<b>- Nett Item Discount on N Items 0.00/10.00% (S\$)</b>	<b>0.00 159.90</b>
					<b>Total Parts (S\$)</b>	<b>2,749.20 1,439.10</b>

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK ,STRAIGHTEN FRONT INNER PANEL ,FRONT LOWER PANEL,FRT SIDE PANEL,RIGHT FRONT WHEELHOUSE ,FRONT SUPPORT PANEL,RENEW FRONT BUMPER ,FRONT RIGHT HEADLAMP ,RIGHT FRONT FENDER AND ASSEMBLY	New	900.00	500.00
2	TO RESPRAY DAMAGED PARTS	New	750.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,650.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >