

INS. C. 2010-10-10

Bom Sen

CC 6, CTI

180

19724

Kfa3n2

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

Pohkin

Date / Time:

30/10/18

Registered in Merimen:

30/10/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SKU 9504M

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$5 D.O.A : 26/10/18

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

ABC 1950L

INSRS:
WSP:
Tel:
Liability:
RMKS:

Lan Tan

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

7/11
CPK

ABC 1950L - NHTA 12004130/W1 ; DOA: 27/12/2012

SKU 9504M - 6/10/18 066131 And 392 ; DOA: 8/14/2018

5/11/18 spoke to OI, OI does not recall the trouble light when crossing the junction. told OI we will request evidence from TP and get back to him

5/11/18 Recall Liability unclear

confirm both party no evidence

After repair photo

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI: 5/11/18	
After call ltr to OI: 20/12/18	
Documentation Check List:	Handler: Typist
Notification ltr (if non-pickup)	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>
Towing Invoice:	<input type="checkbox"/>
LTA / GIA:	<input checked="" type="checkbox"/>
Medical Bill:	<input type="checkbox"/>
PIR:	<input type="checkbox"/>
Mandate/Reject Instruction:	<input type="checkbox"/>
LOD:	<input checked="" type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>
Others:	<input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time: 7/11/2018	Sent By: HMK
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$5 2,950.00	(7 days) Reduction: 41.88 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time: 11/2/2018	Confirm with: Mary
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	411
Repair Cost: (b57) \$3,156.50	\$5 1,578.25		
Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU): \$640.00	\$5 320.00	(\$ 80.00 x 8 days)	
Loss of Income (LOI):	\$5 -	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$5 29.00		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/Independent)	
Legal Cost:	\$5 -		
Total:	\$5 1,925.25	Global Sum \$5:	1,925.00
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$5 1,925.00	Name 1:	Lim Tan Motor Pte Ltd
Payee 2: (Strike if F.A.)	\$5 -	Name 2:	
Payee 3: (Strike if N.A.)	\$5 -	Name 3:	

x Junction, both party no evidence

GPA 27/11/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$400.00

REF: CTL

197me 1k for - (P)

ASSIGNMENT

From:

Date: 01-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBC 1950L

at Workshop n/s

Lim Tan

of

Blk 176 Sin Ming Drive #03-09

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBC 1950L

Yr Regn:

07 11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

To Hvac

C/C

2982

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

292888

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDH201 0070860

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15 X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

011754

Front

Rear

R/Bal.

2

mm

R/Bal.

6

mm

L/Bal.

2

mm

L/Bal.

6

mm

D.O.A.

26/10/18

D.O.I.

1/11/18

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/11 File pass to Customer

Lump Sum \$2,950.00 (Redif 2,125.98 / 41.88%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 \$ - PS \$1

1 Photos

1 Covers

1

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM18D05094C02
Our ref: CC6/CTI18019724/Kfa3

Date: 07/11/2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBC 1950L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01/11/2018 at the premises of M/s Lim Tan Motor Pte Ltd - Sin Ming have the following to report:-

Workshop Estimate Amount	: S\$	5,075.98
Revised Estimate Amount	: S\$	3,708.98
"Check" Items Amount	: S\$	290.33
Total (Including Check Items)	: S\$	3,999.31
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1562E

Vehicle Details

Vehicle No.:	GBC1950L
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 DX M
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	1KD2082937
Chassis No.:	KDH2010070860
Maximum Power Output:	-
Open Market Value:	\$37,390.00
Original Registration Date:	28 Jul 2011
First Registration Date:	28 Jul 2011
Transfer Count:	0
Actual ARF Paid:	\$1,870.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	27 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$23,900.00
COE Rebate Amount:	\$6,546.00
Total Rebate Amount:	\$6,546.00

The information contained herein is correct as at 30 Oct 2018

OK

To Whom It May Concern,

Accident involving my vehicle no GBC 1950L on 26/10/2018 (date) with
SKU 9504M (other veh no) along Traffic junction between Tampines Central 7
and Tampines Concourse

I, ISKANDAR BIN HASSIM NRIC No: 47358601
owner of vehicle no - GBC 1950L am aware of the accident of my vehicle on
26/10/2018 (Date) while car was driven by Mohamed Ibrahim Bin Mohamed Nor
IC No: S1183795F. I hereby authorise him/her to make the report.



Name

Date :

To fill in if there is a OD claim

I am aware of the circumstances and agreeable to claim my own insurance for the
above accident.

Name

Date

Mei Kwan (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 31 October, 2018 2:21 PM
To: Mei Kwan (LKKAuto)
Cc: Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving SKU9504M (OI : CTI - TBA) and GBC1950L (TP : LKK REF - CC6/CTI18019724/fa3) on 26/10/2018 / OUR REF: SNM18D05094C02
Attachments: INSURED REPORT.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Poh Kin,

Please find Insured report.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 30 October, 2018 2:40 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SKU9504M (OI : CTI - TBA) and GBC1950L (TP : LKK REF - CC6/CTI18019724/fa3) on 26/10/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/ Madam,

We refer to the above matter.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/CTI18019724/Kfa3

6th December 2018

JIANG BOHONG

65 Pasir Ris Grove,

#04-09,

Singapore 518217.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLES NOS. SKU 9504M AND
GBC 1950L ALONG TAMPINES CENTRAL 7 ON 26.10.2018**

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **16/12/2018**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

Pohkin, Chong

Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: pohkin@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)*

Poh Kin (LKKAUTO)

From: Mandy <mandy@ltm.sg>
Sent: Monday, 11 February 2019 11:10 AM
To: Poh Kin (LKKAUTO); richard@ltm.sg
Subject: RE: Claim Status - Our Client : GBC1950L Your Insured : SKU9504M D.O.A : 26/10/2018 LKK ref : CC6/CTI18019724/fa3

Importance: High

WITHOUT PREJUDICE

Dear Poh Kin,

Our client is prepared to accept your offer.

Please forward the usual DV for their endorsement and signature.

Hope to hear from you soon.

Thank you and regards,

Mandy Lim

Lim Tan Motor Pte Ltd

www.LTM.sg
+65 6452 0893 (Office)
+65 6458 9127 (Facsimile)

Like us in Facebook!!

www.facebook.com/LTMsg
www.facebook.com/LTM.Performance.Singapore

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Friday, 18 January 2019 4:34 PM
To: 'richard@ltm.sg'; mandy@ltm.sg
Subject: RE: Claim Status - Our Client : GBC1950L Your Insured : SKU9504M D.O.A :
26/10/2018 LKK ref : CC6/CTI18019724/fa3

Importance: High

Without Prejudice

Our Ref: CC6/CTI18019724/Kfa3
Your Ref: LTP102018/084 (GBC 1950L)

Dear Sir/Madam,

We refer to the above matter.

Apologies for late reply.

We are of view that this case could be 50% -50% due to traffic light junction and both party have no evidence. As such, we offer settlement at global sum **\$1,925.00** (all-in) .

Kindly confirm acceptance.

Your prompt reply will be very much appreciate.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth! Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18019724/Kfa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-02-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 9504M	Veh. Inspected	GBC 1950L
Policy No.	DMPCSN1537841803	Coverage (\$)	0.00
Claim No.	SNM18D05094/C02	Excess (\$)	0.00
Assign From		Assign Date	01/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KDH2010070860	Colour	WHITE
Odometer	292898	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	OHTSU	2 mm
L/H Front Tyre	195 R15X8	OHTSU	2 mm
R/H Rear Tyre	195 R15X8	OHTSU	6 mm
L/H Rear Tyre	195 R15X8	OHTSU	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/10/2018	Inspection Date	01/11/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 1950L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S FRONT DOOR	TO REPAIR SEE LABOUR	1,248.90	-
1	N/S FRONT DOOR LOCK PILLAR	BENT	589.10	589.10
1	N/S REAR SLIDING DOOR	BENT	1,855.80	1,855.80
1	N/S REAR SLIDING DOOR RUBBER	NOT NECESSARY	387.10	-
1	N/S REAR SLIDING DOOR FRONT LOCK	CRACKED	311.50	311.50
1	N/S REAR SLIDING DOOR LOCK SWITCH	DENTED	148.90	148.90
	LESS 25% DISCOUNT		-1,135.32	-726.32
			3,405.98	2,178.98
	<u>SPECIAL NETT ITEMS</u>			
1	N/S FRONT DOOR BODY LETTERING (SN)	NECESSARY	20.00	20.00
			20.00	20.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY PAINTING.		850.00	800.00
	TO TRANSFER TAILGATE FITTINGS.		100.00	60.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF N/S FRONT DOOR.		700.00	650.00
			1,650.00	1,510.00
	GRAND TOTAL		5,075.98	3,708.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,950.00

Report Ref No. CC6/CT118019724/Kfa3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.