

ASS. REC. BY:

REF:

CS/C118019752/ Uqdb

Special Instruction:

Surveyor:

Maxis

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

C11

Date/Time:

30/10/18 @ 3.58pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 8252Y

Insured:

GBF 1651J

at Workshop m/s

Chin chuan Garage

Tel:

9673 6356

of

Blk 3006, Ubi Rd 1 # 01-336

Policy No:

DMCVSN1748021801

Claim No:

SNM18005111C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/10/18

CA / REV / REP. / REV 24 HRS

Cup

31/10/18

H.O.D. Endorsement:

Date/Time:

4:30pm @ 30/10/18

Person Contacted:

Juky

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJW 8252Y - NA / AIG 18019574 / 24	Est: 26/10/18
	GBF 1651J - NA / AIG 18019574 / 24	Est: 26/10/18

REF:

271/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / E. & INV / MV

To Inspect Vehicle No:

at Workshop no:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / FR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time | Action / Instruction

1/11/18 4/5 #7400 cont. with Jack (Red & 7662.33, 51%)

Veh. No.

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng. No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modt: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MICT / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

19/11/18

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.R. (\$)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Survey Fee.

Transportation

) \$ + P.S. \$

) Photo

) Other

TOTAL

220

RECEIVED 19 NOV 2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018		30 Oct 2018 15:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	NARADA ASIA PACIFIC PTE LTD			
Vehicle Reg. No.:	SJW8252Y	Date of Loss:	26/10/2018 00:00 - :59	
Claim Type:	TP / SNM18D05111C02	Policy/Cover Note No.:	DMCVSN1748021801	
Vehicle Reg. No. (Insured):	GBF1651J	Policy No. (Claimant):		
		Excess:	\$50.00	
Repairer:	Chin Chuan Garage - Ubi (HQ) Bldg 3006 Ubi Road 1 #01-336, 408700 Ubi - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/11/2018]			
Adj Asg. Remarks:	SURVEY REVERT			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CPc**C PAGLAR & CO**

ADVOCATES & SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E

50 Chin Swee Road
#05-03 Thong Chai Building
Singapore 169874

Telephone: (65) 6536 5456

Facsimile: (65) 6836 2195

Email: pri@cpaglar.com.sg

SERVICE OF COURT DOCUMENTS BY FACSIMILE
WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: **GBF 1651J**
Our Reference: **CP/PRI/SJW8252/18.na**Date : 30th October 2018

62564315

CHINA TAIPING INSURANCE (S'PORE) PTE LTD BY FAX 6224 7478 ONLY
ATTN: MOTOR CLAIMS DEPT

Dear Sirs,

CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASESWe refer to your email dated 29th October 2018.

We are agreeable to one of your appointed single joint expert, Mr Marcus Chua.

Please note that the said vehicle can be inspected at:

CHIN CHUAN GARAGE
Blk 3006 Ubi Road 1
#01-336
Singapore 408700
Contact No.: 9673 6356 (Jack)**KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg**

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

FOR SURVEYORPlease initial here after completion of
pre-repair inspection.
Thank you**C PAGLAR & CO**

Cc client.

SJW 8252Y

Appointed Surveyor (Name & Signature) BY FAX NO. 6747 8378 ONLY

Date & Time of Inspection

Form 3

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3285K

Vehicle Details

Vehicle No.: SJW8252Y
Vehicle to be Exported: No
Intended Deregistration Date: 31 Oct 2018
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour: Silver
Manufacturing Year: 2010
Engine No.: 2AZE167836
Chassis No.: MR053BK4007039405
Maximum Power Output: 123.0 kW (164 bhp)
Open Market Value: \$28,375.00
Original Registration Date: 21 Apr 2010
First Registration Date: 21 Apr 2010
Transfer Count: 0
Actual ARF Paid: \$28,375.00 14187

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Apr 2020
PARF Rebate Amount: \$15,606.00

Intended COE Rebate Details

COE Expiry Date: 20 Apr 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$45,501.00
COE Rebate Amount: \$6,698.00
Total Rebate Amount: \$22,304.00

The information contained herein is correct as at 31 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/10/2018 14:00
Date Of Accident	26/10/2018 16:30
Exact Location Of Accident	JUNC MOUNTBATTEN RD & FORT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW8252Y
Insured/Policyholder	
Name Of Registered Owner	NARADA ASIA PACIFIC PTE LTD
Co Reg No	200503285K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.4 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100205217-08
Cover Note Number	

Driver

Name of Driver	NG SOON HEN
NRIC No	S1672580C
Date Of Birth	02/05/1964
Occupation	OUTDOOR
Date Of Driving Pass	18/05/1991
Driving Experience	27 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96929400
Fax Number	
Contact Number	OFFICE-96929400
Email Address	NOEMAIL

Address 7 SEMBAWANG CRESCENT
#15-16
Postcode 757096
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF1651J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver LIM HUA TECK
NRIC/Passport Number S1821353B
Contact Number 93203661
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name	NG SOON HEN
Approximate Age	
Injuries Sustain	NECK & SHOULDER
Injured person in which vehicle?	SJW8252Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

John: present 3/4/19 12:45

$\triangle A$	$\triangle B$
---------------	---------------

A. JW82527

$\pi_3 = 4.57-1651]$

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____

Accident Sketch Plan

Update. 26/10. I had a car accident afternoon at 4.30 pm -at traffic junction moubatten / fort road traffic junction. It was red light and my car stop at the traffic junction. The van behind me was unable to stop on time and hit my rear badly. Now my car in workshop pending to claim the other party's insurance .

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Below \$10k Depre A Year



Classiest Car You Can Find At
Less Than 10k Per Year Depre
StatAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

3 vehicles

Toyota camry 2.4

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota camry 2.4	Any	Any	2010	Any	Any	Any	Available
	Toyota Camry 2.4A	\$29,500	\$10,250 /yr	30-Apr-2010	2,362 cc	-	Luxury	Available
New 6 Mths Road Tax! 10 Years COE At \$61,000! No Repair Needed! Smooth Ride! Your Best Choice Selection With Us! 1 Stop Services, 90% Loan Financing, Lowest Interest Rate, 100% Accident Free, Best Qua...								
GD Motoring								
Posted: 27-Oct-2018								
Tags: 2010 Toyota Camry, 2010 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota								
	Toyota Camry 2.4A	\$29,800	\$10,530 /yr	26-Apr-2010	2,362 cc	110,858 km	Luxury	Available
1 Owner Only, Lowest Price Tag And Low Depreciation Need No Compare With Others In Terms Of Financing Package Available, Nice Gunmetal Silver, 1 Fussy Previous Owner, Best Short Term Car For Future Co...								
AL Autocar Pte Ltd								
Posted: 22-Oct-2018								
Tags: 2010 Toyota Camry, 2010 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota								
	Toyota Camry 2.4A	\$33,500	\$10,750 /yr	20-Aug-2010	2,362 cc	106,000 km	Luxury	Available
Elegant Black, Buy Back \$15200 After 10 Years, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.								
Prime Motor & Leasing								
Posted: 19-Oct-2018								
Tags: 2010 Toyota Camry, 2010 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

[20 results/page](#)

For old advertisements, view Expired ads

[Home](#) |
 [New Cars](#) |
 [Used Cars](#) |
 [Sell My Car](#) |
 [Directory](#) |
 [Products](#) |
 [Insurance](#) |
 [Article](#) |
 [Forum](#) |
 [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota camry 2.4, Toyota camry 2.4 Singapore, used Toyota camry 2.4 Singapore, used Toyota camry 2.4, used vehicles Singapore or even buy used Toyota camry 2.4 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) |
 [Careers](#) |
 [Contact Us](#) |
 [Sitemap](#) |
 [Terms of Service](#) |
 [Privacy Policy](#) |
 [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

CHIN CHUAN GARAGE

Blk 3006 Ubi Road 1, #01-336, Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No: 50600700J

Date: 26 Oct 2018

Narada Asia Pacific Pte Ltd

C/O Chin Chuan Garage

Blk 3006 Ubi Road 1

#01-336

Singapore 408700

Your Insured Veh No. : SJW8252Y

Toyota Camry 2.4 Auto ABS Airbag

Not Authorised
LKR
W/S \$ 7400/-
31/10/18
the ph after up
7 day.

To supply:-

1 pc	Boot Lid	<i>22/3uc</i>	\$ 913.10	✓
2 pcs	Boot Lid Hinge (\$185.80/pc)	<i>n</i>	\$ 371.60	X
1 pc	Boot Lid Toyota Logo	<i>ner 75.50</i>	\$ 96.80	✓
1 pc	Boot Lid Camry emblem	<i>ner</i>	\$ 79.90	✓
1 pc	Boot Lid 2.4 emblem	<i>ner 48.50</i>	\$ 63.40	✓
2 pcs	Boot Lid reflector (\$410.70/pc)	<i>one</i>	\$ 821.40	✓
1 pc	Bood Lid Outer Garnish	<i>20/02</i>	\$ 413.10	✓
1 pc	Bood Lid Outer Garnish Chrome	<i>one</i>	\$ 195.10	✓
1 pc	Bood Lid Lock	<i>7m</i>	\$ 395.40	✓
2 pcs	Bood Lid Number Plate Lamp (\$86.90/pc)	<i>11</i>	\$ 173.80	X
1 pc	Reverse camera	<i>shab</i>	\$ 250.00	✓
1 pc	Boot Lid Open Switch Sensor	<i>11</i>	\$ 198.70	X
1 pc	Boot Lid Inner Garnish	<i>70.1 485.10</i>	\$ 513.60	✓
1 pc	End Panel	<i>5-500 610.80</i>	\$ 652.10	✓
1 pc	End Panel Key Switch Sensor	<i>one/shab</i>	\$ 216.90	✓
1 pc	End Panel Inner Garnish	<i>twi</i>	\$ 393.80	✓
1 pc	Rear Bumper	<i>Di</i>	\$ 590.50	✓
2 pcs	Rear Bumper Retainer Long (\$87.20/pc)	<i>2nd</i>	\$ 174.40	✓
2 pcs	Rear Bumper Retainer Short (\$68.10/pc)	<i>3rd</i>	\$ 136.20	✓
2 pcs	Rear Bumper Reflector (\$94.10/pc)	<i>01/one</i>	\$ 188.20	ac

CHIN CHUAN GARAGE

Blk 3006 Ubi Road 1, #01-336, Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No: 50600700J

1 pc	Rear Bumper Reinforcement	DD 405.10	\$ 490.10	✓
2 pcs	Tail Lamp (\$513.20/pc)	cm 488.10 x 2 = 972.20	\$ 1,026.40	✓
2 pcs	Tail Lamp Inner Panel (\$190.00/pc)	0/544	\$ 380.00	✓
1 pc	Weather Stripe	7m	\$ 264.60	✓
1 pc	Rear Tyre Board	7m	\$ 255.70	✓
1 pc	End Panel Lock	11	\$ 59.10	X
1 pc	Exhaust Pipe	2	\$ 931.60	X
2 pcs	Exhaust Pipe Mounting (\$60.10/pc)	7m	\$ 120.20	✓
4 pcs	Tail Lamp Inner Panel Clip (\$39.20/pc)	11	\$ 156.80	X
2 pcs	Rear Fender Inner Shield (\$420.10/pc)	21 (7m 395.10 x 2 = 790.20)	\$ 840.20	✓
2 pcs	Rear Fender (\$921.40/pc)	2	\$ 1,842.80	X

Spare Parts Total \$ 13,205.50

Less 25% \$ 3,301.38

Total \$ 9,904.13

8831.7
6623.77

Special Nett Item

1 set	Reverse Sensor	shunt	\$ 280.00	200
1 set	Rear Bumper Clip	2	\$ 50.00	✓
1 set	Boot Lid Inner Garnish Clip	2	\$ 50.00	✓
1 set	End Panel Inner Garnish Clip	11	\$ 50.00	X
1 set	Rear Fender Inner Shield Clip	11	\$ 60.00	X
1 pc	Rear Windscreen Moulding	11	\$ 148.20	X
2 pcs	Rear Windscreen Sealant	11	\$ 50.00	X
1 pc	Rear Number Plate	34	\$ 40.00	✓
Total			\$ 728.20	

- 1) To remove, refit and replace damaged lamps and check up rear electrical wiring
- 2) To remove, refit and replace exhaust silencer and mountings
- 3) To apply undercoating on repaired and replaced panel
- 4) To remove and replace reverse sensor
- 5) To remove and refit rear cushion, rear speaker garnish, rear fender inner garnish
- 6) To remove and refit rear windscreen glass

\$ 60.00 30
\$ 120.00 60
\$ 150.00 60
\$ 100.00 50
\$ 250.00 80
\$ 150.00 X

CHIN CHUAN GARAGE

Blk 3006 Ubi Road 1, #01-336, Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No: 50600700J

- | | | |
|-------|--|-------------|
| 7) | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident | \$ 2,000.00 |
| 8) | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident | \$ 1,600.00 |
| | | <hr/> |
| Total | | \$ 4,430.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019752/UQD3N2
Date: 20/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1748021801
Claimant Vehicle No :	SJW8252Y	Insured Vehicle No :	GBF1651J
Date of Loss:	26/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05111C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW8252Y	Engine No:	2AZE167836
Make & Model:	TOYOTA CAMRY, 2.4 (A)	Chassis No:	MR053BK4007039405
Reg. Date:	21/04/2010 (Man. Year: 2010)	Odometer:	186507 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,632.32	6,963.77	3,668.55	34.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	2,480.00	1,950.00	44.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,062.32	9,443.77	5,618.55	37.30
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	15,062.32	7,400.00	7,662.32	50.87

INSPECTION

Date of Assignment:	30/10/2018	Inspected At:	Chin Chuan Garage - Ubi (HQ) Blk 3006 Ubi Road 1 #01-336 Singapore 408700
Date Inspected:	31/10/2018		

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Nov 2018)
 Parts: 143 TOYOTA CAMRY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJW8252Y)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented/Buckled	913.10 FL	*913.10 FL
2	2		*BOOT LID HINGE	Repair	371.60 FL	*- FL
3	1		*BOOT LID TOYOTA LOGO	Necessary	96.80 FL	*75.50 FL
4	1		*BOOT LID CAMRY EMBLEM	Necessary	79.90 FL	*79.90 FL
5	1		*BOOT LID 2.4 EMBLEM	Necessary	63.40 FL	*48.50 FL
6	2		*BOOT LID REFLECTOR	Cracked	821.40 FL	*821.40 FL
7	1		*BOOT LID OUTER GARNISH	Deformed/Dented	413.10 FL	*413.10 FL
8	1		*BOOT LID OUTER GARNISH CHROME	Cracked	195.10 FL	*195.10 FL
9	1		*BOOT LID LOCK	Twisted	395.40 FL	*395.40 FL
10	2		*BOOT LID NUMBER PLATE LAMP	Not Necessary	173.80 FL	*- FL
11	1		*REVERSE CAMERA	Shorted	250.00 FL	*250.00 FL
12	1		*BOOT LID OPEN SWITCH SENSOR	Not Necessary	198.70 FL	*- FL
13	1		*BOOT LID INNER GARNISH	Torn	513.60 FL	*485.10 FL
14	1		*END PANEL	Badly Dented	652.10 FL	*610.80 FL
15	1		*END PANEL KEY SWITCH SENSOR	Cracked/Shorted	216.90 FL	*216.90 FL
16	1		*END PANEL INNER GARNISH	Twisted	393.80 FL	*393.80 FL
17	1		*REAR BUMPER	Distorted	590.50 FL	*590.50 FL
18	2		*REAR BUMPER RETAINER LONG	Bent	174.40 FL	*174.40 FL
19	2		*REAR BUMPER RETAINER SHORT	Bent	136.20 FL	*136.20 FL
20	1		*REAR BUMPER REFLECTOR	O/s Cracked	188.20 FL	*94.10 FL
21	1		*REAR BUMPER REINFORCEMENT	Dented	490.10 FL	*405.10 FL
22	2		*TAIL LAMP	Cracked	1,026.40 FL	*972.20 FL
23	1		*TAIL LAMP INNER PANEL	O/s Bent	380.00 FL	*190.00 FL
24	1		*WEATHER STRIPE	Twisted	264.60 FL	*264.60 FL
25	1		*REAR TYRE BOARD	Torn	255.70 FL	*255.70 FL
26	1		*END PANEL LOCK	Not Necessary	59.10 FL	*- FL
27	1		*EXHAUST PIPE	Repair	931.60 FL	*- FL
28	1		*EXHAUST PIPE MOUNTING (2 Pcs)	Torn (1 Pc only)	120.20 FL	*60.10 FL
29	4		*TAIL LAMP INNER PANEL CLIP	Not Necessary	156.80 FL	*- FL
30	2		*REAR FENDER INNER TRIM	Deformed/Torn	840.20 FL	*790.20 FL
31	2		*REAR FENDER	Repair	1,842.80 FL	*- FL
32	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
33	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
34	1		*SET BOOT LID INNER GARNISH CLIP	Necessary	50.00 FS	*50.00 FS
35	1		*SET END PANEL INNER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
36	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
37	1		*REAR WINDSCREEN MOULDING	Not Necessary	148.20 FS	*- FS
38	2		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
39	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,933.70 9,171.70

- List Item Discount on L Items 25.00/25.00% (\$\$) 3,301.38 2,207.93

Report was unsubmitted during this print-out.

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (\$\$)					10,632.32	6,963.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT AND REPLACE DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	60.00	30.00
2	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	120.00	60.00
3	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	150.00	60.00
4	TO REMOVE AND REPLACE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE AND REFIT REAR CUSHION,REAR SPEAKER GARNISH,REAR FENDER INNER GARNISH	New	250.00	80.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	-
7	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIR INCLUDING CUT AND WELD;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	1,100.00
8	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,600.00	1,100.00
Gross Labour Cost (S\$)			4,430.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >