



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 10/05/2019

Survey Details:

Date of loss	28-Oct-18
Date of appointment	29-Oct-18
Date of survey	26-Nov-18
Location of survey	KAH MOTOR CO. SDN BHD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLK 6006U
Make and Model	HONDA ODYSSEY 2.4A - 2356cc
Date of registration	20-Jan-17
Excess	
Market Value (est)	\$110,000.00
Parf Rebate (est)	\$64,722.00
Nett Loss (est)	\$45,278.00

Repair details:

Initial Estimate	\$ 17,257.30
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 1,070.14
Check items (estimate)	\$ -
Labour	\$ 5,470.00
Total	\$ 6,540.14
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>5 DAYS</u>
---------------------------	---------------



Remarks:

We have not authorized repairs. We had spoken to the Insured PIC Ms Jasmine where she confirmed accident details and driver had rear-ended TP. Informed of TP claim, agreed to settle and aware NCD issues. A letter was sent out to the Insured company, no feedback till date. TP LOD IN.

Mandate:

Liability(TP)	100%	
Proposed Repair Cost	\$ 6,997.95	w/gst
Loss of Use	\$ 600.00	\$100 x 6 days
Loss of Rental (w/gst)	\$ -	no. of days
Loss of Income	\$ -	no. of days
GIA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 7,599.95	
***TBC - To Be Confirmed		