



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Ref: CC4/ASM18019811/Kea3q2 Date: 27/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 4425X	Veh. Inspected	SKW 849S	
Policy No.	P1794110	Coverage (\$)	0.00	
Claim No.	S8M01113	Excess (\$)	0.00	
Assign From		Assign Date	31/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104539492	Colour	METALLIC BLUE	
Odometer	39587 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	2 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	2 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE UNDERCARRIAGE & BODY STRUCTURE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2018	Inspection Date	31/10/2018	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			18 Working Days	