

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 01 Mar 2019)**Parts:** N/A NISSAN URVAN 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/GBA7936A/01/03/2019 18:01**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts***Supplementary*

| No. | Qty | Part No. | Particulars            | %Disc | %Depr | Amount           |
|-----|-----|----------|------------------------|-------|-------|------------------|
| 1   | 1   |          | *RADIATOR              | 0.00  | 0.00  | *480.00 F bl     |
| 2   | 1   |          | *RADIATOR FAN BLADE    | 0.00  | 0.00  | *105.00 F ora    |
| 3   | 2   |          | *ENGINE MOUNTING       | 0.00  | 0.00  | *150.00 F de dis |
| 4   | 1   |          | *RADIATOR FAN CLUTCH   | 0.00  | 0.00  | *300.00 F dis    |
| 5   | 1   |          | *FRT HEADLAMP PANEL RH | 0.00  | 0.00  | *210.00 F bt     |
| 6   | 1   |          | *RADIATOR FAN COWLING  | 0.00  | 0.00  | *115.00 F ora    |
| 7   | 2   |          | *FRT BUMPER BRACKET    | 0.00  | 0.00  | *110.00 F bt     |

F=Franchise part.

**Total Parts (S\$)****1,470.00****Sng Ah Tee Motor & Panel Service Pte Ltd/GBA7936A/01/03/2019 18:01.** Not valid without Reference section.

Generated using Merimen e-Claims IEAS