

ASS. REC. BY:

REF:

CS/C718019856/R1sbnz

Special Instruction:

Surveyor

Maimin

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

01.11.2018 303pm

Estimated Cost:

Bill to:

OD / TB / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 3243L

Insured:

SOS 6667P

at Workshop m/s

Wah Hong

Tel:

of

38 Toh Guan Rd East #01-57

Policy No:

DMPCSN3058041801

Claim No:

SNM180 0513100.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Sunny

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLP 3243L - R4/EGL 800/1717/mlws

QA: 23012018

SOS 6667P - x

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 8243Lat Workshop m/s Wah Hongof 38, 10th floor, 2015 #0157Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 53k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 8243L Yr Regn: 2017, JunType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI ATTACHE 2.c.c 193Colour: Red A/C: Insured / Std / NI / NASp. Reading: 022352 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MM B8TA 1344H 006305Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 21/10/18 D.O.I. 31/10/18Survey held at Wah HongDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
01/11/18	refer to email. Call Michael from wah hong informs him that repair cost is 8k. He agreed and confirmed
12/11/18	Confirmed HS \$ 8,000/- @ 12 days with Resul. (\$5,852.00 Red - 42%)
	RECEIVED 12 NOV 2018

Date/Time, File Pass to?

12/11/18☐

Preli. Report

1) Typist☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12Resurvey No. of Trip: 2

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$ 8,000/- HS)Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est-Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		01 Nov 2018 15:03 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LEE ENG HOCK, ID: S0089141Z		
Main Claimant:	LEE TENG HOI, ID: S1379558D		
Vehicle Reg. No.:	SLP8243L	Date of Loss:	27/10/2018 21:00 - :59
Claim Type:	TP / SNM18D05131C02	Policy/Cover Note No.:	DMPCSN3058041801 (Comprehensive)
Vehicle Reg. No. (Insured):	SDS6667P	Policy No. (Claimant):	D18MTPV01010626
		Excess:	S\$0.00
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 6773 7377		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/11/2018]		
Driver/Custodian (Insured):	LEE ENG HOCK (69 / Male), NRIC: S0089141Z		
Adj Asg. Remarks:	EST \$15,475.92, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 12 November 2018 11:19 AM
To: 'Michael Tee'
Cc: SUR; Rasul (LKKAuto)
Subject: RE: SLP 8243L doa : 27/10/18

Hi Michael,

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michael Tee [<mailto:michael@wahhong.sg>]
Sent: Monday, 12 November 2018 11:10 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: Re: SLP 8243L doa : 27/10/18

OK FOR Lump Sum At \$8,000.00 & 12 + 2 Days LOU

On 12 Nov 2018, at 9:56 am, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Michael,

Please confirm final fig of \$8,000.00 (lump sum) @ 12 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michael Tee [<mailto:michael@wahhong.sg>]
Sent: Friday, 2 November 2018 3:14 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: Re: SLP 8243L doa : 27/10/18

OK Repair Limit At \$8,000.00

On 2 Nov 2018, at 2:41 pm, Shirley Hiew (LKK Auto)
<ShirleyHiew@lkkauto.com> wrote:

Hi Michael,

As spoken, kindly acknowledge the email below above matter.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto)
Sent: Thursday, 1 November, 2018 9:41 AM
To: 'Michael Tee'
Subject: SLP 8243L doa : 27/10/18

Hi Michael,

As spoken, repair limit for this vehicle is 8K
Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
<image001.jpg> *Save the Earth. Print only when necessary.*

<ESTIMATE MARKED.pdf>

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Thursday, 1 November, 2018 9:41 AM
To: 'Michael Tee'
Subject: SLP 8243L doa : 27/10/18

Hi Michael,

As spoken, repair limit for this vehicle is 8K
Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9558D
Vehicle Details	
Vehicle No.:	SLP8243L
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	3A92UGB5802
Chassis No.:	MMBSTA13AHH006305
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,019.00
Original Registration Date:	20 Jun 2017
First Registration Date:	20 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$40,135.00
Total Rebate Amount:	\$43,885.00

The information contained herein is correct as at 01 Nov 2018

OK

53,500
43,885

9,115

(8K)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2018 11:25
Date Of Accident	27/10/2018 21:40
Exact Location Of Accident	ALONG PIE BEFORE BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP8243L
Insured/Policyholder	
Name Of Registered Owner	LEE TENG HOI
NRIC No	S1379558D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94757933
Alternative Phone No	OFFICE-94757933

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01010626
Cover Note Number	

Driver

Name of Driver	LIM JIA
NRIC No	S8813951H
Date Of Birth	16/04/1988
Occupation	INDOOR
Date Of Driving Pass	11/02/2011
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98445323
Fax Number	
Contact Number	
Email Address	LIMJIA@U.NUS.EDU

Address	BLOCK 203 PETIR ROAD #02-657
Postcode	670203
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDS6667P
Vehicle Make/Model/Colour	VEHICLE (B)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE ENG HOCK
NRIC/Passport Number	S0089141Z
Contact Number	96625067
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : GENDER: :

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLG2641H
Vehicle Make/Model/Colour	VEHICLE (C)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANANTHAN S/O NADARAJAH
NRIC/Passport Number	S7777671J
Contact Number	97651137
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/10/2018

9.36am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 Oct 9.38pm, at PIE before BKE exit, SLG2641H stopped and braked to a stop on the second lane. I managed to reach a stop and was hit by the rear car, SD5 6667P which caused me to hit the car, SLG2641H in front of me. I have a bruise on my abdomen and a sprain on my right ankle.

B - SD5 6667P LEE ENG HOEK 50089141Z 96625067
C - SLG2641H ANANTHAN S/O NADARAJAH 57777671J 97651137

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/10/2018 9.36am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Name: LEE TENG HOI
Address: Blk 203 Petir Road #02-657 S 670203
Policy: D18MTPV01010626

Date: 29 October, 2018
Vehicle No: SLP8243L

Quotation for Reinstste / Repairs for vehicle

Parts Replacement - Cost Price

1 Pc	Front Bonnet	BT	\$	660.00
1 Pc	Front Support Panel	BT	\$	900.00
1 Pc	Front Bumper	DE	\$	720.00
1 Pc	Front R/H Side Bumper Bracket	NE	\$	20.00
1 Pc	Front L/H Side Bumper Bracket	NE	\$	20.00
1 Pc	Front R/H Side Headlamp	CRA	\$	560.00
1 Pc	Front L/H Side Headlamp	CRA	\$	560.00
1 Pc	Front Bumper Grille Chrome	CRA	\$	480.00
1 Pc	Front Bumper Reinforcement	BT	\$	185.00
1 Pc	Front R/H Side Bonnet Hine	BT	\$	70.00
1 Pc	Front L/H Side Bonnet Hine	BT	\$	70.00
1 Pc	Front Bonnet Lock	BT	\$	90.00
1 Pc	Front Grille Under	DE	\$	150.00
1 Pc	Front Bumper Support Top Garnish	DE	\$	120.00
1 Pc	Front Headlamp Panel Support Upr	? X SUC	\$	110.00 X
1 Pc	Front R/H Side Fender	BT	\$	385.00
1 Pc	Radiator	? CRA	\$	830.00
1 Pc	Air Condenser	? BT	\$	750.00
1 Pc	Air Con Fan Motor Cowling	CRA	\$	210.00
1 Pc	Radiator Fan Blade	? X SUC	\$	85.00 X
1 Pc	Front Number Plate	BT	\$	30.00
1 Pc	Weatherstrip Trunk Lid	CRA	\$	180.00
1 Pc	Front Logo	NE	\$	55.00
1 Pc	Rear Boot	BT	\$	760.00
1 Pc	Rear Bumper	DE	\$	600.00
1 Pc	Rear End Panel	BT	\$	480.00
1 Pc	Rear Spare Tyre Board	CRA	\$	210.00
1 Pc	Rear R/H Bumper Bracket	NE	\$	30.00
1 Pc	Rear L/H Bumper Bracket	NE	\$	30.00
1 Pc	Rear L/H Tail Lamp	? X SUC	\$	280.00
1 Pc	Rear R/H Tail Lamp	CRA	\$	280.00
1 Pc	Rear R/H Reflector	CRA	\$	26.00
1 Set	Rr Sensor	AW	\$	120.00

Parts total: \$ 10,056.00
cost plus 10% 1005.60
\$ 10,056.00

MISC & Labour & Charges

- 1 job remove & replace all the parts mentioned above knocking straighten up necessary affected
1 job To spray painting on affected areas

\$ 2,300.00 1900
\$ 1,500.00 1400 1500 } 3400
Labour's Total: \$ 3,800.00
Sub-Total: \$ 13,856.00 14861.60
GST 7%: \$ 969.92
Grand Total: \$ 14,825.92

Thank You
Your Faithfully.

Michael Tee
Wah Hong Motors & Credit Pte Ltd
Tel: 6773 7377
Fax: 6896 6321
Email: michael@wahhong.sg

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

w/ship accepted 8k

WAH HONG

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019856/R1SBN2

Date: 13/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3058041801
Claimant Vehicle No :	SLP8243L	Insured Vehicle No :	SDS6667P
Date of Loss:	27/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05131C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8243L	Engine No:	3A92UGB5802
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AHH006305
Reg. Date:	20/06/2017 (Man. Year: 2017)	Odometer:	22352 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,061.60	10,539.10	522.50	4.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	3,400.00	400.00	10.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,861.60	13,939.10	922.50	6.21
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	14,861.60	8,000.00	6,861.60	46.17
+ GST 7.00/7.00% (\$\$)	1,040.31	560.00	480.31	46.17
Nett Amount (\$\$)	15,901.91	8,560.00	7,341.91	46.17

INSPECTION

Date of Assignment: 01/11/2018

Date Inspected: 31/10/2018 Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
 38 Toh Guan Road East, #01-57,
 Enterprise Hub
 Singapore 608581

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
Parts: 143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8243L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Bent	660.00 F	*660.00 F
2	1		*FRONT SUPPORT PANEL (WCP)	Bent	900.00 F	*900.00 F
3	1		*FRONT BUMPER (WCP)	Deformed	720.00 F	*720.00 F
4	1		*FRONT R/H SIDE BUMPER BRACKET (WCP)	Necessary	20.00 F	*20.00 F
5	1		*FRONT L/H SIDE BUMPER BRACKET (WCP)	Necessary	20.00 F	*20.00 F
6	1		*FRONT R/H SIDE HEADLAMP (WCP)	Cracked	560.00 F	*560.00 F
7	1		*FRONT BUMPER GRILE CHROME (WCP)	Cracked	480.00 F	*480.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	185.00 F	*185.00 F
9	1		*FRONT R/H SIDE BONNET HINE (WCP)	Bent	70.00 F	*70.00 F
10	1		*FRONT L/H SIDE BONNET HINE (WCP)	Bent	70.00 F	*70.00 F
11	1		*FRONT BONNET LOCK (WCP)	Bent	90.00 F	*90.00 F
12	1		*FRONT GRILLE UNDER (WCP)	Deformed	150.00 F	*150.00 F
13	1		*FRONT BUMPER SUPPORT TOP GARNISH (WCP)	Deformed	120.00 F	*120.00 F
14	1		*FRONT HEADLAMP PANEL SUPPORT UPR (WCP)	Serviceable	110.00 F	*- F
15	1		*FRONT R/H SIDE FENDER (WCP)	Bent	385.00 F	*385.00 F
16	1		*RADIATOR (WCP)	Cracked	830.00 F	*830.00 F
17	1		*AIR CONDENSER (WCP)	Bent	750.00 F	*750.00 F
18	1		*AIR CON FAN MOTOR COWLING (WCP)	Cracked	210.00 F	*210.00 F
19	1		*RADIATOR FAN BLADE (WCP)	Serviceable	85.00 F	*- F
20	1		*FRONT NUMBER PLATE (WCP)	Bent	30.00 F	*30.00 F
21	1		*WEATHERSTRIP TRUNK LID (WCP)	Cut	180.00 F	*180.00 F
22	1		*FRONT LOGO (WCP)	Necessary	55.00 F	*55.00 F
23	1		*REAR BOOT (WCP)	Bent	760.00 F	*760.00 F
24	1		*REAR BUMPER (WCP)	Deformed	600.00 F	*600.00 F
25	1		*REAR END PANEL (WCP)	Bent	480.00 F	*480.00 F
26	1		*REAR SPARE TYRE PANEL (WCP)	Cracked	210.00 F	*210.00 F
27	1		*REAR R/H BUMPER BRACKET (WCP)	Necessary	30.00 F	*30.00 F
28	1		*REAR L/H BUMPER BRACKET (WCP)	Necessary	30.00 F	*30.00 F
29	1		*REAR L/H TAIL LAMP (WCP)	Serviceable	280.00 F	*- F
30	1		*REAR R/H TAIL LAMP (WCP)	Cracked	280.00 F	*280.00 F
31	1		*REAR R/H REFLECTOR (WCP)	Cracked	26.00 F	*26.00 F
32	1		*SET RR SENSOR (WCP)	Not Working	120.00 F	*120.00 F
33	1		*FRONT L/H SIDE HEADLAMP (WCP)	Cracked	560.00 F	*560.00 F

F=Franchise part.

Sub Total (\$\$)	10,056.00	9,581.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,005.60	958.10
Total Parts (\$\$)	11,061.60	10,539.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REPLACE ALL THE PARTS MENTIONED ABOVE KNOCKING STRAIGHTEN UP NECESSARY AFFECTED	New	2,300.00	1,900.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	1,500.00
Gross Labour Cost (\$\$)			3,800.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >