

KP

18/11

Not Notified  
Resurvey By part

6 days



**ESTIMATE TO REPAIR**

VEHICLE NO. : SLK 3214 E  
MAKE : HONDA  
MODEL : VEZEL HYBRID 1.5 X SENSING  
YEAR : 2016  
CHASSIS NO : RU31223725

SURVEYOR NAME	: LKK - Kenneth
DATE OF SURVEY	: 01 NOV 2018
TIME OF SURVEY	: afternoon

DATE : 31-Oct-18  
DATE OF ACCIDENT : 29-Oct-18  
THIRD PARTY REF : SKC 1289 G/ AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc ✓	rear bumper				\$762.70
<del>2</del> 2 pcs	<del>rear bumper bracket</del>		\$17.50		<del>\$35.00</del>
2	10 pcs rear bumper clips		\$3.90		\$39.00
1 pc ✓	rear end panel				\$367.50
5	1 pc rear end panel garnish				\$98.00
6	1 pc tail gate				\$953.30
7	1 pc tail gate rubber				\$96.80
8	1 pc tail gate lock				\$157.70
9	1 pc tail gate VEZEL emblem				\$43.00
10	1 pc tail gate HYBRID emblem				\$75.50
11	1 set rear windscreen moulding				\$120.00
12	1 pc rear exhaust silencer				\$528.00
13	1 pc exhaust chrome pipe				\$135.00
	Less 20%				\$3,411.50
					\$682.30
					\$2,729.20
1 set	rear bumper sensor	S.Nett			\$200.00
1 pc	rear windscreen sealant	S.Nett			\$40.00
	To putty & spray paint.				\$800.00
	To transfer tail gate fitting.				\$80.00
	To remove & refix rear windscreen glass.				\$120.00
	To replace rear exhaust silencer box.				\$80.00
	To anti-rust.				\$80.00
	Labour charges.				\$700.00
TG-VL/-	Total				\$4,829.20

**KK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Lim Tan Motor Pte Ltd  
 176 Sin Ming Drive #03-09 Singapore 575721  
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@ltm.sg Website: www.ltm.sg  
 Co Reg No 199307277D  
 GST Reg No 142-0019086-0

IN BUZZER ASSY SMART  
980



**SUPPLEMENTARY TO REPAIR**

VEHICLE NO. : SLK 3214 E  
 MAKE : HONDA  
 MODEL : VEZEL HYBRID 1.5X SENSING  
 YEAR : 2017  
 CHASSIS NO : RU31223725

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 7-Nov-18  
 DATE OF ACCIDENT : 29-Oct-18  
 THIRD PARTY REF : SKC 1289 G / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Buzzer Assembly Smart Less 20%				\$ <sup>CM</sup> 80.00 ✓ \$ 16.00 \$ 64.00
	Parts \$2713.50				
	Supp <u>\$80.00</u>				
	\$2793.50				
	- 20% <u>\$558.70</u>				
	\$2234.80				
	SIN \$240.00				
	labour \$1540.00				
	PPF <u>\$4014.80</u> ✓ ok				
	05 days <i>[Signature]</i> 12/11/18				
TG-RA/-	<b>TOTAL</b>				\$ <b>64.00</b>

Lim Tan Motor Pte Ltd

Bldg 178 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg  
 Co.Reg No.199307277D GST,Reg No.M2-0019086-0