

Not Ashamed
Resurvey B4 part

5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SLK 3214 E
 MAKE : HONDA
 MODEL : VEZEL HYBRID 1.5 X SENSING
 YEAR : 2016
 CHASSIS NO : RU31223725

SURVEYOR NAME :	LKK - Kenneth
DATE OF SURVEY :	01 NOV 2018
TIME OF SURVEY :	afternoon

DATE : 31-Oct-18
 DATE OF ACCIDENT : 29-Oct-18
 THIRD PARTY REF : SKC 1289 G/ AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$762.70
2 pcs	rear bumper bracket		\$17.50		\$35.00
10 pcs	rear bumper clips		\$3.90		\$39.00
1 pc	rear end panel				\$367.50
1 pc	rear end panel garnish				\$98.00
1 pc	tail gate				\$953.30
1 pc	tail gate rubber				\$96.80
1 pc	tail gate lock				\$157.70
1 pc	tail gate VEZEL emblem				\$43.00
1 pc	tail gate HYBRID emblem				\$75.50
1 set	rear windscreen moulding				\$120.00
1 pc	rear exhaust silencer				\$528.00
1 pc	exhaust chrome pipe				\$135.00
					\$3,411.50
	Less 20%				\$682.30
					\$2,729.20
1 set	rear bumper sensor	S.Nett			\$200.00
1 pc	rear windscreen sealant	S.Nett			\$40.00
	To putty & spray paint.				\$800.00
	To transfer tail gate fitting.				\$80.00
	To remove & refix rear windscreen glass.				\$120.00
	To replace rear exhaust silencer box.				\$80.00
	To anti- rust.				\$80.00
	Labour charges.				\$700.00
TG-VL/-	Total				\$4,829.20

LKK Auto Consultants hereby notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming, Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
 Co.Reg No.199307277D Date: GST Reg No.M2-0019086-0