



**ESTIMATE TO REPAIR**

VEHICLE NO. : SLK 3214 E  
 MAKE : HONDA  
 MODEL : VEZEL HYBRID 1.5 X SENSING  
 YEAR : 2016  
 CHASSIS NO : RU31223725

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 31-Oct-18  
 DATE OF ACCIDENT : 29-Oct-18  
 THIRD PARTY REF : SKC 1289 G/ AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$762.70
2 pcs	rear bumper bracket		\$17.50		\$35.00
10 pcs	rear bumper clips		\$3.90		\$39.00
1 pc	rear end panel				\$367.50
1 pc	rear end panel garnish				\$98.00
1 pc	tail gate				\$953.30
1 pc	tail gate rubber				\$96.80
1 pc	tail gate lock				\$157.70
1 pc	tail gate VEZEL emblem				\$43.00
1 pc	tail gate HYBRID emblem				\$75.50
1 set	rear windscreen moulding				\$120.00
1 pc	rear exhaust silencer				\$528.00
1 pc	exhaust chrome pipe				\$135.00
					\$3,411.50
	Less 20%				\$682.30
					\$2,729.20
1 set	rear bumper sensor	S.Nett			\$200.00
1 pc	rear windscreen sealant	S.Nett			\$40.00
	To putty & spray paint.				\$800.00
	To transfer tail gate fitting.				\$80.00
	To remove & refix rear windscreen glass.				\$120.00
	To replace rear exhaust silencer box.				\$80.00
	To anti- rust.				\$80.00
	Labour charges.				\$700.00
TG-VL/-	Total				\$4,829.20

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0