

凱摩哆服務

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701. TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務:汽車意外保險陪償,拖車,汽車修理及維修服務,打嗎呷,噴漆。 Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 31/10/2018

Attn: The Motor Claims Department

Your Insured veh no: SJS 0062 C

AXA Insurance S'pore Pte Ltd

8 Shenton way

27-01 **AXA Tower**

Singapore 068811

Vic

WITHOUT PREJUDICE

(By Email Only)

Tel: 6880 4711 claim dep

Fax: 6880 4838 claim dep

96893735

Dear Sir / Madam

Estimate Cost repair Bill To Nissan E25 No GZ 4957 T & SJS 0062 C on23/10/201/ @11:15:00

To Supply :-

Front bumper Det 1pc

Front bumper side retainer \$ 109.50 2pcs

1pc

less

To dismantle and replace of the accident damaged parts, knocking, repair, adjust and reshape of same.

To putty, apply primer & spray paint on the affecte portion.

785.20 706.68

\$ 566.20 nett SN: 30

\$219.00 nett

\$ 45.00 nett 30/s~)

\$830.20

10% \$ 83.02

\$747.18

\$400.00 200

600

\$500,00 400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15 Adrian () told: 1336:18 02/11/18: 1/5: 1050