



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/10/2018
Vehicle Reg. No.:	SJY6134H	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHONG KAR YEE		
Make/Model:	MINI COOPER, 1.6 (A)	Vehicle Reg. Date:	17/09/2010
Vehicle Colour:	BLACK	Chassis No:	WMWSU32070TY91203
Engine No:	B0361732		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	1,323.00
Miscellaneous Items	10.00
Labour	770.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,103.00
+ GST 7.00% (\$\$)	147.21
Nett Amount (\$\$)	2,250.21

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Oct 2018)
Parts:	N/A MINI COOPER 1.6 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Mova Automotive Pte Ltd/SJY6134H/31/10/2018 17:44
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>DE</i>			
2	1		*REAR BUMPER TOW COVER <i>cut</i>	10.00	0.00	*628.00 F
3	1		*REAR BUMPER LOWER (ROUGH BLACK) ?	10.00	0.00	*31.00 F
4	16		*REAR BUMPER RIVET <i>re</i>	10.00	0.00	*181.00 F
5	10		*REAR BUMPER CLIPS <i>re</i>	10.00	0.00	*80.00 F
6	1		*REVERSE SENSOR RH <i>cut</i>	10.00	0.00	*50.00 F
7	1		*REAR BUMPER LAMP (RED) ?	10.00	0.00	*236.00 F
8	1		*REAR BUMPER LAMP CHROME ?	10.00	0.00	*125.00 F
9	1		*REAR BUMPER SIDE RETAINER LH X	10.00	0.00	*38.00 F
10	1		*REAR BUMPER SIDE RETAINER RH X	10.00	0.00	*18.00 F
11	1		*REAR BUMPER CENTRE BRACKET <i>re</i>	10.00	0.00	*18.00 F
12	1		*REAR BUMPER SPONGE ?	10.00	0.00	*27.00 F
13	1		*REAR BUMPER REINFORCEMENT - CHECK ?	10.00	0.00	*38.00 F
14	1		*REAR EXHAUST PIPE - CHECK ?	10.00	0.00	-
15	1		*REVERSE SENSOR LH - CHECK ?	10.00	0.00	-
				10.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,470.00
- List Item Discount on L Items (\$\$)	147.00
Total Parts (\$\$)	1,323.00

Mova Automotive Pte Ltd/SJY6134H/31/10/2018 17:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

10.0

Sub Total (\$\$)

10.0

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO INSPECT REAR LIGHTING MECHANISM

New

30

50.00

2 TO REMOVE & INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION

New

40

80.00

3 TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION

New

200

280.00

4 TO SPRAY PAINT ON REPAIRED AREAS

New

200

280.00

5 TO CHECK REAR EXHAUST PIPE & ALIGNMENT

New

60

80.00

Gross Labour Cost (\$\$)

770.00

Mova Automotive Pte Ltd/SJY6134H/31/10/2018 17:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rahul

48 90010068

3 days

4s

12/11/18 @ 1220

Resurvey after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: