

ASS. REC. BY:

REF:

CS/FCI/18019904/Rlv d3er

Special Instruction:

Surveyor:
rwsASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time: 11/11/18 @ 3:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

FBM 387S

Insured:

SHC3060X

at Workshop m/s

Weednes Automotive

Tel:

6430 4934

of

45 Long Kee Road

Policy No:

Claim No:

D18007806MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/10/2018

CA / REV / REP. / REV 24 HRS

(up)

2/11/2018

H.O.D. Endorsement:

Date/Time:

4:15pm @ 1/11/18

Person Contacted:

Tony

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

FBM 387S - x

SHC3060X - CS/FCI/18003893/Kqbn2

DUA : 27/02/2018

5/11/18

Email preli revised to FCI

17/1/19

@ 530pm Tony will email us finalised

5/3/19

Final fig \$20,252.70 confirmed by email (Red 3160.70, 1370)

SYNOPSIS *Form*

REF: FCL

91044

ASSIGNMENT

From: Date: 02/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBM 387S

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Tony @ 6430 4434

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'WP'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBM 387S

Yr Regn: 2017 Jan

Type: M.Car / Cycl / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: DUCATI MONSTER 821

C.C. 821

Colour: MULTI

A/C Insured / Std / NI / NA

Sp. Reading

6645

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZOMMCOAAH B000 225

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

120/70ZR17

R:

190/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. mm

L/Bal. mm

D.O.A. 26/10/18

D.O.I. 02/11/18

Survey held at

W6HUES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 MAR 2019

[Signature]
5/3/2019

Date/Time: File Pass to?

☐

: Preli. Report

1).

☐

: Final Report

Date/Time: File Return to?

2) 5/3 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$)

20, 252.70

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation

1. S + PS \$

2. Photos

3. Others

TOTAL

13x15 = 195

170 + 195

50

50

62

527



PRI Header Details

Claim No	D18007806MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : TONY DEVAUX)	Survey Location & Contact Details	45 LENG KEE ROAD Mobile: 0 , Phone: 64740853 , Fax: 64304934 EmailId: TONY.DEVAUX@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3060X	TP Vehicle No	FBM387S
PRI Recieved Date	30-10-2018 03:33:47 PM	Surveyor Appointed Date	01-11-2018 03:08:05 PM	Surveyor Accept Date	01-11-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	01-11-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date	Job Remarks	Action
------	-------------	--------

FINAL SUMMARY

Surveyor Final Adjusted Amount	Surveyor Fees	Remarks	

Submit Assessment

MOTOR SURVEY ASSIGNMENT

Date	30-10-2018	Our Ref No. D18007806MFSH
Accident Date	26-10-2018	Claim Type. Third Party
Insured Vehicle	SHC3060X	Third Party Vehicle. FBM387S
Survey Location	45 LENG KEE ROAD	
Contact Person.	TONY DEVAUX	
Contact No.	64740853/ 0	Fax No. 64304934
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 5 November 2018 1:53 PM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007806MFSH/1, FBM 387S
Attachments: FBM 387S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FBM 387S
Date of survey: 2/11/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 1 November 2018 5:06 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007806MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 02/11/2018.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 1 November 2018 3:08 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007806MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18007806MFSH
Our Ref: CS/FCI18019904/R1vd3

Date :5/11/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FBM 387S


We thank you for your instruction on 1/11/2018

Please be informed that we had conducted the inspection of the above mentioned
2/11/2018 at the premises of M/s WEARNES AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$23,201.60
Revised Estimate Amount	: S\$11,417.90
"Check" Items Amount	: S\$10,733.70
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9104A
Vehicle Details	
Vehicle No.:	FBM387S
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	DUCATI
Vehicle Model:	MONSTER 821
Primary Colour:	Grey
Secondary Colour:	Red
Manufacturing Year:	2016
Engine No.:	ZDM821W4G000246
Chassis No.:	ZDMMC00AAHB000225
Maximum Power Output:	-
Open Market Value:	\$12,004.00
Original Registration Date:	16 Jun 2017
First Registration Date:	16 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,101.00
COE Rebate Amount:	\$5,253.00
Total Rebate Amount:	\$5,253.00

The information contained herein is correct as at 05 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/10/2018 15:26
Date Of Accident	26/10/2018 06:45
Exact Location Of Accident	ALONG CECIL ST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBM387S
Insured/Policyholder	
Name Of Registered Owner	FAIRHEAD GARETH WAYNE LOUIS
NRIC No	S7889104A
Email Address	GARETHFAIRHEAD@YAHOO.COM.AU
Mobile Phone No	(LOCAL) +65-85330192
Alternative Phone No	OFFICE-85330192
Vehicle Particulars	
Manufacturer	DUCATI
Model	MONSTER 821
Exact Purpose for which vehicle was being used at time of accident	MOTORCYCLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V06303
Cover Note Number	
Driver	
Name of Driver	FAIRHEAD GARETH WAYNE LOUIS
NRIC No	S7889104A
Date Of Birth	04/07/1978
Occupation	OUTDOOR
Date Of Driving Pass	31/05/2013
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85330192
Fax Number	
Contact Number	OFFICE-85330192
EMail Address	GARETHFAIRHEAD@YAHOO.COM.AU

Address

71 HOLLAND ROAD #01-03 SINGAPORE 258869

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I was riding straight on my lane when suddenly veh b came out from capital tower carpark driveway. I horned to alert him of my oncoming. However, he swerve back into mY lane and collided with mY bike. My bike was damaged and I suffer slight bruises and abrasion on my left.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC3060X

Vehicle Make/Model/Colour HYUNDAI/AE IONIQ HEV 1.6 DCT

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver YEO BOK CHUAN JAMES

NRIC/Passport Number S1333459E

Contact Number 96702578

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name FAIRHEAD GARETH WAYNE LOUIS

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBM387S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - i. I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Signature]
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
REPORTING OFFICER
Md Sharil

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

I was riding straight on my lane when suddenly veh b came out from capital tower carpark driveway. I horned to alert him of my oncoming. However, he swerve back into my lane and collided with my bike. My bike was damaged and I suffer slight bruises and abrasion on my left.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

27 October 2018 at 10:34 AM

Date/Time:

27 October 2018 at 10:34 AM

SERVICE ESTIMATE

97201 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Gareth Fairhead
2a Cornwall Gardens
#03-19 The Cornwall
Singapore

Singapore 269678

Closed by : Tony Alfred Desire D
Svc Consultant : 0648
Remarks : Mr Gareth Fairhead

Inv.No. .. : D 0 Page 1
Inv.date .. : 29/10/2018
WIP No. .. : 35456
Veh. In/Out:
*Tel.No. .. : Mobile: 85330192
Reg.No. .. : FBM387S / New M
Reg.date .. :
Mileage .. : 0
Chassis No.: ZDMMC00AAHB000225
Variant... : M821

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
NOTES	NOTES				0.00	0			S
	To provide repair estimate								
	To repair damaged parts caused by accident							4000	✓
DUCO-1	To replace damaged parts caus				4800.00	0		4800.00	S
	REAR-VIEW MIRRO <i>SCA</i>			1.0 EA	123.00			123.00	S ✓
	SCREW TCEIF M8X <i>NE</i>			1.0 EA	4.80			4.80	S ✓
	SPRING WASHER 8 <i>NE</i>			1.0 EA	0.60			0.60	S ✓
	HANDLEBAR <i>RA</i>			1.0 EA	167.90			167.90	S ✓
	THROTTLE CONTRO <i>CA</i>			1.0 EA	419.60			419.60	S ✓
	BALANCER SET, H <i>MS</i>			1.0 EA	1.70			1.70	S ✓
	CLUTCH LEVER <i>SCA</i>			1.0 EA	59.90			59.90	S ✓
	REAR FRAME COMP <i>? RA</i>			1.0 EA	973.50			973.50	S ✓
	VIBRATION DAMPE			1.0 EA	2.50			2.50	S ✓
	RUBBER PAD			2.0 EA	1.50			3.00	S ✓
	CLAMP TUCKER			3.0 EA	1.70			5.10	S ✓
	GUARD <i>? NE</i>			1.0 EA	3.50			3.50	S ✓
	SCREW, SPECIAL			2.0 EA	12.10			24.20	S ✓
	SCREW			2.0 EA	16.00			32.00	S ✓
	SPACER			2.0 EA	9.70			19.40	S ✓
	RUBBER PAD			6.0 EA	8.20			49.20	S ✓
	SHIM TH. 0.3			3.0 EA	40.80			122.40	S ✓
	SCREW M 10 X 60			1.0 EA	23.20			23.20	S ✓
	SCREW			4.0 EA	12.30			49.20	S ✓
	LOCK WASHER			4.0 EA	10.50			42.00	S ✓

SERVICE ESTIMATE

97201 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Gareth Fairhead
2a Cornwall Gardens
#03-19 The Cornwall
Singapore
Singapore 269678
Singapore 269678

Inv.No. . . : D 0 Page 2
Inv.date . . : 29/10/2018
WIP No. . . : 35456
Veh. In/Out:
*Tel.No. . . : Mobile: 85330192
Reg.No. . . : FBM387S / New M
Reg.date . . :
Mileage . . : 0
Chassis No.: ZDMMC00AAHB000225
Variant... : M821

Closed by : Tony Alfred Desire D
Svc Consultant : 0648
Remarks : Mr Gareth Fairhead

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	WATER COOLER AS <i>PA</i>			1.0 EA	1499.50			1499.50 S	✓
	RADIATOR CAP <i>X Svc</i>			1.0 EA	41.80			41.80 S	✓
	R.H. AIR DEFLEC <i>etc</i>			1.0 EA	385.50			385.50 S	✓
	COVER <i>DE</i>			1.0 EA	36.90			36.90 S	✓
	AIR SHROUD CYLID <i>DE</i>			1.0 EA	22.20			22.20 S	✓
	COVER <i>DE</i>			1.0 EA	28.30			28.30 S	✓
	RUBBER PAD <i>na</i>			8.0 EA	8.20			65.60 S	✓
	SENSOR, TEMPERA <i>? ✓ na</i>			1.0 EA	79.70			79.70 S	✓
	SCREW <i>na</i>			4.0 EA	12.30			49.20 S	✓
	SEAL RING <i>na</i>			2.0 EA	37.30			74.60 S	✓
	CLAMP 61-20 MM <i>cut</i>			2.0 EA	30.90			61.80 S	✓
	BRACKET <i>✓ na</i>			1.0 EA	34.40			34.40 S	✓
	HOSE PUMP/COOLE <i>cut</i>			1.0 EA	42.00			42.00 S	✓
	CLAMP 20-35 MM <i>na</i>			4.0 EA	5.60			22.40 S	✓
	INUGEL OPTIMAL <i>na</i>			3.0 EA	21.00			63.00 S	✓
	FUEL TANK, GRAY <i>na</i>			1.0 EA	3310.00			3310.00 S	✓
	EMBLEM DUCATI <i>na</i>			2.0 EA	29.50			59.00 S	✓
	GASKET KIT <i>na</i>			1.0 EA	62.40			62.40 S	✓
	GASKET <i>na</i>			1.0 EA	4.80			4.80 S	✓
	ITALIAN FLAG DE <i>na</i>			1.0 EA	27.10			27.10 S	✓
	GUARD			1.0 EA	24.60			24.60 S	✓
	RUBBER SECTION <i>} na</i>			1.0 EA	36.90			36.90 S	✓
	PAD, FUEL TANK			2.0 EA	12.30			24.60 S	✓
	UNION			2.0 EA	19.80			39.60 S	✓

SERVICE ESTIMATE

97201 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Gareth Fairhead
2a Cornwall Gardens
#03-19 The Cornwall
Singapore
Singapore 269678
Singapore 269678

Inv.No. .. : D 0 Page 3
Inv.date .. : 29/10/2018
WIP No. .. : 35456
Veh. In/Out:
*Tel.No. .. : Mobile: 85330192
Reg.No. .. : FBM387S / New M
Reg.date .. :
Mileage .. : 0
Chassis No.: ZDMMC00AAHB000225
Variant... : M821

Closed by : Tony Alfred Desire D
Svc Consultant : 0648
Remarks : Mr Gareth Fairhead

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	TANK, WATER RES <i>X sur</i>			1.0 EA	173.80			173.80	S
	MARKING PLATE <i>? ✓ ne ✓</i>			1.0 EA	44.30			44.30	S
	VIBRATION DAMPE			4.0 EA	8.40			33.60	S
	BUSH ✓			5.0 EA	5.30			26.50	S
	SCREW, SPECIAL <i>? ✓ ne ✓</i>			3.0 EA	15.60			46.80	S
	PLUG ✓			2.0 EA	9.10			18.20	S
	CUSHION, SEAT.			1.0 EA	6.20			6.20	S
	LEFT FORK LEG A <i>? ✓ ne ✓</i>			1.0 EA	1352.00			1352.00	S
	RIGHT FORK LEG <i>? ✓ ne ✓</i>			1.0 EA	1352.00			1352.00	S
	REFLECTOR, ADHE <i>? ✓ ne ✓</i>			2.0 EA	8.90			17.80	S
	FOOTREST PIN <i>ne ✓</i>			1.0 EA	4.20			4.20	S
	CIRCLIP <i>ne ✓</i>			1.0 EA	0.20			0.20	S
	LEFT FOOTREST <i>sea ✓</i>			1.0 EA	61.50			61.50	S
	FOOT PEG RUBBER <i>cut ✓</i>			1.0 EA	12.30			12.30	S
	SPRING, FOOTRES <i>ne ✓</i>			1.0 EA	3.10			3.10	S
	GEARCHANGE LEVE <i>Bro ✓</i>			1.0 EA	135.20			135.20	S
	BUSH			1.0 EA	5.30			5.30	S
	O-RING			1.0 EA	0.30			0.30	S
	PIN PEDAL <i>ne ✓</i>			1.0 EA	7.90			7.90	S
	WASHER 8.2X20X1			1.0 EA	1.60			1.60	S
	COVER PEDAL <i>M83 ✓</i>			1.0 EA	11.80			11.80	S
	BALL JOINT, RIG <i>ne ✓</i>			1.0 EA	24.60			24.60	S
	COMPLETE SWINGA <i>? X sur</i>			1.0 EA	1966.50			1966.50	S
	REAR WHEEL SPIN <i>? X sur</i>			1.0 EA	174.70			174.70	S

SERVICE ESTIMATE

97201 - C00018
 Mr Gareth Fairhead
 2a Cornwall Gardens
 #03-19 The Cornwall
 Singapore
 Singapore 269678
 Singapore 269678

SL: SERVICE/PARTS SALES - DUCATI

Inv.No. .. : D 0 Page 4
 Inv.date .. : 29/10/2018
 WIP No. .. : 35456
 Veh. In/Out:
 *Tel.No. .. : Mobile: 85330192
 Reg.No. .. : FBM387S / New M
 Reg.date .. :
 Mileage .. : 0
 Chassis No.: ZDMMC00AAHB000225
 Variant... : M821

Closed by : Tony Alfred Desire D
 Svc Consultant : 0648
 Remarks : Mr Gareth Fairhead

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	REAR WHEEL RIM	✓	✓	1.0 EA	1996.00			1996.00	S
	FRONT BRAKE DIS	✓	✓	2.0 EA	485.70			971.40	S
	STEERING HEAD	✓	✓	1.0 EA	430.20			430.20	S
	CUSHION, HANDLE	✓	✓	2.0 EA	20.40			40.80	S
	SEAL RING	✓	✓	2.0 EA	10.60			21.20	S
	BEARING, STEERI	✓	✓	2.0 EA	84.20			168.40	S
	WASHER	✓	✓	1.0 EA	3.90			3.90	S
	STEERING HEAD B	✓	✓	1.0 EA	634.30			634.30	S
	WATER PUMP COVE	✓	✓	1.0 EA	258.20			258.20	S
	GASKET 6X12X1 D	✓	✓	2.0 EA	0.80			1.60	S
	LIQUID GASKET	✓	✓	1.0 EA	31.20			31.20	S
	SEAL KIT	✓	✓	1.0 EA	82.80			82.80	S
	SCREW TBEI M6X1	✓	✓	6.0 EA	3.10			18.60	S
	SCREW, SPECIAL	✓	✓	1.0 EA	40.00			40.00	S

RASUL
Hp 90010068
5 clays
P/P
02/11/18 @ 16 40
Repair by paint

[Signature]
5/11/18

23,413.40

=====
 Amount 23,201.60
 Amount 23,201.60
 GST @ 7 % 1,624.11
 Total Amount 24,825.70
 Less Amt Paid 0.00
 Nett Amount 24,825.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour Total 4,800.00
 Parts Total 18,401.60
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
 Service Estimates are valid for 10 days from the above date.
 This is a computer generated invoice, no signature is required.

SERVICE ESTIMATE

97201 - F00003 SL: FIRST CAPITAL INSURANCE LTD

Mr Gareth Fairhead
2a Cornwall Gardens
#03-19 The Cornwall
Singapore

Singapore 269678

Closed by : Tony Alfred Desira D
Svc Consultant : 0648
Remarks : Mr Gareth Fairhead

Inv.No. ... : D 0 Page 1
Inv.date ... : 24/01/2019
WIP No. ... : 35456
Veh. In/Out:
*Tel.No. ... : Mobile: 85330192
Reg.No. ... : FBM387S / New M
Reg.date ... :
Mileage ... : 6,545
Chassis No.: ZDMMC00AAHB000225
Variant... : M821

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
NOTES	NOTES				0.00	0			S
	To provide repair estimate								
	To repair damaged parts caused by accident								
DUC0-1	To replace damaged parts caus		Ch		4000.00	0		4000.00	S
	REAR-VIEW MIRRO			1.0 EA	123.00			123.00	S
	SCREW TCEIF M8X			1.0 EA	4.80			4.80	S
	SPRING WASHER 8			1.0 EA	0.60			0.60	S
	HANDLEBAR			1.0 EA	167.90			167.90	S
	THROTTLE CONTRD			1.0 EA	419.60			419.60	S
	BALANCER SET, H			1.0 EA	1.70			1.70	S
	CLUTCH LEVER			1.0 EA	59.90			59.90	S
	REAR FRAME COMP			1.0 EA	973.50			973.50	S
	VIBRATION DAMPE			1.0 EA	2.50			2.50	S
	RUBBER PAD			2.0 EA	1.50			3.00	S
	CLAMP TUCKER			3.0 EA	1.70			5.10	S
	GUARD			1.0 EA	3.50			3.50	S
	SCREW, SPECIAL			2.0 EA	12.10			24.20	S
	SCREW			2.0 EA	16.00			32.00	S
	SPACER			2.0 EA	9.70			19.40	S
	RUBBER PAD			6.0 EA	8.20			49.20	S
	SHIM TH. 0.3			3.0 EA	40.80			122.40	S
	SCREW M 10 X 60			1.0 EA	23.20			23.20	S
	SCREW			4.0 EA	12.30			49.20	S
	LOCK WASHER			4.0 EA	10.50			42.00	S

SERVICE ESTIMATE

97201 - F00003 SL: FIRST CAPITAL INSURANCE LTD

Mr Gareth Fairhead
2a Cornwall Gardens
#03-19 The Cornwall
Singapore
Singapore 269678
Singapore 269678

Inv.No. : 0 Page 2
Inv.date : 24/01/2019
WIP No. : 35456
Veh. In/Out:
*Tel.No. : Mobile: 85330192
Reg.No. : FBM387S / New M
Reg.date :
Mileage : 6,645
Chassis No. : ZDMMCO0AAMB000225
Variant... : M821

Closed by : Tony Alfred Desire D
Svc Consultant : 0648
Remarks : Mr Gareth Fairhead

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	WATER COOLER AS			1.0 EA	1499.50			1499.50	S
	R.H. AIR DEFLEC			1.0 EA	385.50			385.50	S
	COVER			1.0 EA	36.90			36.90	S
	AIR SHROUD CYLI			1.0 EA	22.20			22.20	S
	COVER			1.0 EA	28.30			28.30	S
	RUBBER PAD			8.0 EA	8.20			65.60	S
	SENSOR, TEMPERA			1.0 EA	79.70			79.70	S
	SCREW			4.0 EA	12.30			49.20	S
	SEAL RING			2.0 EA	37.30			74.60	S
	CLAMP 61-20 MM			2.0 EA	30.90			61.80	S
	BRACKET			1.0 EA	34.40			34.40	S
	HOSE PUMP/COOLE			1.0 EA	42.00			42.00	S
	CLAMP 20-35 MM			4.0 EA	5.60			22.40	S
	INUGEL OPTIMAL			3.0 EA	21.00			63.00	S
	FUEL TANK, GRAY			1.0 EA	3310.00			3310.00	S
	EMBLEM DUCATI			2.0 EA	29.50			59.00	S
	GASKET KIT			1.0 EA	62.40			62.40	S
	GASKET			1.0 EA	4.80			4.80	S
	ITALIAN FLAG DE			1.0 EA	27.10			27.10	S
	GUARD			1.0 EA	24.60			24.60	S
	RUBBER SECTION			1.0 EA	36.90			36.90	S
	PAD, FUEL TANK			2.0 EA	12.30			24.60	S
	UNION			2.0 EA	19.80			39.60	S
	MARKING PLATE			1.0 EA	44.30			44.30	S

SERVICE ESTIMATE

97201 - F00003 SL: FIRST CAPITAL INSURANCE LTD

Mr Gareth Fairhead
2a Cornwall Gardens
#03-19 The Cornwall
Singapore
Singapore 269678
Singapore 269678

Inv.No. : D 0 Page 3
Inv.date : 24/01/2019
WIP No. : 35456
Veh. In/Out:
*Tel.No. : Mobile: 85330192
Reg.No. : FBM387S / Naw M
Reg.date :
Mileage : 6,645
Chassis No.: ZDMMC00AAHB000225
Variant... : M821

Closed by : Tony Alfred Desire D
Svc Consultant : 0648
Remarks : Mr Gareth Fairhead

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	VIBRATION DAMPE			4.0 EA	8.40			33.60	S
	BUSH			5.0 EA	5.30			26.50	S
	SCREW, SPECIAL			3.0 EA	15.60			46.80	S
	PLUG			2.0 EA	9.10			18.20	S
	CUSHION, SEAT			1.0 EA	6.20			6.20	S
	LEFT FORK LEG A			1.0 EA	1352.00			1352.00	S
	RIGHT FORK LEG			1.0 EA	1352.00			1352.00	S
	REFLECTOR, ADHE			2.0 EA	8.90			17.80	S
	FOOTREST PIN			1.0 EA	4.20			4.20	S
	CIRCLIP			1.0 EA	0.20			0.20	S
	LEFT FOOTREST			1.0 EA	61.50			61.50	S
	FOOT PEG RUBBER			1.0 EA	12.30			12.30	S
	SPRING, FOOTRES			1.0 EA	3.10			3.10	S
	GEARCHANGE LEVE			1.0 EA	135.20			135.20	S
	BUSH			1.0 EA	5.30			5.30	S
	O-RING			1.0 EA	0.30			0.30	S
	PIN PEDAL			1.0 EA	7.90			7.90	S
	WASHER 8.2X20X1			1.0 EA	1.60			1.60	S
	COVER PEDAL			1.0 EA	11.80			11.80	S
	BALL JOINT, RIG			1.0 EA	24.60			24.60	S
	REAR WHEEL RIM			1.0 EA	1996.00			1996.00	S
	FRONT BRAKE DIS			2.0 EA	485.70			971.40	S
	STEERING HEAD			1.0 EA	430.20			430.20	S
	CUSHION, HANDLE			2.0 EA	20.40			40.80	S

SERVICE ESTIMATE

97201 - F00003 SL: FIRST CAPITAL INSURANCE LTD

Mr Gareth Fairhead
 2a Cornwall Gardens
 #03-19 The Cornwall
 Singapore
 Singapore 269678
 Singapore 269678

Inv.No. . . : D 0 Page 4
 Inv.date . : 24/01/2019
 WIP No. . . : 35456
 Veh. In/Out:
 Tel.No. . . : Mobile: 85330192
 Reg.No. . . : FBM387S / New M
 Reg.date . :
 Mileage . . : 6,645
 Chassis No.: ZDMMC00AAHB000225
 Variant... : MB2i

Closed by : Tony Alfred Desira D
 Svc Consultant : 0648
 Remarks : Mr Gareth Fairhead

Op No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	SEAL RING			2.0 EA	10.60			21.20	0
	BEARING, STEERI			2.0 EA	84.20			168.40	0
	STEERING HEAD B			1.0 EA	634.30			634.30	0
	WATER PUMP COVE			1.0 EA	258.20			258.20	0
	GASKET 6X12X1 D			2.0 EA	0.80			1.60	0
	LIQUID GASKET			1.0 EA	31.20			31.20	0
	SEAL KIT			1.0 EA	82.80			82.80	0
	SCREW TBEI M6X1			6.0 EA	3.10			18.60	0
	SCREW, SPECIAL			1.0 EA	40.00			40.00	0
	CLAMP 16-27 MM			2.0 EA	4.70			9.40	0
	WHEEL RUNNER BU			5.0 EA	22.20			111.00	0
	SEAL RING			1.0 EA	18.40			18.40	0
	GUARD			1.0 EA	3.50			3.50	0
	SEAT SUPPORT			1.0 EA	57.80			57.80	0
	SCREW			3.0 EA	0.90			2.70	0
	SCREW			6.0 EA	1.50			9.00	0

(A)

Amount 20,252.70
 Amount 20,252.70
 GST @ 7 % 1,417.69
 Total Amount 21,670.39
 Less Amt Paid 0.00
 Nett Amount 21,670.39

Labour Total 4,000.00
 Parts Total 16,252.70
 Package Total 0.00

GST: S=StdRated, O=OutOfScope; Z=ZeroRated
 Service Estimates are valid for 10 days from the above date.
 This is a computer generated invoice, no signature is required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 5 March 2019 4:01 PM
To: 'Tony Alfred Desire Devaux'
Cc: SUR; Benjamin Ong Ban Su
Subject: RE: Third party claim between FBM387S & SHC3060X

Dear Tony,

WITHOUT PREJUDICE

Confirmed finalize amount \$20,252.70 before GST @ 5 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>
Sent: Thursday, 24 January 2019 11:24 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>; Benjamin Ong Ban Su <benjamin.ong@wearnes.com>
Subject: RE: Third party claim between FBM387S & SHC3060X

Dear Veron,

Please find in attach the documents regarding FBM387S

Final invoice

Supplementary

LOD

LOA

Kindly let me know if you need anything else

Kind regards

Tony Devaux
Service Consultant



Wearnes Automotive Pte Ltd
45 Leng Kee Road Singapore 159103
F (65) 6474 0853 D (65) 6430 4934
www.wearnesauto.com tony.devaux@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, 8 January 2019 4:04 PM
To: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Third party claim between FBM387S & SHC3060X

Dear Tony,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, 3 December 2018 2:50 PM
To: 'Tony Alfred Desire Devaux' <tony.devaux@wearnes.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Third party claim between FBM387S & SHC3060X

Dear Tony,

Please refer to First Capital OIC May Chua.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>
Sent: Monday, 3 December 2018 2:30 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: Third party claim between FBM387S & SHC3060X

Dear Veron,

I'm still waiting for the authorisation to repair, can you please let me know?

Kind regards

Tony Devaux
Service Consultant



Wearnes Automotive Pte Ltd
45 Leng Kee Road Singapore 159103
F (65) 6474 0853 D (65) 6430 4934
www.wearnesauto.com tony.devaux@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 3 December 2018 11:38 AM
To: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Third party claim between FBM387S & SHC3060X

Dear Tony,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>
Sent: Tuesday, 30 October 2018 3:59 PM
To: Motor Claims <MotorClaims@msfirstcapital.com.sg>
Subject: FW: Third party claim between FBM387S & SHC3060X

Dear claim department,

We understood that you are the insurer of the vehicle SHC3060X.

We would like to enquire a survey of the vehicle FBM387S which is ready for survey in our premises at 45 leng kee road.

Please find in attach the GIA report and Quotation.

Kind regards

Tony Devaux
Service Consultant



Wearnes Automotive Pte Ltd
45 Leng Kee Road Singapore 159103
F (65) 6474 0853 D (65) 6430 4934
www.wearnesauto.com tony.devaux@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019904/R1vd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3060X	Veh. Inspected	FBM 387S	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18007806MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	01/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	DUCATI MONSTER 821	c.c	821	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZDMMC00AAHB000225	Colour	MULTI COLOUR	
Odometer	6645	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	PIRELLI	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/60Z R17	PIRELLI	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2018	Inspection Date	02/11/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 387S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR-VIEW MIRRO (SN)	SCRATCHED	123.00	123.00
1	SCREW TCEIF M8X (SN)	NECESSARY	4.80	4.80
1	SPRING WASHER 8 (SN)	NECESSARY	0.60	0.60
1	HANDLEBAR (SN)	BENT	167.90	167.90
1	THROTTLE CONTRO (SN)	CUT	419.60	419.60
1	BALANCER SET, H (SN)	MISSING	1.70	1.70
1	CLUTCH LEVER (SN)	SCRATCHED	59.90	59.90
1	REAR FRAME COMP (SN)	BENT	973.50	973.50
1	VIBRATION DAMPE (SN)	NECESSARY	2.50	2.50
2	RUBBER PAD (SN)	NECESSARY	3.00	3.00
3	CLAMP TUCKER (SN)	NECESSARY	5.10	5.10
1	GUARD (SN)	NECESSARY	3.50	3.50
2	SCREW, SPECIAL (SN)	NECESSARY	24.20	24.20
2	SCREW (SN)	NECESSARY	32.00	32.00
2	SPACER (SN)	NECESSARY	19.40	19.40
6	RUBBER PAD (SN)	NECESSARY	49.20	49.20
3	SHIM TH. 0.3 (SN)	NECESSARY	122.40	122.40
1	SCREW M 10 X 60 (SN)	NECESSARY	23.20	23.20
4	SCREW (SN)	NECESSARY	49.20	49.20
4	LOCK WASHER (SN)	NECESSARY	42.00	42.00
1	WATER COOLER AS (SN)	BENT	1,499.50	1,499.50
1	RADIATOR CAP (SN)	SERVICEABLE	41.80	-
1	R.H. AIR DEFLEC (SN)	DEFORMED	385.50	385.50
1	COVER (SN)	DEFORMED	36.90	36.90
1	AIR SHROUD CYLI (SN)	DEFORMED	22.20	22.20
1	COVER (SN)	DEFORMED	28.30	28.30
8	RUBBER PAD (SN)	NECESSARY	65.60	65.60
1	SENSOR, TEMPERA (SN)	NOT WORKING	79.70	79.70
4	SCREW (SN)	NECESSARY	49.20	49.20
2	SEAL RING (SN)	NECESSARY	74.60	74.60
2	CLAMP 61-20 MM (SN)	CUT	61.80	61.80

Report Ref No. CS/FCI18019904/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACKET (SN)	NECESSARY	34.40	34.40
1	HOSE PUMP / COOLE (SN)	CUT	42.00	42.00
4	CLAMP 20-35MM (SN)	NECESSARY	22.40	22.40
3	INUGEL OPTIMAL (SN)	NECESSARY	63.00	63.00
1	FUEL TANK, GRAY (SN)	BENT	3,310.00	3,310.00
2	EMBLEM DUCATI (SN)	NECESSARY	59.00	59.00
1	GASKET KIT (SN)	NECESSARY	62.40	62.40
1	GASKET (SN)	NECESSARY	4.80	4.80
1	ITALIAN FLAG DE (SN)	NECESSARY	27.10	27.10
1	GUARD (SN)	NECESSARY	24.60	24.60
1	RUBBER SECTION (SN)	NECESSARY	36.90	36.90
2	PAD, FUEL TANK (SN)	NECESSARY	24.60	24.60
2	UNION (SN)	NECESSARY	39.60	39.60
1	TANK, WATER RES (SN)	SERVICEABLE	173.80	-
1	MARKING PLATE (SN)	NECESSARY	44.30	44.30
4	VIBRATION DAMPE (SN)	NECESSARY	33.60	33.60
5	BUSH (SN)	NECESSARY	26.50	26.50
3	SCREW, SPECIAL (SN)	NECESSARY	46.80	46.80
2	PLUG (SN)	NECESSARY	18.20	18.20
1	CUSHION, SEAT (SN)	NECESSARY	6.20	6.20
1	LEFT FORK LEG A (SN)	BENT	1,352.00	1,352.00
1	RIGHT FORK LEG (SN)	BENT	1,352.00	1,352.00
2	REFLECTOR, ADHE (SN)	NECESSARY	17.80	17.80
1	FOOTREST PIN (SN)	NECESSARY	4.20	4.20
1	CIRCLIP (SN)	NECESSARY	0.20	0.20
1	LEFT FOOTREST (SN)	SCRATCHED	61.50	61.50
1	FOOT PEG RUBBER (SN)	CUT	12.30	12.30
1	SPRING FOOTRES (SN)	NECESSARY	3.10	3.10
1	GEARCHANGE LEVE (SN)	BROKEN	135.20	135.20
1	BUSH (SN)	NECESSARY	5.30	5.30
1	O-RING (SN)	NECESSARY	0.30	0.30
1	PIN PEDAL (SN)	NECESSARY	7.90	7.90
1	WASHER 8.0X20X1 (SN)	NECESSARY	1.60	1.60

Report Ref No. CS/FCI18019904/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER PEDAL (SN)	MISSING	11.80	11.80
1	BALL JOINT, RIG (SN)	NECESSARY	24.60	24.60
1	COMPLETE SWINGA (SN)	SERVICEABLE	1,966.50	-
1	REAR WHEEL SPIN (SN)	SERVICEABLE	174.70	-
1	REAR WHEEL RIM (SN)	BENT	1,996.00	1,996.00
2	FRONT BRAKE DIS (SN)	BENT	971.40	971.40
1	STEERING HEAD (SN)	BENT	430.20	430.20
2	CUSHION, HANDLE (SN)	NECESSARY	40.80	40.80
2	SEAL RING (SN)	NECESSARY	21.20	21.20
2	BEARING, STEERI (SN)	NECESSARY	168.40	168.40
1	WASHER (SN)	NOT NECESSARY	3.90	-
1	STEERING HEAD B (SN)	BENT	634.30	634.30
1	WATER PUMP COVE (SN)	SCRATCHED	258.20	258.20
2	GASKET 6X12X1 D (SN)	NECESSARY	1.60	1.60
1	LIQUID GASKET (SN)	NECESSARY	31.20	31.20
1	SEAL KIT (SN)	NECESSARY	82.80	82.80
6	SCREW TBEI M6X1 (SN)	NECESSARY	18.60	18.60
1	SCREW, SPECIAL (SN)	NECESSARY	40.00	40.00
2	CLAMP 16-27MM (SN) (ADDITIONAL)	NECESSARY	9.40	9.40
5	WHEEL RUNNER BUSH (SN) (ADDITIONAL)	NECESSARY	111.00	111.00
1	SEAL RING (SN) (ADDITIONAL)	NECESSARY	18.40	18.40
1	GUARD (SN) (ADDITIONAL)	NECESSARY	3.50	3.50
1	SEAT SUPPORT (SN) (ADDITIONAL)	NECESSARY	57.80	57.80
3	SCREW (SN) (ADDITIONAL)	NECESSARY	2.70	2.70
6	SCREW (SN) (ADDITIONAL)	NECESSARY	9.00	9.00
			18,613.40	16,252.70
	LABOUR			
	TO REPLACE DAMAGED PARTS CAUS.		4,800.00	4,000.00
			4,800.00	4,000.00
GRAND TOTAL			23,413.40	20,252.70
RECOMMENDED COST OF REPAIRS				20,252.70

Report Ref No. CS/FCI18019904/R1vd3e2



Report Ref No. CS/FCI18019904/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.