

ASS. REC. BY:

REF:

CS/CTLI8020008/Uuber

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Catherine Tina

of

CTI

Date/Time:

02/11/2018 4:40pm

Estimated Cost:

Bill to:

DI

/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

SKW 629K

To Inspect Vehicle No:

Insured:

at Workshop m/s

Kah motor

Tel:

81006306

of

15 Ubi Rd 4

Policy No:

DMP(SN 166A89180)

Claim No:

SNM18005189C01

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

D.O.A.

31/07/018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

05-11-2018 11:11am

Person Contacted:

Amy

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 629K - CS/CTLI8012047/Civil302

DFA: 30062018

5/11/18

Revert via merimen

5/11/18

Recd approved \$15,849.84 from Alfred by merimen

5/11/18

Informed Amy c/a ex \$1000 by email

Insurance (name)

REF:

CTI/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKW 629K
at Workshop m/s Boh motor

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

966

IDAC Accident Report:

Consistent? : Yes or No

GIA PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LIAB 62832

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW 629K

Yr Regit:

10/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Odyssey

C.C

2358

Colour:

White

Acc

Insured / Std / NI / NA

Sp. Reading

18962

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRC1890FC 203162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215-55-217

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

no x x x

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/10/18

D.O.I.

5/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rp. & n/s Rp.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Final report, 24/12

15/11/18 confirmed final fig \$14003.42 with my

15/11/18 final fig \$15,003.40 confirmed by email (Red 2805.52, 16/11)

15/11/2018

RECEIVED 1.5. NOV 2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2) 15/11 - typist

Report Format:

men men

Lump Sum / I.B.I: (\$

15,003.40

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

220

Transportation:

1 \$ + RS \$

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 16:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG DJONI								
Vehicle Reg. No.:	SKW629K	Date of Loss:	31/10/2018 00:00 - :59						
Claim Type:	OD / SNM18D05189C01	Policy/Cover Note No.:	DMPCSN1669891802 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 5 November 2018 4:48 PM
To: Ary Chua; SUR
Subject: SKW 629K-DOA: 31/10/2018 (CHINA TAIPING OD)

Dear Ary,

As instructed by our client , please proceed to repair the **insured vehicle SKW 629K (Excess S1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKW629K (SNM18D05189C01)**

OD

Oct 31 2018 12:00AM

[NG DJONI]

Kah Motor Co Sdn Bhd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **05/11/2018 16:44 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15849.84) - SKW629K - Claim Handler: Catherine Thia

Approved:15849.84:Proceed to authorize repairs UP TO \$15,849.84 before EXCESS of \$1,000.00. Re-inspection of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 05 Nov 2018

Preliminary Advice

Vehicle No	: SKW629K	Accident Date	: 31/10/2018
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1669891802
Assignment Date	: 02/11/2018	Excess	: S\$1,000.00
Date of Inspection	: 05/11/2018	Est. Duration of Repair	: 7.00
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,658.56
Revised Amount	:S\$	13,310.60
Check Items (Estimated)	:S\$	2,539.24
Total	:S\$	15,849.84

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	62,832.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,168.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

()

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6554J

Vehicle Details

Vehicle No.:	SKW629K
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K24W71011552
Chassis No.:	JHMRC1890FC203162
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,090.00
Original Registration Date:	15 Oct 2015
First Registration Date:	15 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$29,926.00 14963

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2025
PARF Rebate Amount:	\$22,444.00

Intended COE Rebate Details

COE Expiry Date:	14 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$40,388.00
Total Rebate Amount:	\$62,832.00

The information contained herein is correct as at 05 Nov 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

UNI QLO ARIGATO FAN FEST!
THANK YOU FOR LETTING US BE PART OF YOUR LIFE 2.11-8.11



EZY ANKLE PAIN
\$39.90 UP \$49.90

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW 7 Series 740Li Sunroof.



Highest Specs. With Director
Passenger Seats, Tip Top Stock
Condition.
Direct Owner StarAd

PRIME MOTOR

ICHENG YONG CREDIT ENTERPRISES PTE LTD
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Make


Browse by Category

Sort by Date Posted

19 vehicles

Honda Odyssey

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Ty
Search Selection	Honda Odyssey	Any	Any	2015	Any	Any	Any
	Honda Odyssey 2.4A EXV-S	\$106,999	\$13,470 /yr	03-Sep-2015	2,356 cc	51,800 km	MF
1 Female Owner Only! Well Maintained Under Shade, Regularly Serviced At Honda, New Set Of Tyres. Perfect For Small-large Families To Drive Luxury! Powerful Engine Gives Yo U An Amazing Driving Expe...							
Posted: 05-Nov-2018 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							
	Honda Odyssey 2.4A EXV-S	\$99,800	\$11,810 /yr	17-Dec-2015	2,356 cc	59,000 km	MF
Flawless Condition, Classic Black. Feel The Luxurious Class Of All New Odyssey Model. Quite, Smooth And Awesome Drive. Still In New Condition Agent Maintained By Kah Motors. View To Believe. Hig...							
Starise Automobile							
Posted: 31-Oct-2018 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							
	Honda Odyssey 2.4A EXV-S	\$99,800	\$12,140 /yr	30-Sep-2015	2,356 cc	59,000 km	MF
Price Negotiable For Sincere Buyer, Agent Car Unit And Still Under Warranty! Very Well Taking Care By Ex Owner, Regularly Serviced, Excellent Exterior And Interior! Full Sized Spacious 7 Seater MPV Wi...							
Posted: 26-Oct-2018 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							
	Honda Odyssey 2.4A EXV-S	\$97,800	\$13,070 /yr	06-Mar-2015	2,356 cc	49,000 km	MF
One Owner, Down Payment \$10000.Vehicle Come With 5 Years Unlimited Mileage Warranty.Excellent Condition, As Good As New.100% Accident Free.Elegant 7 Seaters To Bring Your Family Around, Coupled With A...							
Posted: 26-Oct-2018 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							
	Alloy Screw-on Grille Badge (Mugen)						
Theft resistant as the badge is secured by screws and bolts. Drilling usually not required if the screws can go through the grille.							
More info about this product							
	Honda Odyssey 2.4A EXV-S	\$97,800	\$11,710 /yr	28-Oct-2015	2,356 cc	83,000 km	MF
Cheapest EXV-S Model In Market. Highest Spec Model From Agent's Kah Motor Unit. Fully Agent Maintained Since Day 1, 5 Years Warranty Un Motor. Accident Free. STA And VICOM Evaluation Welcome. F...							
Grande Auto Credit							
ad: 24-Oct-2018 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2018 15:05
Date Of Accident	31/10/2018 10:30
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW629K
Insured/Policyholder	
Name Of Registered Owner	NG DJONI
NRIC No	S7276554J
Email Address	NGDJONI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81989989
Alternative Phone No	OFFICE-81989989

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 ABSOLUTE (RC1) (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1669891802
Cover Note Number	

Driver

Name of Driver	NG DJONI
NRIC No	S7276554J
Date Of Birth	19/05/1972
Occupation	INDOOR
Date Of Driving Pass	14/06/1996
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81989989
Fax Number	
Contact Number	OFFICE-81989989
Email Address	NGDJONI@GMAIL.COM

Address	BLK 260B SENGKANG EAST WAY #13-442
Postcode	S542260
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NOBODY INJURY DURING THE ACCIDENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFE5757U
Vehicle Make/Model/Colour	BMW/520I/BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SCRAMBER
Vehicle Make/Model/Colour	UNKNOWN
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle No

SKW629K

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/ins) packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

15:00pm
01 NOV 2018ARY
ARY CHUA

A = SFE 57574
B = SKW629K
C = Scrambler bike
(unknown #)
Hit & Run

Please continue in Annex E

Vehicle No SKW6291C

Annex E

Describe Circumstances of the Accident

On 31/10/18, around 1030am, I was travelling along
Vinhua Ave 1.

After ascending the slope, a car ^{new} parked at the center of
the road and I have no time to react ~~out~~.

Noticed that the road in front of the car was empty, quite
a distance to the traffic light and he was parking there.

There was a scrambler bike behind me also could not
react and collided onto the back of my vehicle but ride
off without stopping. I could not take down his bike number
as he was too fast

Refer to Police Report No: T/20181031/7023

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

15:00pm
01 NOV 2018



ARY CHUA

Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20181031/7023

1 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20181031/7023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/10/2018 22:56	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: NG DJONI			Address: APT BLK 260B SENGKANG EAST WAY #13-442 SINGAPORE 542260	
ID Type / ID No.: NRIC NO / S7276554J			Contact No.: Home/Office:	Mobile: 81989989
Nationality: INDONESIAN			Email: ngdjoni@gmail.com	
Sex: Male	Age: 46	Date of Birth: 19/05/1972	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class:	

General Information of the Accident

General Information of the Accident:				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 31/10/2018 10:30	Type of Location: Gradient
Location: YISHUN AVENUE 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFE5757U	Car	BMW	520d	Blue	Slightly Damaged	2
SKW629K	Car	HONDA	ODYSSEY 2.4 EXV-S CVT SR	White		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20181031/7023

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20181031/7023

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKW629K	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN1669891802	15/10/2018	14/10/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Lim Lye Huat		ID No.	S1762122Z
Related Vehicle	SFE5757U (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	NG DJONI		ID No.	S7276554J
Related Vehicle	SKW629K (Car)		Contact No.	81989989
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

I was traveling along yishun avenue 1 and it was ascending slope up. When the slope descend, a stationery car SFE5757U suddenly came into my view resulting insufficient time for me to react.

I noticed that there were no cars in front of car plate number SFE5757u, and it was a distance away from the traffic light around 4 car spaces. I did not ask the reason of them parking in the middle of the road, we only exchange contact number and took some photographs.

A scrambler bike following behind me also collided onto the back of my car, and scratched my left front before running off. I could not took down his plate number in time as I was recovering from shock.



**SINGAPORE
POLICE FORCE**



T/20181031/7023

3 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20181031/7023

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20181031/7023

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20181031/7023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
ABDUL KAREEM BIN ABDUL HAGUE
Contact No.: 65476079

Authentication Stamp
NP188

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
31/10/2018 22:56

Classification Of Case:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

NOISE SH
ADDRESS
Cov. Type: C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1958 (Malaysia)

Engine No: K23W71011552 Chassis No: JHNRCL5P012201162	
1. Index Mark and Registration Number of Vehicle	SDW629E
2. Name of Policy Holder	SD BORN
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	15 OCTOBER 2018
4. Date of Expiry of Insurance	14 OCTOBER 2019
5. Persons or Classes of Persons entitled to drive *	NAMED DRIVERS EX SECT. 1 \$21,000.00 ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. 1 - AGE <= 25 \$51,000.00 EX SECT. 1 - AGE >= 26 \$2500.00 * AGE AS AT DATE OF ACCIDENT EX OR MINORSEEN \$5100.00

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY SANCTION OR REGULATION IN THAT REGARD FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.

THE POLICY DOES NOT COVER USE FOR HIRE OR HIRE AND RETURN DRIVING TEST RACING JACK-HAIRING, ROADABILITY TESTS, SMOKE-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$2500 WILL APPLY TO THE THEFTED AND NAMED DRIVERS IN THE EVENT OF TWO SEPARATE CLAIMS AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

RENT PURCHASE CO.: SD BORN LTD AS IT OWNED

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act, 1997 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1962 (Malaysia).
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned by:

Authorized Officer

Authorized Signatory

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

11/10/2018 Car In
69418434 Catherine LK Auto

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004676	Page	1
	3 ANSON ROAD #16-00	Date	: 31. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 31. Oct 2018 3:58:36 PM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: NG DJONI	Survey Date	: HT : +65 8100 6306		
Ins Policy No.	: DMPCSN1669891802	Authorisation Date	: Email : arychua@honda.com.sg		
Date of Accident	: 31/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	OWN DAMAGE CLAIMS-J/NO: 71526						
	POLICY/CLAIMS NO: DMPCSN1669891802						
	OWNER: NG DJONI						
	ACC DATE: 31/10/2018@10.30AM						
	SURVEYED BY: <i>Marcus Chua@lkauto.com</i> 16/14 pm						
	AUTHORIZED ON:						
	REF NO:						

BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60
60400-T6A-310ZZ	BULKHEAD COMPFR.	<i>Self/Sec</i> 1	451.70	✓ 25	338.77	23.71	362.48
60433-T6A-300ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE	<i>Self</i> 1	33.00	✓ 25	24.75	1.76	26.96
60483-T6A-300ZZ	SUPPORT.L.FR.BULKHEAD UPP SIDE	<i>Self</i> 1	35.30	✓ 25	26.47	1.85	28.32
60210-T6A-300ZZ	FENDER COMPR.FR.	<i>Self/Sec</i> 1	537.80	✓ 25	403.35	28.23	431.58
60260-T6A-300ZZ	FENDER COMPL.FR.	<i>Self/Sec</i> 1	537.80	✓ 25	403.35	28.23	431.58
74150-T6A-000	FENDER ASSYL.FR INNER	<i>Self</i> 1	118.30	X 25	88.72	6.21	94.93
60100-T6A-000ZZ	HOOD COMP	<i>Self</i> 1	658.20	✓ 25	493.65	34.56	528.21
60120-T6A-000ZZ	HINGE COMPR.HOOD	<i>Self</i> 1	46.50	✓ 25	34.87	2.44	37.31
60170-T6A-000ZZ	HINGE COMPL.HOOD	<i>Self</i> 1	46.50	✓ 25	34.87	2.44	37.31
74120-T6A-003	LOCK ASSYHOOD	<i>Self</i> 1	104.10	✓ 25	78.07	5.46	83.53
74141-T6A-010	INSULATORHOOD	<i>Self</i> 1	92.50	✓ 25	69.37	4.86	74.23
80111-T6A-003	CONDENSER COMP	<i>Self/Sec</i> 1	668.50	✓ 25	501.37	35.10	536.47
80341-T6A-003	PIPE COMPRECEIVER	<i>Self</i> 1	173.20	X 25	129.90	9.09	138.99
19010-5X6-J02	RADIATOR COMP	<i>Self/Sec</i> 1	1320.90	✓ 25	990.67	69.35	1060.02
38611-5A4-H02	FAN COMPCOOLING	<i>Self</i> 1	53.10	X 25	39.82	2.79	42.61
38615-5X6-J01	SHROUD COMP	<i>Self</i> 1	82.10	X 25	61.57	4.31	65.88
38616-5X6-J01	MOTORCOOLING FAN	<i>Self</i> 1	316.30	X 25	237.22	16.61	253.83
38619-5X6-J01	HEAT PROTECTORFAN MOTOR	<i>Self</i> 1	8.40	X 25	6.30	0.44	6.74
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	<i>Self</i> 1	2237.20	✓ 25	1677.90	117.45	1795.35
33150-T6A-Q11	HEADLIGHT ASSY.L.WITH LED	<i>Self</i> 1	2237.20	✓ 25	1677.90	117.45	1795.35



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 Registration No : SKW629K
 Chassis No : JHMRC1890FC203162
 Model : ODYSSEY 2.4 EXV-S 15YM
 Owner's Name : NG DJONI
 Ins Policy No. : DMPCSN1669891802
 Date of Accident : 31/10/2018

Document No. : SQT18004676 Page 2
 Date : 31. Oct 2018
 Customer No. : WC008
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : K24W71011552
 Date | Time : 31. Oct 2018 3:58:36 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
71104-T6A-921	GARNISHR.FR.BUMPER	1	45.20	25	33.90	2.37	36.27
71109-T6A-921	GARNISHL.FR.BUMPER	1	45.20	25	33.90	2.37	36.27
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	897.00	25	672.75	47.09	719.84
72415-T6A-003	MOLDING ASSYR.FR.CORNER	1	88.00	25	65.77	4.52	69.02
71121-T6A-003	BASEFR.GRILLE	1	165.60	25	124.20	8.69	132.89
71122-T6A-003	MOLDINGFR.GRILLE	1	258.10	25	193.57	13.55	207.12
75700-TA0-A00	EMBLEMFR.	1	25.90	25	19.42	1.36	20.78
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
36560-T6A-J01	CAMERA ASSY.MVC FR.	1	509.80	25	382.35	26.76	409.11
36561-T6A-N01	COVERMVC FR.CAMERA	1	8.10	25	6.07	0.42	6.49
04711-T6A-900ZZ	FACE.FR.BUMPER	1	686.20	25	514.65	36.03	550.68
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	65.80	25	49.35	3.45	52.80
71130-T6A-310ZZ	BEAM COMP.FR.BUMPER	1	286.10	25	214.57	15.02	229.59
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71151-T6A-911	BASEMID GRILLE	1	182.80	25	137.10	9.60	146.70
71152-T6A-921	UPPER MOLDINGMID GRILLE	1	150.60	25	112.95	7.91	120.86
71153-T6A-921	MID MOLDINGMID GRILLE	1	144.20	25	108.15	7.57	115.72
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
91505-TM8-003	CLIP,BUMPER	10	2.00	25	15.00	1.05	16.05
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	26	23.20	25	52.20	3.65	55.85
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
Sum Item					10228.56	715.98	10,944.54

BOSUN	SUNDRIES	1	40.00	20	40.00	2.80	42.80
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	1	100.00		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	120	180.00	12.60	192.60

Printed on 31/10/2018 5:56:29 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. : DMPCSN1669891802

Date of Accident : 31/10/2018

Document No. : SQT18004676 Page 3

Date : 31. Oct 2018

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 31. Oct 2018 3:58:36 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11 X	250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	280.00	250 -	280.00	19.60	299.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	350.00	280 -	350.00	24.50	374.50
BOMISC1	REMOVE, INSTALL & CALIBRATE FRONT CAR VIEW CAMERA(N)	1	350.00	300 -	350.00	24.50	374.50
BKBH12B	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP.	1	2800.00	1960 -	2800.00	196.00	2996.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00	2400 -	2800.00	196.00	2996.00
Sum Labor					7250.00	507.50	7,757.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 17,658.56 1,236.08 18,894.64

Total (Inclusive of GST) 18,894.64

17,808.92

Consultants hence notify

the following:

- Survey before/after spray painting
- Survey damaged part(s) during resurvey
- Survey is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- While final modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 31/10/2018 5:56:29 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WC008 / CHINA TAIPING
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 18964
Engine No: K24W71011552

Document No: SVO18085774
Printed By: ARYCHUA
Order Date: 7. November 2018
Order Time: 8:08:24 AM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 71526 POLICY/CLAIMS NO: DMPCSN1669891701 OWNER: NG DJONI ACC DATE: 31/10/2018@10.30AM SURVEYED BY: MARCUS CHUA(LKKAUTO)05/11/18@14:14PM AUTHORIZED ON: 05/11/2018@16.48PM REF NO:						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	1,000.00		-1,000.00	-70.00	-1,070.00
	SUM EXCESS:				-1,000.00	-70.00	-1,070.00
60400-T6A-310ZZ	BULKHEAD COMPFR.	1	451.70	25	338.77	23.71	362.48
60433-T6A-300ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE	1	35.30	25	26.47	1.85	28.32
60483-T6A-300ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE	1	35.30	25	26.47	1.85	28.32
60210-T6A-300ZZ	FENDER COMPR.FR.	1	537.80	25	403.35	28.23	431.58
60260-T6A-300ZZ	FENDER COMPL.FR.	1	537.80	25	403.35	28.23	431.58
60100-T6A-000ZZ	HOOD COMP	1	658.20	25	493.65	34.56	528.21
60120-T6A-000ZZ	HINGE COMPR.HOOD	1	46.50	25	34.87	2.44	37.31
60170-T6A-000ZZ	HINGE COMPL.HOOD	1	46.50	25	34.87	2.44	37.31
74120-T6A-003	LOCK ASSYHOOD	1	104.10	25	78.07	5.46	83.53
74141-T6A-010	INSULATORHOOD	1	92.50	25	69.37	4.86	74.23
80111-T6A-003	CONDENSER COMP	1	681.90	25	511.42	35.80	547.22
19010-5X6-J02	RADIATOR COMP	1	1,347.30	25	1,010.47	70.73	1,081.20
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2,237.20	25	1,677.90	117.45	1,795.35
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED	1	2,237.20	25	1,677.90	117.45	1,795.35
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	897.00	25	672.75	47.09	719.84
71121-T6A-003	BASEFR.GRILLE	1	165.60	25	124.20	8.69	132.89
71122-T6A-003	MOLDINGFR.GRILLE	1	258.10	25	193.57	13.55	207.12
75700-TA0-A00	EMBLEMFR.	1	25.90	25	19.42	1.36	20.78
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
04711-T6A-900ZZ	FACE,FR.BUMPER	1	686.20	25	514.65	36.03	550.68
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	65.80	25	49.35	3.45	52.80
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	1	286.10	25	214.57	15.02	229.59
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71151-T6A-911	BASEMID GRILLE	1	182.80	25	137.10	9.60	146.70
71152-T6A-921	UPPER MOLDINGMID GRILLE	1	150.60	25	112.95	7.91	120.86
71153-T6A-921	MID MOLDINGMID GRILLE	1	144.20	25	108.15	7.57	115.72
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
91505-TM8-003	CLIP,BUMPER	10	2.00	25	15.00	1.05	16.05
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	25	104.40	7.31	111.71
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
72415-T6A-003	MOLDING ASSYR.FR.CORNER	-1	87.70	25	-65.77	-4.60	-70.37
	SUM PARTS:				9,293.40	650.52	9,943.92
BOSUN	0672	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00

WD=7



KAH MOTOR CO. SDN. BHD.

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Document No: SVO18065774
Printed By: ARYCHUA
Order Date: 7. November 2018
Order Time: 8:08:24 AM
Service Advisor: ARY CHUA WAI NGEE

Code	Description	Qty	Unit Price	Amount	Rate	Total
BOJSE	BODY UNDERSIDE COATING (N) 0672	1	100.00	100.00	7.00	107.00
BML01I	BODY JOINT SEALANT, EXT-YJ	1	120.00	120.00	6.40	126.40
BMC01D	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N) EXT-YJ	1	250.00	250.00	17.50	267.50
BMA01D	REMOVE & INSTALL RADIATOR WITH FITTINGS, PRESSURE TEST COOLING SYSTEM.(N) EXT-YJ	1	280.00	280.00	19.60	299.60
BOMISC1	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS, VACUUM & RECHARGE A/C GAS.(N) EXT-YJ	1	300.00	300.00	21.00	321.00
BKBH12B	REMOVE,INSTALL & CALIBRATE FRONT CAR VIEW CAMERA(N) EXT-YJ	1	1,960.00	1,960.00	137.20	2,097.20
BP06R	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP. STRAIGHTEN ALIGN FR R FRAME & RENEW DAMAGE PARTS. EXT-YBH	1	2,400.00	2,400.00	168.00	2,568.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)					
			SUM LABOUR:	5,530.00	387.10	5,917.10
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60	192.60
			SUM EXT SERVICE:	180.00	12.60	192.60
			TOTAL SGD	14,003.40	980.22	14,983.62
			Total Payable (SGD)			14,983.62

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: S7276554J / NG DJONI
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 18964
Engine No: K24W71011552

Document No: SVO18065774
Printed By: ARYCHUA
Order Date: 7. November 2018
Order Time: 8:08:24 AM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Incd Amount	GST
	OWN DAMAGE CLAIMS-J/NO: 71526 POLICY/CLAIMS NO: DMPCSN1669891701 OWNER: NG DJONI ACC DATE: 31/10/2018@10.30AM SURVEYED BY: MARCUS CHUA(LKKAUTO)05/11/18@14.14PM AUTHORIZED ON: 05/11/2018@16.48PM SUPPLEMENTARY ITEM PARTS & LABOR						
72415-T6A-003	MOLDING ASSYR.FR.CORNER	1		25	87.70	65.77	4.60
					SUM PARTS:	65.77	4.60
					TOTAL SGD	65.77	4.60

Total Payable (SGD)

70.37

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 15 November 2018 10:53 AM
To: 'Ary Chua'; Admin A
Cc: Liew Thye Wui; Faeaz; SUR
Subject: RE: Finalise OD-CT: SKW629K DOA: 31/10/2018@10.30AM

Dear Ary,

Confirmed amount \$15,003.40 before excess \$1000 and GST

No of days: 7 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, 14 November 2018 5:45 PM
To: Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: Finalise OD-CT: SKW629K DOA: 31/10/2018@10.30AM

Hi Marcus Chua,
Kindly Finalise OD-CT: SKW629K DOA: 31/10/2018@10.30AM

Final Repair Costs (include GST)	\$14,003.40 (-EXCESS \$1000) + (\$980.22) = \$14,983.62
Repair Period* (Working Day)	07

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610
E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018		02 Nov 2018 16:40 Edit Adj Rpt	S\$15,003.40 Edit Estimates	S\$15,003.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NG DJONI, ID: 572765543		
Vehicle Reg. No.:	SKW629K	Date of Loss:	31/10/2018 00:00 - :59 [36 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D05189C01	Policy/Cover Note No.:	DMPCSN1669891802 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/11/2018]		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- CHINA_TAIPIING (05/11/2018): Alert - Adj Mandate Approved (S\$15849.84) - SKW629K - Claim Handler: Catherine T...

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW629K (SNM18D05189C01)

OD

Oct 31 2018 12:00AM

[NG DJONI]

Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page ☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	05/11/18 16:25	Adjuster Immediate Advice
		Thumbnail Print 1 Load HTML
Photos/Images		3 per page ☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	05/11/18 16:11	General View
2	15/11/18 10:22	Reinspection Photo
		Thumbnail Print 1 Load PDF 1 Load PDF
Documentation		1 per page ☐
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
1	02/11/18 16:38	REPAIR EST WITH OI GIA
2	02/11/18 16:40	IMG 1
3	02/11/18 16:40	IMG 2
4	02/11/18 16:40	IMG 3
5	02/11/18 16:40	IMG 4
6	02/11/18 16:40	IMG 5
7	02/11/18 16:40	IMG 6
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	05/11/18 16:12	MARK ESTIMATE
2	26/11/18 14:00	Supplementary
		Thumbnail Print 1 Load PDF 1 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118020008/UVBE2

Date: 26/11/2018

REFERENCE

Insured/Claimant: NG DJONI Policy No: DMPCSN1669891802
Date of Loss: 31/10/2018 Nature of Claim: OD Claim No: SNM18D05189C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW629K**
Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A) Engine No: K24W71011552
Reg. Date: 15/10/2015 (Man. Year: 2015) Chassis No: JHMRC1890FC203162
Colour: White Odometer: 18962 km
Engine Capacity: 2356 cc
Market Value/New Car Price: S\$96,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,418.92	9,313.40	1,105.52	10.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,390.00	5,690.00	1,700.00	23.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,808.92	15,003.40	2,805.52	15.75
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	16,808.92	14,003.40	2,805.52	16.69
+ GST 7.00/7.00% (S\$)	1,176.62	980.24	196.38	16.69
Nett Amount (S\$)	17,985.54	14,983.64	3,001.90	16.69

INSPECTION

Date of Assignment: 02/11/2018
Date Inspected: 05/11/2018 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610
Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW629K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BULKHEAD COMPFR.	Bent / Buckled	338.77 FS	*338.77 FS
2	1		*SUPPORTR.FR.BULKHEAD UPP SIDE	Bent	26.47 FS	*26.47 FS
3	1		*SUPPORT,L.FR.BULKHEAD UPP SIDE	Bent	26.47 FS	*26.47 FS
4	1		*FENDER COMPR.FR.	Bent / Twisted	403.35 FS	*403.35 FS
5	1		*FENDER COMPL.FR.	Bent / Twisted	403.35 FS	*403.35 FS
6	1		*FENDER ASSYL.FR.INNER	Not Necessary	88.72 FS	*- FS
7	1		*HOOD COMP	Buckled	493.65 FS	*493.65 FS
8	1		*HINGE COMPR.HOOD	Bent	34.87 FS	*34.87 FS
9	1		*HINGE COMPL.HOOD	Bent	34.87 FS	*34.87 FS
10	1		*LOCK ASSYHOOD	Twisted	78.07 FS	*78.07 FS
11	1		*INSULATORHOOD	Deformed	69.37 FS	*69.37 FS
12	1		*CONDENSER COMP	Bent / Punctured	511.42 FS	*511.42 FS
13	1		*PIPE COMPRECEIVER	Not Necessary	129.90 FS	*- FS
14	1		*RADIATOR COMP	Bent / Punctured	1,010.47 FS	*1,010.47 FS
15	1		*FAN COMPCOOLING	Not Necessary	39.82 FS	*- FS
16	1		*SHROUD COMP	Not Necessary	61.57 FS	*- FS
17	1		*MOTORCOOLING FAN	Not Necessary	237.22 FS	*- FS
18	1		*HEAT PROTECTORFAN MOTOR	Not Necessary	6.30 FS	*- FS
19	1		*HEADLIGHT ASSYR.WITH LED	Cracked	1,677.90 FS	*1,677.90 FS
20	1		*HEADLIGHT ASSY,L WITH LED	Cracked	1,677.90 FS	*1,677.90 FS
21	1		*GARNISHR.FR.BUMPER	Not Necessary	33.90 FS	*- FS
22	1		*GARNISHL.FR.BUMPER	Not Necessary	33.90 FS	*- FS
23	1		*DISK ALUMINIUM WHEEL 17X7J	Cut	672.75 FS	*672.75 FS
24	1		*MOLDING ASSYR.FR.CORNER	Bent	65.77 FS	*65.77 FS
25	1		*BASEFR.GRILLE	Cracked	124.20 FS	*124.20 FS
26	1		*MOLDINGFR.GRILLE	Cracked	193.57 FS	*193.57 FS
27	1		*EMBLEMFR.	Necessary	19.42 FS	*19.42 FS
28	1		*NUTPUSH 3MM (2PCS)	Necessary	2.85 FS	*2.85 FS
29	1		*CAMERA ASSY,MVC FR	Serviceable	382.35 FS	*- FS
30	1		*COVERMVC FR.CAMERA	Not Necessary	6.07 FS	*- FS
31	1		*FACE,FR.BUMPER	Dented / Torn	514.65 FS	*514.65 FS
32	1		*GRILLEFR.BUMPER LOWER	Twisted	49.35 FS	*49.35 FS
33	1		*BEAM COMP,FR.BUMPER	Bent	214.57 FS	*214.57 FS
34	1		*BEAMR.FR.BUMPER UPPER	Bent	25.65 FS	*25.65 FS
35	1		*BASEMID GRILLE	Cracked	137.10 FS	*137.10 FS
36	1		*UPPER MOLDING MID GRILLE	Cracked	112.95 FS	*112.95 FS
37	1		*MID MOLDINGMID GRILLE	Cracked	108.15 FS	*108.15 FS
38	1		*LOWER MOLDINGR.MID GRILLE	Cracked	29.02 FS	*29.02 FS
39	1		*LOWER MOLDINGL.MID GRILLE	Cracked	29.02 FS	*29.02 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BEAML.FR.BUMPER UPPER	Bent	25.65 FS	*25.65 FS
41	1		*SPACERR.FR.BUMPER SIDE	Bent	8.70 FS	*8.70 FS
42	1		*SPACERL.FR.BUMPER SIDE	Bent	8.70 FS	*8.70 FS
43	10		*CLIP, BUMPER	Necessary	15.00 FS	*15.00 FS
44	6		*COOLANT ANTI-FREEZE TYPE 2	Necessary	104.40 FS	*104.40 FS
45	1		*NUMBER PLATE WITH CASING	Broken	45.00 FS	*45.00 FS
46	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
47	1		*MOLDING ASSYR.FR.CORNER	Repeated	65.77 FS	*- FS
Total Parts (S\$)					10,418.92	9,313.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WHEEL ALIGNMENT X 4	New	180.00	180.00
2	BODY UNDESIDE COATING	New	100.00	100.00
3	BODY JOINT SEALANT	New	100.00	100.00
4	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	120.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
6	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	280.00	250.00
7	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	350.00	280.00
8	REMOVE, INSTALL & CALIBRATE FRONT CAR VIEW CAMERA	New	350.00	300.00
9	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP	New	2,800.00	1,960.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	2,800.00	2,400.00
Gross Labour Cost (S\$)			7,390.00	5,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >