



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020139/Kfb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 18-07-2019



ATTN: JAS TAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGE 3248A	Veh. Inspected	GBC 189A
Policy No.	GA335562/1	Coverage (\$)	0.00
Claim No.	S8M010UO	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	07/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTFAT35Y60K201411	Colour	SILVER
Odometer	162343	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	BRIDGESTONE	7 mm
L/H Front Tyre	195 R15X8	BRIDGESTONE	7 mm
R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/10/2018	Inspection Date	07/11/2018
Survey held at	160 SIN MING DRIVE		
Repairer	CITY AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------