

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 9298Z (Supplementary)

DATE : 12.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>chrome mounting</i>			\$ 1,052.20 ✓
	Headlamp Support Panel Assy <i>chrome</i>			\$ 907.40 ✓
	SUB TOTAL			\$ 1,959.60
	LESS 20%			\$ 391.92
	DISCOUNTED TOTAL			\$ 1,567.68
<div><i>12/11/2018</i> <i>[Signature]</i> <i>24K Auto</i> <i>[Signature]</i> <i>14/11/18</i></div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				