

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; FAX: (065)\; FAX: (065)\; FAX: (065)\; FAX: (065)\; F$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 31/12/2018

Survey Details:

Date of loss	6-Nov-18
Date of appointment	8-Nov-18
Date of survey	18-Dec-18
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKS 8019P
Make and Model	HONDA HRV 1.5 LX CVT
Date of registration	8/5/2015
Excess	
Market Value	\$65,000
Parf Rebate	\$57,468
Nett Loss	\$7,532

Repair details:

Initial Estimate	Ś	3,680.67
Inneral Estimate	1 7	3,000.07

Proposed/Revised repair cost:

Parts	\$ 493.80	list price -25%
Check items (estimate)	\$ -	
Labour	\$ 1,580.00	
Total	\$ 2,073.80	
Lump Sum(if applicable)	\$ -	

Number of days for repair	3



 $51\; UBI\; AVE\; 1,\#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; UBI\; PARK,\; SINGAPORE\; 408933\;\; TEL:\\ (065)\; 62563561\;\; FAX:\\ (065)\; 62564315\;\; PAYA\; UBI\; PAYA\; UBI\;$

Remarks:

We have not authorized repairs.		

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,218.97	\$2073.80 +7%gst
Loss of use	\$ -	
Loss of rental	\$ 321.00	\$100.00 x 3 days +7%gst
Loss of income	\$ -	
LTA search fees	\$ 7.45	
Others	\$ -	
Proposed Total	\$ 2,547.42	